

CITY OF SAINT PAUL Christopher B. Coleman, Mayor COMMERCE BUILDING 8 Fourth Street East, Suite 200 St Paul, Minnesota 55101-1024 
 Telephone:
 651-266-9090

 Facsimile:
 651-266-9099

 Web:
 www.stpaul.gov/dsi

April 21, 2008

#### FREDDIE MAC C/O CENTURY 21 PASTRANA REALTY 2929 4TH AVE S SUITE 105 MINNEAPOLIS MN 55408

Re: 289 Burgess St File#: 07 174003 VB2

Dear Property Owner:

Pursuant to your request the above-referenced property was inspected and the following report is submitted:

# **BUILDING**

- 1. Rafter framing does not meet code (3'spacing). Add more framing members.
- 2. The inspectors were unable to inspect crawl space. Appears that main floor may have had water damage (floor buckled, stains on ceiling/walls) will need to make crawl space available for inspection.
- 3. Support basement stairs/landing.
- 4. Make basement stair risers uniform in height.
- 5. Repair interior and exterior of foundation.
- 6. Make rear deck stair risers uniform in height, install handrail to code.
- 7. Install tempered glass in window within 2' of front door.
- 8. Install provide hand and guardrails on all stairways and steps as per attachment.
- 9. Tuck point interior/exterior foundation.
- 10. Install floor covering in the bathroom and kitchen that is impervious to water.
- 11. Install tempered glass in window on stair landing.
- 12. Provide thumb type dead bolts for all entry doors. Remove any surface bolts.
- 13. Repair or replace any deteriorated window sash, broken glass, sash holders, re-putty etc. as necessary.
- 14. Provide storms and screens complete and in good repair for all door and window openings.
- 15. Repair walls and ceilings throughout, as necessary.
- 16. Provide hand and guardrails on all stairways and steps as per attachment.
- 17. Where wall and ceiling covering is removed, attic, replace doors and windows, (insulation, glass, weather stripping, etc.) shall meet new energy code standards.
- 18. Prepare and paint interior and exterior as necessary (take the necessary precautions if lead base paint is present).

Re: 289 Burgess St Page 2

## **BUILDING**

- 19. Any framing members that do not meet code (where wall and ceiling covering is removed, members that are over-spanned, over-spaced, not being carried properly, door and window openings that are not headered, etc.) are to be reconstructed as per code.
- 20. Habitable rooms with new usage, replaced windows shall have glass area equal to 8% of floor area, or a minimum of 8 sq. ft., one-half of which shall operate and all bedroom windows shall meet emergency egress requirements (20" wide minimum, 24" high minimum but not less than 5.7 sq. ft. overall).
- 21. Provide general clean-up of premise.
- 22. Provide smoke detectors as per the Minnesota State Building Code.
- 23. Repair soffit, fascia trim, etc. as necessary.
- 24. Provide proper drainage around house to direct water away from foundation.
- 25. Install downspouts and a complete gutter system.
- 26. Replace house and garage roof covering and vent to Code.
- 27. Provide general rehabilitation of garage.

#### **GARAGE**

- 28. Install treated plate on bottom of walls.
- 29. Remove/replace all rotten wood members.
- 30. Repair foundation.
- 31. Slope grade away from structure and maintain 6" clearance from grade to siding.
- 32. Replace overhead and service door.
- 33. Install address numbers on alley side.

## **ELECTRICAL**

- 1. Bond around water meter with a copper wire sized for the electrical service per Article 250 of the NEC.
- 2. Provide a complete circuit directory at service panel.
- 3. Verify/install a separate 20 ampere laundry circuit & a separate 20 ampere kitchen appliance circuit.
- 4. Install "S" type fuse adapters and proper size "S" fuses/ listed circuit breakers.
- 5. Verify that fuse/circuit breaker amperage matches wire size.
- 6. Close open knockouts in service panel/junction boxes with knockouts seals.
- 7. Install/replace GFCI receptacle in basement/first bathroom/second bathroom adjacent to the sink.
- 8. Remove all cord wiring.
- 9. Repair or replace all broken, missing or loose light fixtures, switches & outlets, covers and plates.
- 10. Check all 3-wire outlets for proper polarity and verify ground.
- 11. Remove any 3-wire ungrounded outlets, and replace with 2-wire, or ground 3-wire to code.
- 12. Throughout building, install outlets and light fixtures, as specified in Bulletin 80-1.

Re: 289 Burgess St Page 3

#### **ELECTRICAL**

- 13. Install hard-wired, battery backup smoke detector, as specified in Bulletin 80-1, and other smoke detectors as required by the IRC.
- 14. Install exterior lights at front/side/back entry doors.
- 15. Remove and/or rewire all illegal, improper or hazardous wiring in garage.
- 16. Rework romex at panel in basement.
- 17. Kitchen remove and properly wire hood fan, protect romex in cabinet, ensure sink light is grounded.
- 18. Bath GFCI does not test.
- 19. Attic Repair wiring per code, remove/rewire cable on stair.
- 20. Garage No access, remove all wiring and rewire per code.

## **PLUMBING**

All plumbing work requires permit(s) and must be done by a plumbing contractor licensed in Saint Paul.

#### **Basement**

- 1. The water heater gas venting is incorrect need 4" into liner.
- 2. The water heater is not fired or in service.
- 3. The water meter is removed and not in service.
- 4. The water meter service valves are not functional or correct.
- 5. Repair or replace all corroded, broken or leaking water piping.
- 6. The gas pipe sizing is incorrect.
- 7. Remove and plug, cap unsused gas lines.
- 8. The soil and waste piping has no front sewer cleanout; no soil stack base cleanout and has unplugged or open piping, back pitched piping.
- 9. The soil and waste piping has improper supports and improper connections, transitions, fitting or pipe usage.
- 10. The laundry tub waste is incorrect and unvented.

## <u>First Floor</u>

- 11. The bathtub, lavatory and kitchen sink waste are incorrect and unvented.
- 12. The laundry stand pipe waste is incorrect and unvented.

## **Exterior**

13. The lawn hydrants requires back flow assembly or device.

# **HEATING**

- 1. Install supply and return ducts on heating system to code.
- 2. Install approved lever handle manual gas shutoff valve on furnace/boiler.
- 3. Clean and Orsat furnace burner. Check all controls for proper operation. Check furnace heat exchanged for leaks; provide documentation from a licensed contractor that the heating unit is safe.

Re: 289 Burgess St Page 4

#### **HEATING**

- 4. Replace furnace and water heater venting into chimney liner.
- 5. Provide adequate clearance from flue vent pipe on furnace/boiler to combustible materials or provide approved shielding according to code.
- 6. Vent clothes dryer to code.
- 7. Install approved lever handle manual building shutoff gas valve in an accessible location ahead of the first branch tee.
- 8. Clean all supply and return ducts for warm air heating system.
- 9. Repair and/or replace heating registers as necessary.
- 10. Appropriate mechanical permits are required for this work.

## ZONING

1. This house was inspected as a single family dwelling.

## <u>NOTES</u>

\*\*See attachment for permit requirements and appeals procedure.

All items noted as <u>recommended</u> do not have to be completed for code compliance but should be completed at a later date. Possible purchasers of property shall be made aware of these items.

This is a registered vacant building. In order to reoccupy the building, all deficiencies listed on the code compliance report must be corrected and be in compliance with the Minimum Housing Standards of the St. Paul Legislative Code (Chapter 34), and all required permits must receive final approval.

#### \*\*VACANT BUILDING REGISTRATION FEES MUST BE PAID AT NEIGHBORHOOD HOUSING AND PROPERTY IMPROVEMENT (NHPI) FOR PERMITS TO BE ISSUED ON THIS PROPERTY\*\*. For further information call, NHPI at

651-266-1900, located at 1600 White Bear Avenue.

Sincerely,

James L. Seeger Code Compliance Officer

JLS:ml

Attachments