

# Saint Paul Fire Department FIRE INCIDENT DISPOSITION



INCIDENT NUMBER:	19-46939	DATE OF INCIDENT: 12-07-2019	
TIME OF INCIDENT:	2038 HOURS	POLICE CASE #: N/A	
INVESTIGATOR (s) :	JEREMY K. LARSON		
INCIDENT ADDRESS:	2002 BUSH AVENUE, SAINT PAUL, MN 55119		
OCCUPANT NAME:	JASMINE D. JOHNSON DOB: 08/14/1989	PHONE: 651-404-5771	
OWNER NAME:	WEI ZOU	PHONE: 651-767-2468	
ADDRESS OF OWNER:	3034 EDGEWATER DR, ST. PAUL, MN 55125		
PROPERTY DAMAGED:	1 1/2-STORY SINGLE-FAMILY DWELLING	AREA OF ORIGIN: UPPER LEVEL LIVING SPACE	
DAMAGE ESTIMATE:	Building \$10,000	Vehicle \$0	Other (Describe) \$0
VALUE:	Building \$102,900	Vehicle \$0	Other (Describe) \$0
Damage Estimate CONTENTS ONLY:	\$5,000		
INJURY/DEATH (if yes, explain)	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes		
SMOKE DETECTOR, SPRINKLER, and CARBON MONOXIDE INFORMATION:	Smoke Detector Present: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown Detector Functioning: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown Sprinkler System Present: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown Sprinkler Heads activated: <input type="checkbox"/> Yes # <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown C.O Detector Present: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown		
FIRE CAUSE CLASSIFICATION:	<input checked="" type="checkbox"/> Accidental <input type="checkbox"/> Juvenile/Incendiary <input type="checkbox"/> Incendiary <input type="checkbox"/> Child (under 10 years old) <input type="checkbox"/> Natural <input type="checkbox"/> Undetermined <input type="checkbox"/> Under Investigation		
SYNOPSIS:	Saint Paul Fire Department was dispatched for a report of smoke in the upper level of a dwelling. Fire companies arrived to find a mattress fire in the upper level of a 1 1/2 story, single-family dwelling. Firefighters performed extinguishment and overhaul. Interviews conducted on-scene with the juvenile occupants left home unsupervised revealed they had recently been upstairs to change clothes and approximately 1/2 after heard the smoke alarms and observed smoke in the upper level. The juvenile occupants were then removed by a neighbor. Investigation revealed charred and melted mattress materials with an unshaded lamp in the area of origin. The ignition source was most likely normal heat of an unshielded light bulb. The first fuel ignited was most likely the polyurethane foam mattress material. The act that brought these two together was most likely combustibles stored too near a heating source. The classification of fire cause is accidental.		
DISPOSITION:	<input type="checkbox"/> E-mail only <input type="checkbox"/> Hold Scene until approved <input type="checkbox"/> DO NOT DEMOLISH until approved <input checked="" type="checkbox"/> Scene Released <input type="checkbox"/> Analysis of Evidence Pending <input checked="" type="checkbox"/> Report to Follow		

