## DEPARTMENT OF SAFETY AND INSPECTIONS Ricardo X. Cervantes, Director



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 St Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-9124

 Web:
 www.stpaul.gov/dsi

August 22, 2016

Re: Site Review

Code Compliance Inspection (Building)

Address: 1179 7th. St. E.

## **Deficiencies**

## Exterior:

- 1) Repair all damaged mortar and brick work ,many areas have damage. SPLC Sect. 34.33 (1) b
- 2) Repair roof where leaking into building. SPLC Sect. 34.33 (1) d
- 3) Replace decayed or damaged and improperly installed siding on east side of building SPLC Sect. 34.33 (1) b & c
- 4) Repair grading around building to keep water from seeping into structure. SPLC Sect. 34. 08 (2)
- 5) Repair all old window openings and framing around old basement windows and foundation. SPLC Sect. 34.303 (3) a & c.

## Interior:

- 1) In basement replace all decayed wood and rusted steel post and replace all decayed framing. SPLC Section 34.34 (1)
- Install vapor barrier on grade in crawl space in area between basement sections .SPLC Sect.34.34
   (4)
- 3) East side stairwell on north wall has water damage in wall and needs replacement. SPLC Sect. 34.34 (6).
- 4) 1st. floor bathroom walls have some decayed studs and drywall and need replacement. SPLC
- 5) Sect. 34.34 (6)

James Seeger Code Compliance Officer