

Saint Paul Fire Department FIRE INCIDENT DISPOSITION



INCIDENT NUMBER:	20-17786	DATE OF INCIDENT: 05-19-2020	
TIME OF INCIDENT:	0259 HOURS	POLICE CASE #: N/A	
INVESTIGATOR (s) :	JEREMY K. LARSON		
INCIDENT ADDRESS:	1525 DIETER STREET, SAINT PAUL, MN 55106		
OCCUPANT NAME:	KUE LEE DOB: 10/17/1979	PHONE: 651-500-6509	
OWNER NAME:	ANDREA LYNETTE EVANS	PHONE: 612-759-4112	
ADDRESS OF OWNER:	611 CALIFORNIA AVE E, ST. PAUL, MN 55130		
PROPERTY DAMAGED:	2-STORY SINGLE-FAMILY DWELLING	AREA OF ORIGIN: ATTIC AREA	
DAMAGE ESTIMATE:	Building \$80,000	Vehicle \$	Other (Describe) \$0
VALUE:	Building \$148,700	Vehicle \$	Other (Describe) \$0
Damage Estimate CONTENTS ONLY:	\$30,000		
INJURY/DEATH (if yes, explain)	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes		
SMOKE DETECTOR, SPRINKLER, and CARBON MONOXIDE INFORMATION:	Smoke Detector Present: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown Detector Functioning: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown Sprinkler System Present: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown Sprinkler Heads activated: <input type="checkbox"/> Yes # <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown C.O Detector Present: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown		
FIRE CAUSE CLASSIFICATION:	<input checked="" type="checkbox"/> Accidental <input type="checkbox"/> Juvenile/Incendiary <input type="checkbox"/> Incendiary <input type="checkbox"/> Child (under 10 years old) <input type="checkbox"/> Natural <input type="checkbox"/> Undetermined <input type="checkbox"/> Under Investigation		
SYNOPSIS:	Saint Paul Fire Department was dispatched for a report of an attic fire. Fire companies arrived to find fire coming from the roof of a 2-story, single-family dwelling. Firefighters performed extinguishment and overhaul. Interviews conducted on-scene with the occupant revealed he was awoken by the smoke alarms and observed smoke in the bathroom ceiling upon investigating. Investigation revealed mass loss and charring to the roof and roof trusses above the bathroom area with electrical passing through. The ignition source was most likely heat of electrical resistance. The first fuel ignited was most likely combustible building materials. The act that brought these two together was most likely an electrical malfunction. The classification of fire cause is accidental.		
DISPOSITION:	<input type="checkbox"/> E-mail only <input type="checkbox"/> Hold Scene until approved <input type="checkbox"/> DO NOT DEMOLISH until approved <input checked="" type="checkbox"/> Scene Released <input type="checkbox"/> Analysis of Evidence Pending <input checked="" type="checkbox"/> Report to Follow		

