Saint Paul Safety & Inspections

375 Jackson Street #220

St. Paul, MN 55101

RE: 1436 Snelling Ave N SPLC 34.23

Photos were taken by Roy Kingsley DSI Fire Inspector

- 1. Front of 1436 Snelling
- 2. Front of house
- 3. Address of house
- 4. Front door of house
- 5. Looking at living room from front door
- 6. Staircase to 2nd floor.
- 7. Bathroom at top of 2nd floor
- 8. Bedroom to the left of hallway
- 9. Looking at bedroom window.
- 10. Close look at bedroom window is not operational and taped up.
- 11. Bedroom to the right on 2nd floor
- 12. Bedroom window of bedroom on the right
- 13. Another window located in 2nd bedroom.
- 14. 2nd floor bedroom sink with sign located on top do not use.
- 15. Smoke detector located at top of stairs on 2nd floor.
- 16. Ceiling panel for the 2nd floor bedroom.
- 17. Another view of the smoke detector on 2nd floor with rapping still on it.
- 18. Light fixture in hallway of the 2nd floor hanging by the wires.
- 19. Exit door location on the 2nd floor to outside roof.
- 20. Looking at roof line from 2nd floor exit door.
- 21. Storage tote in living room
- 22. Extension cord located in the living room.
- 23. Same extension cord showing it was not plug into it this time.
- 24. Cox cable from living room to upper level.
- 25. Fly strip located in the living room.
- 26. Another fly strip located in the living room.
- 27. Looking at room next to the living room.
- 28. Window located in room next to living room.
- 29. Blue extension cord from living room to kitchen.

- 30. Blue extension cord plugs into outlet in living room.
- 31. Blue extension cord behind refrigerator.
- 32. Another look at blue extension cord behind refrigerator.
- 33. Refrigerator cord plugs into blue extension cord.
- 34. Pizza oven located in the kitchen.
- 35. Looking at kitchen sink.
- 36. Kitchen stove top with combustibles located on it.
- 37. Kitchen counter space
- 38. Another look at kitchen counter space
- 39. Stairwell to basement.
- 40. Standing at bottom of stairs to the basement looking at bedroom.
- 41. Looking down hallway to laundry room.
- 42. Looking at storage next to furnace
- 43. Looking at freezer, dryer and wash machine located in the laundry room.
- 44. Looking at gas line located
- 45. Looking at wiring for old phone lines.
- 46. Storage located on top of washer machine.
- 47. More storage next to wash machine.
- 48. Light fixture located in laundry room missing light bulb.
- 49. Fly strip located in lower-level laundry room.
- 50. Gas line for furnace with gas valve in the open position.
- 51. Looking into bedroom located in lower level.
- 52. Another view of lower-level bedroom with no egress window.
- 53. Window located in lower-level bedroom.
- 54. Ceiling in lower-level bedroom.
- 55. Storage located on furnace
- 56. Looking inside furnace burn area
- 57. Looking at the lower level of furnace with cobwebs throughout.
- 58. Room located in rear of home on the main level going to the outside.
- 59. Light fixture in back room
- 60. Power strip located in back room for permanent power.
- 61. Outlet in back room of main level.
- 62. Rear door of the house
- 63. Photo of Condemned date 11/7/2025
- 64. Pole located at front door deconstruction.
- 65. Front door with Condemned placard date 11/7/2025