TO: City of St Paul

RE: 221 Montrose Place

The roof was leaking in a particular area, and after assessing the situation a section of the roof was replaced. After replacing and prior to closing the ceiling I watched for 90 days to make sure the section that was replaced did not result in any leaks.

Signed

Angel morales Ramez

Angel Morales