

Saint Paul Fire Department FIRE INCIDENT DISPOSITION



INCIDENT NUMBER:	20-16278	DATE OF INCIDENT: 05-07-2020	
TIME OF INCIDENT:	1501 HOURS	POLICE CASE #: N/A	
INVESTIGATOR (s) :	JEREMY K. LARSON		
INCIDENT ADDRESS:	182 CHARLES AVENUE, SAINT PAUL, MN 55103		
OCCUPANT NAME:	ANDREA J. HINDERAKER DOB: 05/26/1976	PHONE: 612-251-6162	
OWNER NAME:	INCIDENT: ANDREA HINDERAKER EXPOSURE: LISA H LEE	PHONE: 612-251-6162 UNKNOWN	
ADDRESS OF OWNER:	INCIDENT: 182 CHARLES AVE, ST. PAUL, MN 55103 EXPOSURE: 181 SHERBURNE AVE, ST. PAUL, MN 55103		
PROPERTY DAMAGED:	INCIDENT: DETACHED GARAGE EXPOSURE: DETACHED GARAGE	AREA OF ORIGIN: INTERIOR OF INCIDENT GARAGE	
DAMAGE ESTIMATE:	Building \$ INCIDENT: 20,000 EXPOSURE: 1,000	Vehicle \$	Other (Describe) \$ 0
VALUE:	Building \$ 2,090,000	Vehicle \$	Other (Describe) \$ 0
Damage Estimate CONTENTS ONLY:	\$5,000		
INJURY/DEATH (if yes, explain)	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes		
SMOKE DETECTOR, SPRINKLER, and CARBON MONOXIDE INFORMATION:	Smoke Detector Present: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown Detector Functioning: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown Sprinkler System Present: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown Sprinkler Heads activated: <input type="checkbox"/> Yes # <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown C.O Detector Present: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown		
FIRE CAUSE CLASSIFICATION:	<input checked="" type="checkbox"/> Accidental <input type="checkbox"/> Juvenile/Incendiary <input type="checkbox"/> Incendiary <input type="checkbox"/> Child (under 10 years old) <input type="checkbox"/> Natural <input type="checkbox"/> Undetermined <input type="checkbox"/> Under Investigation		
SYNOPSIS:	<p>Saint Paul Fire Department was dispatched for a report of a garage fire. Fire companies witnessed fire coming from the rear of a detached garage structure. Firefighters performed extinguishment and overhaul. Interviews conducted on-scene with the occupant revealed she observed smoke and flames coming from the garage and had not been in the garage. Investigation revealed charring and mass loss to the incident garage within a walled off room of the garage and roof area. Investigation also revealed charring to the fascia of the exposure garage. The ignition source was most likely heat of electrical resistance. The first fuel ignited was most likely combustible building materials. The act that brought these two together was most likely an electrical malfunction. The classification</p>		

	of fire cause is accidental.	
DISPOSITION:	<input type="checkbox"/> E-mail only	<input type="checkbox"/> Hold Scene until approved
	<input type="checkbox"/> DO NOT DEMOLISH until approved	<input checked="" type="checkbox"/> Scene Released
	<input type="checkbox"/> Analysis of Evidence Pending	<input checked="" type="checkbox"/> Report to Follow

DFSS Form #141 (12/19/2013)