

NFIRS-1 Basic

A									
62210	MN	02	07	2021	Station #18 (18)	SPFD210207	005303	1	
FDID	State	Month	Day	Year	Station	Number		Exposure	
B Location Type Street Address Intersection In Front Of Rear Of Adjacent To Directions US National Grid	329 Number Apt./Suite/F		LAWSC Street Saint Pa City	or Highway			/E- Avenue eet Type S511 Zip C	W-West Suffix	ract: 08.00
C Incident Type 111-Building fire D Aid Given Or Recei	ved			E1 Dates a Alarm Arrival Controlle Last Unit Cleared	02 07 2021 2	22:46	E2 Shifts a C Shift or A Platoon	1 D2	trict
1 Mutual Aid Recc 2 Auto. Aid Rece 3 Mutual Aid Give 4 Auto. Aid Giver 5 Other Aid Give	ived Thei	r FDID	Their State J umber				E3 Special 9244 ID#	Studies 4 - Unkno Value	wn
F Actions Taken 11-Extinguishment by personnel Primary Action Take			Suppres I Ot	Apparatusion 12 EMS 2 ther 0 ce counts includes	nel Module is used. s Personnel 0 0 0 ude aid received	Property Content Pre-Inci Property	d Dollar Loss Required for known. Optic non-fires. /: \$ 40,000.00 s: \$ 15,000.00 dent Values: /: \$ 70,300.00 s: \$ 50,000.00	all fires if onal for all	None None

Completed Modules 2 - Fire 3 - Structure Fire 4 - Civilian Fire Cas. 5 - Fire Service Cas. 6 - EMS 7 - HazMat 8 - Wildland Fire 9 - Apparatus 10 - Personnel 11 - Arson	H1 Casualties None Deaths Injuries Fire 0 0 Service 0 Civilian 0 0 H2 Detector Required for Confined Fires 1 - Detector Alerted Occupants 2 - Detector Did Not Alert Them 3 - Unknown	H3 Hazardous Materials Release 1 - Natural Gas 2 - Propane Gas 3 - Gasoline 4 - Kerosene 5 - Diesel Fuel / Fuel Oil 6 - Household Solvents 7 - Motor Oil 8 - Paint 0 - Other None	Mixed Use Property Not Mixed 10 - Assembly Use 20 - Education Use 33 - Medical Use 40 - Residential Use 51 - Row Of Stores 53 - Enclosed Mall 58 - Business and Residential 59 - Office Use 60 - Industrial Use 63 - Military Use 65 - Farm Use 00 - Other Mixed Use
---	---	--	--

Property Use None Structures 131 Church, Place of Worship 161 Restaurant or Cafeteria 162 Bar/Tavern or Nightclub 213 Elementary School, Kindegarten 215 High School, Junior High 241 College, Adult Education 311 Nursing Home 331 Hospital	341 Clinic, Clinic-Type Infirmary 342 Doctor/Dentist Office 361 Prison or Jail, Not Juvenile 419 1- or 2-Family Dwelling 429 MultiFamily Dwelling 439 Rooming/Boarding House 449 Commerical Hotel or Motel 459 Residential, Board and Care 464 Dormitory/Barracks 519 Food and Beverage Sales	539 Household Goods, Sales, Repairs 571 Gas or Service Station 579 Motor Vehicle/Boat Sales/Repairs 599 Business Office 615 Electric-Generating Plant 629 Laboratory/Science Laboratory 700 Manufacturing Plant 819 Livestock/Poultry Storage (Barn) 882 Non-Residential Parking Garage 891 Warehouse
Outside 124 Playground or Park 655 Crops or Orchard 669 Forest (Timberland) 807 Outdoor Storage Area 919 Dump or Sanitary Landfill 931 Open Land or Field 936 Vacant Lot	938 Graded/Cared for Plot of Land 946 Lake, River, Stream 951 Railroad Right-of-Way 960 Other Street 961 Highway/Divided Highway 962 Residential Street/Driveway 981 Construction Site 984 Industrial Plant Yard	Property Use: Description Look up and enter a Property Use code and description only if you have NOT checked a Property Use box.

Owner						
Local Option	Person/Ent	it y Type	Business	Name (if applicable)	Phone Number	
		[[
Mr., Ms., Mrs.	First Name	MI		Last Name	Suffix	
Number	Prefix	Street or H	lighway	Street Type	Suffix	
Post Office Box		Apt./Suite/Room		City		
İ			11			

L Remarks:

Fire crews responded to structure fires at 329 and 331 Lawson Avenues. These structures were duplexes built approximately 3 to 4 feet apart. It appears the fire started in 331 Lawson on the 1st floor extending to the 2nd floor, attic, and to 329 Lawson's siding, 1st floor, 2nd floor, and the attic.

Engine 22 on arrival deployed 1 3/4 inch hose line extinguishing exterior fire between the homes. Engine 22 then made entry into 329 Lawson extinguishing interior fire in the attic, 1st and 2nd floors. Ladder 22 completed a primary search of 329 Lawson and worked with Engine 22 on fire attack and overhaul.

Engine 18 deployed 1 3/4 inch attack line into the 1st floor of 331 Lawson extinguishing the fire. Squad 1 deployed a 2nd 1 3/4 inch hose line from Engine 18 to the 2nd floor and attic extinguishing the fire. Ladder 18 completed a primary search of the 331 Lawson Avenue.

Chief 3 was safety officer, Engine 8 secured a water supply for Engine 22 and Engine 18, Engine 8 was RIT, Engine 17 and Squad 3 were used for secondary searches, utility control, fire attack, overhaul, and ventilation in both structures. Ladder 22 deployed the aerial ladder to the roof of 331 Lawson.

Medic 5's Captain was the FIT. Medic 5 provided EMS coverage and assisted one resident to a local hotel at the conclusion of the incident.

MTC bus was secured for rehab. Water department shut water off to both structures and checked hydrant at conclusion of incident. Public works was notif...

Full primary narrative can be found in NFIRS 1S - Supplemental $\,$

^M Authorization										
1835	Baumeister, Arthur	DC	C1	02/08/2021						
Officer In Charge ID	Signature	Position or Rank	Assignment	Date						
1835	Baumeister, Arthur	DC	C1	02/08/2021						
Member Making Report ID	Signature	Position or Rank	Assignment	Date						

NFIRS-2 Fire

А										
622	10	MN	02	07	2021	Station #18 (18)	SPFD2102070	005303	1	
FDID)	State	Month	Day	Year	Station	Number		Exposure	
1010	•	State	Monen	Day	rear	Sederon	ramber		Exposure	
В						С				
	erty Details					On-Site Materials		On-Site Mat	:-!-	
· .	4	Not Re	esidential			Or Products		Storage Use		
L	stimated numbe			units in the	huilding					
	of origin whether				Duituing					
B2 L		Buildir	ngs Not Inv	olved						
1	Number of buildir									
B3 L		☑ None	Less th	nan 1 acre						
<i>A</i>	Acres burned (out	tside fires)								
							F2			
D Igniti	on			E1 Cause o	of Ignition		E3 Human Fa	ctors Contr	ibutina to	
D1	70- Structural area	a other	1	1 - In	tentional		Ignition	applicable boxes		
	Area of Fire Origin		_		nintentional silure of Equip	oment or Heat	☑ None			
	82-Radiated heat		1	Source	ct of Nature		1 - Asle 2 - Poss			
D2	another fire			5 - Cause Under Investigation drugs				attended person		
Heat Source 99-Multiple items first ignited				Investig		4 - Poss	ssibly Mentally Disabled ysically Disabled ıltiple Persons Involved			
				F2						
Item First Ignited D4 Undetermined			_	E2 Factor	s Contributi	7 - Age				
				,	oosure fire	Estimated Person Inv				
Type of Material First Ignited			Factor Contributing to Ignition					Female		
F1				F2				G		
Equip	ment Involved	In Ignitio	n	Equipme	nt Power So	игсе		Fire Supp	oression Factors	
☑ No	ne			11						
∐ .				L Equipment Power Source						
Equipr	nent Involved		-	F3				1		
Brand					nt Portabilit	у				
Mode	el			1 - Por	table					
Serial	#			2 - Sta	tionary					
Year				persons.	equipilient noi	mally can be moved by	one or two			
H1	la Deanaster to	مايية		H2	lla Desarett	Type and Mate-		Local Use		
	le Property Inv Not involved in		ut burned	MOD	ile Property	Type and Make		Pre-Fire	Plan Available	
1 - Not involved in ignition, but burned 2 - Involved in ignition, but did not burn				Mobil	e Property Typ	oe		Arson Re	port Attached port Attached	
3 - Involved in ignition and burned None								Coroner	Report Attached	
				Mobil	e Property Ma	ke		— Other Re	eports Attached	
Mobile	Property Model			 Year	-					
Mobile										
State	License Pl	ate Numbe	١٢	VIN			-			

NFIRS-3 Structure Fire

Building Status 1 - Under Construction 2 - In Normal Use 3 - Idle, Not Routinely Used 4 - Under Major Renovation 5 - Vacant and Secured 6 - Vacant and Unsecured 7 - Being Demolished 0 - Other U - Undetermined	Building Height 2 Number of Storie At/Above Grade 1 Number of Storie Below Grade	ts Total Square Feet OR		
Number of Stories w/Minor Number of Stories w/Signific Number of Stories w/Heavy I Number of Stories w/Extrem	Damage (1-24%) ant Damage (25-49%) Damage (50-74%) ne Damage (75-100%)	K Type of Material Contributing Most to Flame Spread K1 Item Contributing Most to Flame Spread K2 Type of Material Contributing Most To Flame Spread		
L3 Detector Power Supply 1 - Battery Only 2 - Hardwire Only 3 - Plug-In 4 - Hardwire With Battery 5 - Plug-In With Battery 6 - Mechanical	L5 Detector Effectiveness 1 - Alerted Occupants, Occupants Responded 2 - Alerted Occupants, Occupants Failed to Respond 3 - There Were No Occupants 4 - Failed to Alert Occupants U - Undetermined			
& Power Supplies 0 - Other U - Undetermined	2 - Improper Insta 3 - Defective 4 - Lack of Mainte	Shutoff, or Disconnect allation or Placement enance, Dirty ng or Disconnected arged or Dead		
Extinguishing System 1 - Operated/Effective 2 - Operated/Not Effectiv 3 - Fire Too Small To Activ 4 - Failed To Operate 0 - Other U - Undetermined Required if fire was within designed range M4 Number of Sprinkler Heads Operating Required if system operated	System Failur 1 - System 9 2 - Not Enoi e 3 - Agent D 4 - Wrong T 5 - Fire Not 6 - System 0 7 - Lack of 1 8 - Manual 1 0 - Other U - Undetei	Shut Off ugh Agent Discharged ischarged But Did Not Reach Fire ype of System In Area Protected Components Damaged Maintenance ntervention		
	Building Status 1 - Under Construction 2 - In Normal Use 3 - Idle, Not Routinely Used 4 - Under Major Renovation 5 - Vacant and Secured 6 - Vacant and Unsecured 7 - Being Demolished 0 - Other U - Undetermined J3 Number of Stories Damaged By Number of Stories w/Minor I Number of Stories w/Signific Number of Stories w/Extrem *Count the roof as part of the high 1 - Battery Only 2 - Hardwire Only 3 - Plug-In 4 - Hardwire With Battery 5 - Plug-In With Battery 6 - Mechanical 7 - Multiple Detectors & Power Supplies 0 - Other U - Undetermined L4 Detector Operation 1 - Fire Too Small To Activate 2 - Operated 3 - Failed To Operate U - Undetermined W3 Operation of Automatic Extinguishing System 1 - Operated/Effective 2 - Operated 0 - Other U - Undetermined Required if Fire was within designed range	Building Status 1 - Under Construction 2 - In Normal Use 3 - Idle, Not Routinely Used 4 - Under Major Renovation 5 - Vacant and Secured 6 - Vacant and Unsecured 7 - Being Demolished 0 - Other U - Undetermined Number of Stories Damaged By Flame Number of Stories w/Minor Damage (1-24%) Number of Stories w/Significant Damage (25-49%) Number of Stories w/Heavy Damage (50-74%) Number of Stories w/Extreme Damage (75-100%) *Count the roof as part of the highest story *Count the ro		

NFIRS-1S Supplemental

Α								
	62210	MN	02	07	2021	Station #18 (18)	SPFD210207005303	1
	FDID	State	Month	Day	Year	Station	Number	Exposure

Primary Narrative:

Fire crews responded to structure fires at 329 and 331 Lawson Avenues. These structures were duplexes built approximately 3 to 4 feet apart. It appears the fire started in 331 Lawson on the 1st floor extending to the 2nd floor, attic, and to 329 Lawson's siding, 1st floor, 2nd floor, and the attic.

Engine 22 on arrival deployed 1 3/4 inch hose line extinguishing exterior fire between the homes. Engine 22 then made entry into 329 Lawson extinguishing interior fire in the attic, 1st and 2nd floors. Ladder 22 completed a primary search of 329 Lawson and worked with Engine 22 on fire attack and overhaul.

Engine 18 deployed 1 3/4 inch attack line into the 1st floor of 331 Lawson extinguishing the fire. Squad 1 deployed a 2nd 1 3/4 inch hose line from Engine 18 to the 2nd floor and attic extinguishing the fire. Ladder 18 completed a primary search of the 331 Lawson Avenue.

Chief 3 was safety officer, Engine 8 secured a water supply for Engine 22 and Engine 18, Engine 8 was RIT, Engine 17 and Squad 3 were used for secondary searches, utility control, fire attack, overhaul, and ventilation in both structures. Ladder 22 deployed the aerial ladder to the roof of 331 Lawson.

Medic 5's Captain was the FIT. Medic 5 provided EMS coverage and assisted one resident to a local hotel at the conclusion of

MTC bus was secured for rehab. Water department shut water off to both structures and checked hydrant at conclusion of incident. Public works was notified to sand and salt Lawson street /sidewalks between Virginia and Farrington. Xcel Energy locked out gas and pulled electrical meters to both addresses. Board up was called to secure both properties. DSI Inspector 12 condemned the properties as not habitable. Chief 3 made contact with all occupants on scene and connected them with Red Cross.

Captain Blank is the fire investigator for this incident. Call #5303.