

Saint Paul Fire Department FIRE INCIDENT DISPOSITION



INCIDENT NUMBER:	20-22135	DATE OF INCIDENT: 6-17-2020	
TIME OF INCIDENT:	1220 Hours	POLICE CASE #: n/a	
INVESTIGATOR(s):	Blank, J		
INCIDENT ADDRESS:	101 Como Ave Saint Paul, MN 55103		
OCCUPANT NAME:	Kiefer M Morgan	PHONE: 651-321-2972	
OWNER NAME:	Xin Zhou	PHONE: 650-283-6467	
ADDRESS OF OWNER:	19151 Broadmoore Dr Eden Prairie, MN 55346		
PROPERTY DAMAGED:	Duplex	AREA OF ORIGIN: East Staircase Deck	
DAMAGE ESTIMATE:	Building \$25,000	Vehicle \$n/a	Other (Describe) \$n/a
VALUE:	Building \$93,000	Vehicle \$n/a	Other (Describe) \$n/a
Damage Estimate CONTENTS ONLY:	\$1,000		
INJURY/DEATH (if yes, explain)	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes		
SMOKE DETECTOR, SPRINKLER, and CARBON MONOXIDE INFORMATION:	Smoke Detector Present: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown Detector Functioning: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown Sprinkler System Present: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown Sprinkler Heads activated: <input type="checkbox"/> Yes # <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown C.O Detector Present: <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Unknown		
FIRE CAUSE CLASSIFICATION:	<input checked="" type="checkbox"/> Accidental <input type="checkbox"/> Juvenile/Incendiary <input type="checkbox"/> Incendiary <input type="checkbox"/> Child (under 10 years old) <input type="checkbox"/> Natural <input type="checkbox"/> Undetermined <input type="checkbox"/> Under Investigation		
SYNOPSIS:	The Fire Department was called to a report of a dwelling fire. Firefighters arrived to find an exterior fire on the dwelling and quickly extinguished it. The occupant admits using a bucket for disposing of cigarette butts on the deck in the area of origin. Construction workers notified the occupants of the fire and stated that the fire was only around the base of the bucket when they first saw flames. The ignition source was a cigarette butt. The first fuel ignited was wood decking. The action that brought these items together was due to a cigarette butt not making it into the bucket and landing on the wood decking. The classification of fire cause is accidental.		
DISPOSITION:	<input type="checkbox"/> E-mail only <input type="checkbox"/> Hold Scene until approved <input type="checkbox"/> DO NOT DEMOLISH until approved <input checked="" type="checkbox"/> Scene Released <input type="checkbox"/> Analysis of Evidence Pending <input checked="" type="checkbox"/> Report to Follow		