



CITY OF SAINT PAUL

375 Jackson Street, Suite 220  
Saint Paul, Minnesota 55101-1806

Telephone: 651-266-8989  
Facsimile: 651-266-8951  
Web: [www.stpaul.gov/dsi](http://www.stpaul.gov/dsi)

June 30, 2022

JEFF HEEGAARD  
THE HOME COMPANY  
213 4TH ST. E  
ST PAUL MN 55101

## FIRE INSPECTION CORRECTION NOTICE

RE: 213 4TH ST E  
Ref. #11020

Dear Property Representative:

Your building was inspected on June 30, 2022 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. **A re-inspection will be made on July 29, 2022 at 9:30 am.**

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional re-inspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

### DEFICIENCY LIST

1. 4th floor - Service fire extinguisher - MSFC 901.6 - Provide required annual maintenance of the fire extinguishers by a qualified person and tag the fire extinguishers with the date of service.
2. Basement - Elevator equipment room - MSFC 901.6 - Provide required annual maintenance of the fire extinguishers by a qualified person and tag the fire extinguishers with the date of service.

3. Basement - Meter room - MSFC 901.6 - Provide required annual maintenance of the fire extinguishers by a qualified person and tag the fire extinguishers with the date of service.
4. Fire alarm - Report - MSFC 907.8, NFPA 72 14.3.1 - Provide required annual maintenance of the fire alarm system by a qualified person and provide written documentation to this office as proof of compliance.-Provide the most recent copy of the fire alarm report.
5. Fire sprinkler - Report - MSFC 901.6 - Provide required annual inspection and testing of the fire sprinkler system by a licensed fire sprinkler contractor and provide written documentation to this office as proof of compliance. Tags must be maintained on the riser showing the latest date of inspection and testing.-Provide the most recent copy of the fire sprinkler report.
6. Kitchen - Hood cleaning report - MSFC 607.3.3 - Contact a qualified hood and duct cleaning service company to clean and service grease duct vent for commercial cooking equipment. Provide documentation as proof of compliance. Maintain venting system in a clean and sanitary condition.-Provide the most recent copy of the hood cleaning report.
7. Lost Fox - Above bar - NFPA 13 Escutcheons used with recessed, flush-type, or concealed sprinklers shall be part of a listed sprinkler assembly.  
-Missing sprinkler escutcheons above the bar.
8. Lost Fox - By coffee bar and behind bar - MSFC 906.1, MN Stat. 299F.361 - Provide approved fire extinguishers in accordance with the following types, sizes and locations.-Provide minimum 2A10BC fire extinguishers spaced not more than 75 feet travel distance from any point in the building to an extinguisher. They must be permanently mounted between 3 and 5 feet high in readily visible and easily accessible locations.
9. Lost Fox - Cooking equipment - MNFGC 411.1.4 Movable Appliances. Where appliances are equipped with casters or are otherwise subject to periodic movement or relocation for purposes such as routine cleaning and maintenance, such appliances shall be connected to the supply system piping by means of an approved flexible connector designed and labeled for the application. Such flexible connectors shall be installed and protected against physical damage in accordance with the manufacturer's installation instructions.  
-Install the tethers on the cooking equipment.
10. Lost Fox - Correct hood suppression - MSFC 904.1.1 - Contact a qualified contractor to provide an approved hood and duct ventilation fire suppression system. All work must be done under a permit. Call DSI at (651) 266-8989.-The hood suppression is incorrect. Move the equipment back to its original location, or have your contractor pull a permit and have the suppression corrected.
11. Lost Fox - Service hood suppression - MSFC 904.12.5.2 - Provide required six month service of the hood and duct fire suppression system. Provide documentation from qualified contractor.

12. Suite 201 - Change of use - MSBC 1300.022 Subp. 3 - The occupancy group or use division of this building has been changed from that previously approved. Discontinue the unapproved occupancy or use or contact the Building Official at 651-266-8989 with your code analysis and to comply with requirements for approved occupancy.-Suite 201 was set up as a residential unit. It was previously approved as a business use. Complete a change of use under permit, or discontinue the use as a residential unit.

13. Suite 201 - Service fire extinguisher - MSFC 901.6 - Provide required annual maintenance of the fire extinguishers by a qualified person and tag the fire extinguishers with the date of service.

14. Suite 201 - Sleeping loft - NFPA 13 17.1.3.1 - Remove all objects, equipment or storage hanging from the fire sprinkler piping and/or fire sprinkler heads.-Remove the lights from the sprinkler piping.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: <http://www.stpaul.gov/cofo>

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: [george.niemeyer@ci.stpaul.mn.us](mailto:george.niemeyer@ci.stpaul.mn.us) or call me at 651-266-8991 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

George Niemeyer  
Fire Safety Inspector

Reference Number 11020