

Date: April 06, 2022
File #: 17 - 081394
Folder Name: 1839 IVY AVE E
PIN: 232922320167



Date: April 06, 2022
File #: 17 - 081394
Folder Name: 1839 IVY AVE E
PIN: 232922320167



Date: April 06, 2022
File #: 17 - 081394
Folder Name: 1839 IVY AVE E
PIN: 232922320167



Date: April 06, 2022
File #: 17 - 081394
Folder Name: 1839 IVY AVE E
PIN: 232922320167



Date: April 06, 2022
File #: 17 - 081394
Folder Name: 1839 IVY AVE E
PIN: 232922320167



Date: April 06, 2022
File #: 17 - 081394
Folder Name: 1839 IVY AVE E
PIN: 232922320167



Date: April 06, 2022
File #: 17 - 081394
Folder Name: 1839 IVY AVE E
PIN: 232922320167



Date: April 06, 2022
File #: 17 - 081394
Folder Name: 1839 IVY AVE E
PIN: 232922320167

Model Number 58STA070 -- -- 16108
Serial Number 2619A19683

ANS Z21.47-2016 - CSA 2.3-2016
Central Furn

Carrier Corporation
7310 West Morris Street
Indianapolis, IN 46231

DESIGN CERTIFIED

PRODUCT 58STA070 -- -- 16108
MODEL 58STA070-08
SERIES 8
SERIAL 2619A19683
DATE OF MANUFACTURE JUN 2019

AHRI CERTIFIED
www.ahridirectory.org

NATURAL GAS
FACTORY ORIFICE 43

HEAT STAGE

INPUT	BTU/HR	66,000
OUTPUT	BTU/HR	53,000
AIR TEMPERATURE RISE	DES. F	40-70
DESIGN MAX. OUTLET AIR TEMPERATURE	DES. C	22-39
	DES. F	165
	DES. C	66
MAX. HEATING EXT. STATIC PRESSURE	IN. W.C./GCS	KPa
MAX. INLET GAS PRESS.	0.5	0.125
MIN. INLET GAS PRESS.	13.5	3.39
	4.5	1.13
FOR PURPOSE OF INPUT ADJUSTMENT	ALTIMETER	2.2-2.3
		0.90-0.95

SECTION 1: GENERAL INFORMATION AND DIMENSIONS

FIRE ASPHYXIA

Improper adjustment,
maintenance, or
serious injury or

Read and follow in
precautions in Use
provided with this f
and service must be
qualified service age
supplier.

CAUTION

Check entire gas assem
lighting this appliance.

INSTALLATION

1. This furnace must be installed in accordance with the manufacturer's instructions and local codes. In the absence of local codes, follow the Fuel Gas Code ANSI Z223.1 or CSA B-149.1 Gas Installation.
2. This furnace must be installed in accordance with the provisions for combustion air. See manufacturer's installation information provided with this furnace.

OPERATION

This furnace is equipped with the limit switch(es) in burner compartment to protect against overheating conditions. If a limit switch is tripped, the furnace will not operate until the limit switch is reset. Do not attempt to reset the limit switch if the furnace is not operating properly. If the limit switch is tripped, contact a qualified service technician for assistance.

WARNING
ELECTRIC SHOCK HAZARD
Disconnect the electric power before servicing.

Date: April 06, 2022
File #: 17 - 081394
Folder Name: 1839 IVY AVE E
PIN: 232922320167



Date: April 06, 2022
File #: 17 - 081394
Folder Name: 1839 IVY AVE E
PIN: 232922320167



Date: April 06, 2022
File #: 17 - 081394
Folder Name: 1839 IVY AVE E
PIN: 232922320167



Date: April 06, 2022
File #: 17 - 081394
Folder Name: 1839 IVY AVE E
PIN: 232922320167



Date: April 06, 2022
File #: 17 - 081394
Folder Name: 1839 IVY AVE E
PIN: 232922320167



Date: April 06, 2022
File #: 17 - 081394
Folder Name: 1839 IVY AVE E
PIN: 232922320167



Date: April 06, 2022
File #: 17 - 081394
Folder Name: 1839 IVY AVE E
PIN: 232922320167

