

NFIRS-1 Basic

Α						
62210 FDID		2 31 onth Day	2021 Year	(04)	SPFD211231057289 umber	Exposure
B Location Type Street Address Intersection In Front Of Rear Of Adjacent To Directions US National Grid	829 L Number Pr Apt./Suite/Room Cross Street	efix Street Saint F City	or Highway aul		ST-Street Street Type MN State	Census tract: 0345.00 E-East Suffix S5106 Zip Code
C Incident Type 111-Building fire D Aid Given Or Receive 1 Mutual Aid Receive			E1 Dates and Alarm Arrival Controlled Last Unit Cleared	12 31 2021 12	:25	2 Shifts and Alarms C 1 D3 Shift Alarms District or Platoon
2 Auto. Aid Recei 3 Mutual Aid Give 4 Auto. Aid Given 5 Other Aid Giver None	rheir FDID	Their State ont Number			E	Special Studies 9244 4- Unknown ID# Value
F Actions Taken 11-Extinguishment by personnel Primary Action Taken		G1 Resources Apparatus or Module is used. App Suppressibal EMS 3 Other 1 Resource coureceived resource	errsonnel 0	G2 Estimated D Losses: Property: Contents: Pre-Incident V Property: Contents:	known. non-fir \$ 20,0 \$ 2,00	ed for all fires if Optional for all es. 000.00 None

Completed Modules 2 - Fire 3 - Structure Fire 4 - Civilian Fire Cas. 5 - Fire Service Cas. 6 - EMS 7 - Haz/Mat 8 - Wildland Fire 9 - Apparatus 10 - Personnel 11 - Arson	H1 Casualties None Deaths Injuries Fire Service 0 0 0 Civilian 0 0 H2 Detector Required for Confined Fires 1 - Detector Alerted Occupants 2 - Detector Did Not Alert Them 3 - Unknown		H3 Hazardous Materials Rele 1 - Natural Gas 2 - Propane Gas 3 - Gasoline 4 - Kerosene 5 - Diesel Fuel / Fuel Oil 6 - Household Solvents 7 - Motor Oil 8 - Paint 0 - Other None	Mixed Use Property Not Mixed 10 - Assembly Use 20 - Education Use 33 - Medical Use 40 - Residential Use 51 - Row Of Stores 53 - Enclosed Mall 58 - Business and Residential 59 - Office Use 60 - Industrial Use 63 - Military Use 65 - Farm Use 00 - Other Mixed Use
Property Use None Structures 131 Church, Place of Worship 161 Restaurant or Cafeteria 162 Bar/Tavern or Nightclub 213 Elementary School, Kindegarten 215 High School, Junior High 241 College, Adult Education 311 Nursing Home 331 Hospital		341 Clinic, Clinic-Type I 342 Doctor/Dentist Of 342 Prison or Jail, Not 419 1- or 2-Family Dwe 429 MultiFamily Dwelli 439 Rooming/Boarding 449 Commerical Hotel 459 Residential, Board 464 Dormitory/Barrack 519 Food and Beverage	Fice 571 Gas of Juvenile 579 Moto Uluyenile 579 Moto Uling 599 Busin ng 615 Elect 1 House 629 Labo or Motel 700 Manu and Care 819 Lives ss 882 Non-	sehold Goods, Sales, Repairs or Service Station or Vehicle/Boat Sales/Repairs ness Office ric-Generating Plant ratory/Science Laboratory Jfacturing Plant tock/Poultry Storage (Barn) Residential Parking Garage
Outside 124 Playground or Park 655 Crops or Orchard 669 Forest (Timberland) 807 Outdoor Storage Area 919 Dump or Sanitary Landfill 931 Open Land or Field 936 Vacant Lot		938 Graded/Cared for I 946 Lake, River, Strean 951 Railroad Right-of-V 960 Other Street 961 Highway/Divided H 962 Residential Street, 981 Construction Site 984 Industrial Plant Yai	NVay Look up and description o	enter a Property Use code and nly if you have NOT checked a
K2 Owner Local Option	 Person/Er	tity Type Bus	iness Name (if applicable) P	hone Number
	First Name	MI	Last Name	Suffix
Mr., Ms., Mrs.				
Mr., Ms., Mrs. L Number	Prefix	Street or Highway	Street Type	Suffix
L	Prefix	Street or Highway L Apt./Suite/Room	Street Type City	Suffix
L Number	Prefix	L Apt./Suite/Room		Suffix
L Number L Post Office Box L State L Remarks:	atched to smoke cor	Apt./Suite/Room L Zip	City Code ntial structure. On arrival Distr	ict Chief 3 upgraded the fire
L Number L Post Office Box L State L Remarks: Fire crews were dispresponse to a fire assignment of the state	atched to smoke cor nment due to heavy ed an 1 3/4 attack ho ed up Squad 1. Ladc	Apt./Suite/Room Zip Ining from a 2.5 story reside a smoke coming from the at use line through side Charlie or 7 performed a primary s	City Code ntial structure. On arrival Distr tic. The structure was vacant are	ict Chief 3 upgraded the fire nd condemned.
L Number L Post Office Box L State L Remarks: Fire crews were disp. response to a fire assig Squad 1's crew deploys with a bundle and back the second floor. Engin Engine 4 and Ladder 7 performed fire investic Coordinator assisted w	atched to smoke cor Inment due to heavy ed an 1 3/4 attack ho led up Squad 1. Lado le 24 and Engine 9 e performed roof ven Jation duties. Distric ith rehab.	Apt./Suite/Room Zip Ining from a 2.5 story reside smoke coming from the at use line through side Charlie er 7 performed a primary s stablished water supplies. tilation in several locations t Chief 2 was Safety Officer	City Code ntial structure. On arrival Distr tic. The structure was vacant are	ict Chief 3 upgraded the fire and condemned. e 17's crew deployed a 2 1/2 and then performed overhaul on adder 8 was IRIT and Squad 2 ditions while Car 50-EMS
L Number L Post Office Box L State L Remarks: Fire crews were disp. response to a fire assig Squad 1's crew deploys with a bundle and back the second floor. Engin Engine 4 and Ladder 7 performed fire investic Coordinator assisted w	atched to smoke cor Inment due to heavy ed an 1 3/4 attack ho led up Squad 1. Lado le 24 and Engine 9 e performed roof ven Jation duties. Distric ith rehab.	Apt./Suite/Room Zip Ining from a 2.5 story reside smoke coming from the at use line through side Charlie er 7 performed a primary s stablished water supplies. tilation in several locations t Chief 2 was Safety Officer	City Code ntial structure. On arrival District. The structure was vacant are for primary fire attack. Enginearch on all floors (Negative) a due to fire in the knee walls. Leand provided side Charlie conditions.	ict Chief 3 upgraded the fire and condemned. e 17's crew deployed a 2 1/2 and then performed overhaul on adder 8 was IRIT and Squad 2 ditions while Car 50-EMS
L Number L Post Office Box L State L Remarks: Fire crews were disp. response to a fire assig Squad 1's crew deploys with a bundle and back the second floor. Engin Engine 4 and Ladder 7 performed fire investic Coordinator assisted w Fire was contained to to	atched to smoke cor Inment due to heavy ed an 1 3/4 attack ho led up Squad 1. Lado le 24 and Engine 9 e performed roof ven Jation duties. Distric ith rehab. he attic and second	Apt./Suite/Room Zip Apt./Suite/Room Zip Ining from a 2.5 story reside e smoke coming from the at use line through side Charlie er 7 performed a primary s stablished water supplies. tilation in several locations t Chief 2 was Safety Officer floor. The structure was vac	City Code Intial structure. On arrival District. The structure was vacant at error primary fire attack. Enginearch on all floors (Negative) adue to fire in the knee walls. Leand provided side Charlie concentrations and board up was contacted.	ict Chief 3 upgraded the fire and condemned. e 17's crew deployed a 2 1/2 and then performed overhaul on adder 8 was IRIT and Squad 2 ditions while Car 50-EMS and to secure the building.
L Number L Post Office Box L State L Remarks: Fire crews were dispresponse to a fire assigned and back the second floor. Engine Engine 4 and Ladder 7 performed fire investic Coordinator assisted we fire was contained to the second floor.	atched to smoke cor Inment due to heavy ed an 1 3/4 attack ho led up Squad 1. Lado le 24 and Engine 9 e performed roof ven Jation duties. Distric ith rehab.	Apt./Suite/Room Zip Ining from a 2.5 story reside smoke coming from the at use line through side Charlie er 7 performed a primary s stablished water supplies. tilation in several locations t Chief 2 was Safety Officer	City Code ntial structure. On arrival District. The structure was vacant are for primary fire attack. Enginearch on all floors (Negative) a due to fire in the knee walls. Leand provided side Charlie conditions.	ict Chief 3 upgraded the fire and condemned. e 17's crew deployed a 2 1/2 and then performed overhaul on adder 8 was IRIT and Squad 2 ditions while Car 50-EMS
L Number L Post Office Box L State L Remarks: Fire crews were dispressionse to a fire assignment of the second floor. Engine Engine 4 and Ladder 7 performed fire investic Coordinator assisted were was contained to the second floor. M Authorization 4588	atched to smoke cor inment due to heavy ed an 1 3/4 attack ho ed up Squad 1. Lado e 24 and Engine 9 e performed roof ven jation duties. Distric ith rehab. he attic and second	Apt./Suite/Room Zip Ining from a 2.5 story reside smoke coming from the at the set line through side Charlie er 7 performed a primary stablished water supplies. Cilation in several locations the Chief 2 was Safety Officer floor. The structure was vacational control of the structure w	City Code Intial structure. On arrival Districtic. The structure was vacant and erfor primary fire attack. Enginearch on all floors (Negative) and due to fire in the knee walls. Larand provided side Charlie concentrations and board up was contacted.	ict Chief 3 upgraded the fire and condemned. e 17's crew deployed a 2 1/2 and then performed overhaul on adder 8 was IRIT and Squad 2 ditions while Car 50-EMS and to secure the building.

NFIRS-2 Fire

	NFIR5-2	riie				
A 62210 MN 12 FDID State Month	31 2021 Day Year	Station #4 SPFD21123105 Station Number	7289 0 Exposure			
B Property Details B1 2 Not Residentia Estimated number of residential living u whether or not all units became involved B2 1 Buildings Not In Number of buildings involved B3 None Less U Acres burned (outside fires)	nits in the building of origin I nvolved	C On-Site Materials Or Products	On-Site Materials Storage Use			
D1 74-Attic: vacant, crawl space above top story Area of Fire Origin D2 10-Heat from powered equipment, other Heat Source D3 10-Structural component or finish, other Item First Ignited D4 65-Fiberboard, particleboard, and hardboard	ct of Nature ause Under Investigation ause Undetermined After	Human Factors Contributing to Ignition Check all applicable boxes None 1 - Asleep 2 - Possibly impaired by alcohol or drugs 3 - Unattended person 4 - Possibly Mentally Disabled 5 - Physically Disabled 6 - Multiple Persons Involved 7 - Age Was A Factor Estimated Age of Person Involved Male Female				
F1 Equipment Involved In Ignition None Equipment Involved Brand Model Serial # Year	F2 Equipment Power Source Equipment Power Source F3 Equipment Portability 1 - Portable 2 - Stationary Portable equipment normally persons.	can be moved by one or two	G Fire Suppression Factors			
H1 Mobile Property Involved 1 - Not involved in ignition, but burned 2 - Involved in ignition, but did not burned 3 - Involved in ignition and burned None Mobile Property Model License Plate Number	H2 Mobile Property Type at L Mobile Property Type Mobile Property Make Year VIN	nd Make	Pre-Fire Plan Available Arson Report Attached Police Report Attached Coroner Report Attached Other Reports Attached			

NFIRS-3 Structure Fire

	141 IV2-2 2CI acca	C 1	11 C		
I1 Structure Type 1 - Enclosed Building 2 - Portable/Mobile Structure 3 - Open Structure 4 - Air-Supported Structure 5 - Tent 6 - Open Platform 7 - Underground Structure 8 - Connective Structure 0 - Other	Building Status 1 - Under Construction 2 - In Normal Use 3 - Idle, Not Routinely Used 4 - Under Major Renovation 5 - Vacant and Secured 7 - Being Demolished 0 - Other U - Undetermined		Building Height 3 Number of Stories At/Above Grade 1 Number of Stories Below Grade		Main Floor Size 900 Total Square Feet OR BY Length (ft) X Width (ft)
J1 Fire Origin 3 Below Grade Story of Fire Origin J2 Fire Spread Confined to Object of Origin 3 - Confined to Building of Origin 4 - Confined to Building of Origin 5 - Beyond Building of Origin 5 - Beyond Building of Origin		ige (1-24 Damage age (50- mage (7	Most to Flame Spread K1 Lem Contributing Most to Flame Spread K2 Lem Contributing Most to Flame Spread K2 Lem Contributing Most to Flame Spread K2 Lem Contributing Most to Flame Spread		Flame Spread Contributing Most ame Spread of Material Contributing
L1 Presence of Detectors N - None Present 1 - Present U - Undetermined	L3 Detector Power Supply 1 - Battery Only 2 - Hardwire Only 3 - Plug-In 4 - Hardwire With Battery 5 - Plug-In With Battery 6 - Mechanical	1 - 2 - 3 - 4 -	Detector Effectiveness 1 - Alerted Occupants, Occupants Responded 2 - Alerted Occupants, Occupants Failed to Respond 3 - There Were No Occupants 4 - Failed to Alert Occupants U - Undetermined		
L2 Detector Type 1 - Smoke 2 - Heat 3 - Combination of Smoke and Heat 4 - Sprinkler, Water Flow Detection 5 - More Than One Type Present 0 - Other U - Undetermined	7 - Multiple Detectors & Power Supplies 0 - Other U - Undetermined L4 Detector Operation 1 - Fire Too Small To Activate 2 - Operated 3 - Failed To Operate U - Undetermined		Detector Failure Reason 1 - Power Failure, Shutoff, or Disconnect 2 - Improper Installation or Placement 3 - Defective 4 - Lack of Maintenance, Dirty 5 - Battery Missing or Disconnected 6 - Battery Discharged or Dead 0 - Other U - Undetermined		
M1 Presence of Automatic Extinguishing System N - None Present 1 - Present 2 - Partial System Present U - Undetermined M2 Type of Automatic Extinguishing System	M3 Operation of Automatic Extinguishing System 1 - Operated/Effective 2 - Operated/Not Effective 3 - Fire Too Small To Activate 4 - Failed To Operate 0 - Other U - Undetermined Required if fire was within designed range		M5 Reason for Automatic Extingu System Failure 1 - System Shut Off 2 - Not Enough Agent Discha 3 - Agent Discharged But Did 4 - Wrong Type of System 5 - Fire Not In Area Protected 6 - System Components Dam 7 - Lack of Maintenance 8 - Manual Intervention 0 - Other U - Undetermined Required if system failed or not eff		ff Jent Discharged Jed But Did Not Reach Fire System a Protected Jenents Damaged nance ention
1 - Wet-Pipe Sprinkler 2 - Dry-Pipe Sprinkler 3 - Other Sprinkler System 4 - Dry Chemical System 5 - Foam System 6 - Halogen-Type System 7 - Carbon Dioxide System 0 - Other U - Undetermined Required if fire was within designed range of AES	M4 Number of Sprinkler Heads Operating Required if system operated		Required I	i system ralli	ed of not effective