

□ Other

APPLICATION FOR APPEAL

NOV 18 2011 CITY CLERK

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

The City Clerk needs the following to process your appeal:	
\$25 filing fee payable to the City of Saint Paul	VOLUE HEADDIG D. (155)
(if cash: receipt number) Copy of the City-issued orders or letter which	YOUR HEARING Date and Time:
are being appealed	Tuesday, 12 -6-11
☐ Attachments you may wish to include ☐ This appeal form completed	Time/:30
•	Location of Hearing:
Walk-In OR Mail-In	Room 330 City Hall/Courthouse
Address Being Appealed:	
Number & Street: 124 bexington Pkwy N City: St. Paw State: MN Zip: 55103	
Appellant/Applicant: Benjamin Robers	Email Blackstrebora ADL'Com
Phone Numbers: Business Residence	
Signature: Benjamin Robert	Date:
Name of Owner (if other than Appellant):	
Address (if not Appellant's): 1493 GRAND Aul, St. Paul, MN, 55/05	
Phone Numbers: Business Residence	Cell (651) 398-1147
What Is Being Appealed and Why? Attachments Are Acceptable	
Vacate Order/Condemnation/	10 10 10 10 10 10
Revocation of Fire C of O Summary/Vehicle Abatement Summary/Vehicle Abatement	taking for veryance on
□ Fire C of O Deficiency List	as pleams to coal
¥ Fire C of O: Only Egress Windows	*
□ Code Enforcement Correction Notice	
□ Vacant Building Registration	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

October 19, 2011

BENJAMIN ROBERTS 1493 GRAND AVE ST PAUL MN 55105-2714

FIRE INSPECTION CORRECTION NOTICE

RE:

124 LEXINGTON PKWY N

Ref. #101916

Residential Class: C

Dear Property Representative:

Your building was inspected on October 19, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A reinspection will be made on November 29, 2011 at 2:00 PM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. 1 SPLC 34.19 Provide access to the inspector to all areas of the building.
 - 2. Basement SPLC 34.12 (2), 34.35 (1) Repair and maintain all required and supplied equipment in an operative and safe condition.-Remove or repair unused appliances.
 - 3. Double hung MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI

at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.Second floor north
19.5 h x 37.5 w Glazed 9.6 sq ft
Second floor south
18.5 h x 37.5 w Glazed 9.6 sq ft

- 4. Exterior SPLC 34.09 (1) b,c, 34.32 (1) b,c Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.-Scrape and remove chipped and peeling paint.
- 5. Exterior MN Stat 299F.18 Immediately remove and discontinue excessive accumulation of combustible materials.-Reduce storage of cardboard and wood from the basement by 20 percent.
- 6. First floor bedroom MSFC 1011.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.-Reduce storage by 25 percent.
- 7. Second floor SPLC 34.10 (7), 34.33 (6) Repair and maintain the floor in an approved manner.-Current unfinished floor is a tripping hazard.
- 8. Second floor steps SPLC 34.10 (3), 34.33(2) Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.
- 9. ZCADILLAC SEVILLE MAROON SEG387 SPLC 163.03, 163.01 (2), (3) Currently license (tabs) all vehicles on the property and return the vehicles to an operative mechanical condition or remove vehicles from the property.-Inoperable.
- 10. SPLC 71.01 The address posted is not visible from street. (HN-1)-Provide address numbers that contrast with the background.
- 11. SPLC 34.08 (1), 34.31 (1) All exterior property areas shall be maintained free from any accumulation of refuse, garbage or feces. Remove pile of furniture south of shed,
- 12. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 13. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse,

15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: rick.gavin@ci.stpaul.mn.us or call me at 651-266-8994. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Rick Gavin Fire Inspector

Reference Number 101916