www.nardinifire.com / sales@nardinifire.com

		WET A	GENT	T FIRE	SUP	PRESSIO	N SY	YSTEM	1 INS	SPECT	ΓΙΟΝ	AN	D TE	STING	REPORT	1				
Work Site #: 1829									_	Service Ticket #: ST00162886										
Name of Facility: BEST STEAK HOUSE									Ir	Installation/Service Report Date: 10/22/2020										
Street Address: 1676 WHITE BEAR AVE.											Time In: 400 Time Out: 484									
										_	Last Maintenance Date: 2020-01-22									
City: SAINT PAUL State: MN Zip: 55																				
Auth. Contact: IRENE-651-501-7442, Phone: 6517765419										_	System 1 of 1 System location:									
Suppression System Type Panel Type (electrical only)																				
Manufacturer: Protex Model: Protex II								Mar	Manufacturer: Serial #: Rev #:											
Type of Agent: Wet Agent Serial #: Model:																				
Water flow connection: Waterline union above system tank: Lockable valv												lve accessible	9							
Water flow pressi		Tamper Sw	itch Fi						Electrical appliance shutdown Alarm Forced exhaust Makeup air Other											
		- III-F						ROL/I												
							0111	ROL/I		D/ I/OL	DIXI	4.1								
Manufacturer	anufacturer Mech/Elec Model Year Test A				of ators									Damage. Corrosio						
Protex	Mechanica		tex2		003	2016	_	1								Othe			Corrosio	
Hotex	Wicchamet	110	ICAL	20	703	2010		1			Top of tank					Ouic				
	<u> </u>																			
							EXP	ELLA	NT (GAS L	INE						_			
										Dista										
Expellant Line Material		Leal			Hose Dates			Dama		with					,	ъ.	Ι,		Inspected	
		Test		Hose		Dates		Corro	sion		Limit		Cartridge Type		ype	Date	_	Weight	Replaced	
Oth	er	Pass						Pa			ss N2				01/2019	12	2 grams	Inspected		
1							TAN	K/CYI	LINI	DER D	<u>ATA</u>			, ,						
			Pressure Gauge in																	
				Proper																
				Last	Rar															
			_	Internal	Cyli		Val				# (****	# of		overage		mage/		
Manufacturer	Mode		ate	Test Full I		Mod	del	_	nifold'.	_		IPI	Flows		Area C Entire Hazard		rosion	Serial #		
Protex	L4600) 20	003	2016) Pass			No		6 Pas		Pass	6	Entire riazard		-	No			
									-		-						-			
											<u> </u>									
									-		-						-			
											<u> </u>									
									-		-						-			
											<u> </u>									
											<u> </u>	_					1			
											<u> </u>	_					1			
									_		<u> </u>									
									_		1						-			
									_		1						-			
									_		1						-			
									_		1									
											1									
									ZZL											
Plenum 1 Duct 2 Range Griddle 1 Fryer 1 Broiler Up. Broiler Chain Broiler																				
	Salamander		Wok	k	-	Γilt		Skillet		_	Cettle		1	Pizza Ov	en	Other				
								ETEC'												
Mashs::1/			T.	mr of		Tues of														
Mechanical/							nks/Tu			naratas Dal			Datactor Housing M.			Domaga/ Ca		ge/ Corrosion		
Electric/Pneumatic # of Detec						+				perates Release			Detector Housing Model Damag Series			corrosion				
Mechanical		2		500		Link		2			Pass				Ser	ies				
					_															
			1		1		- 1											l		

www.nardinifire.com / sales@nardinifire.com

						REM	OTE RELE	ASE DA	TA					
Mechanical/ Electric/Pneumatic Manufacturer						Operable?	Height from Floor (Inches)		At Pt. of Egress		Distance from Hood (Feet)	Damage/ Corrosion		
Mechanical Protex					Pass			Pass		9				
						-	GAS VALVE	DATA						
							JAS VALVE	DATA						
	nanical/ Pneumatic	Monu	Size Manufacturer (Inches)			I	ocation		Manual Reset Relay	Operable I		fno why?	Damage/ Corrosion	
				3/4						Yes	If no, why?		Corrosion	
Mechanical		11	Protex 3/4		Dem	Behind fryer		No	103					
						ELEC	CTRICAL FU	JNCTIO	NS					
Function Micro/ Switch Breake Pressure Operates Relay						Breaker/Relay Location								
Exhaust Micro Yes			Yes	Rela	y									
						-								
						NOTIFIC	CATION/AN	NUNCIA	ATION				l .	
Dials Out or Alarmed Local Received Fire Panel Location					itoring Compa		Monitor Co. Phone # Account		Account #	and password	System Normal			
No														
	C	tom/Hogor	d Inconcetion	_		Yes/No/N	AT A				Comments			
							NA				omments			
 Blow off caps replaced / Nozzle seals? Filters installed and in good condition? 														
System installed utilizing good construction practices?						Yes Yes								
Hood penetrations sealed with UL listed device?														
5. Hazard changes?														
6. System installed per manufacturer specifications?														
7. System complies with all local codes and standards?						No Yes								
8. System meets UL300 listing?						Yes								
9. System red tagged?						Yes	Imprope	Improper nozzle coverage over fryer and broiler						
10. Proper hand portable extinguisher near hood & serviced?						Yes	1							

Comments:

Lead	Mark Lottie		
2nd		Victor	

Nardini Fire Technician

Customer / Authorized Agent – Printed Name

Customer / Authorized Agent - Signature