

CITY OF SAINT PAUL

375 Jackson Street, Suite 220 Saint Paul, MN 55101-1806 Telephone: 651 - 266 - 8989 Facsimile: 651 - 266 - 9124 www.stpaul.gov/dsi

Code Compliance Report

February 18, 2021

* * This Report must be Posted on the Job Site * *

Maurice L Griffin PO Box 803 Willernie MN 55090

Re: 521 York Ave File#: 19 070000 VB3

Dear Property Owner:

The following is the Code Compliance report you requested on December 30, 2020.

Please be advised that this report is accurate and correct as of the date February 18, 2021. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from February 18, 2021. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected. A Legislative Code exemption (Chapter 33.03(f)) allows a Category 2 Vacant Building to be sold "as is" providing the buyer, prior to closing, completes an approval process. For further information, call Reid Soley at 651-266-9120.

ZONING

- 1. This property is in a(n) R4 zoning district.
- 2. This property was inspected as a Single Family Dwelling.

BUILDING Inspector: Nathan Bruhn Phone: 651-266-9033

- 1. Insure basement cellar floor is even, is cleanable, and all holes are filled. SPLC 34.10 (1)
- 2. Repair walls, ceiling and floors throughout, as necessary. SPLC 34.34 (6)
- 3. Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present. SPLC 34.33 (1)

Re: 521 York Ave February 18, 2021

Page 2

- 4. Any framing members that required repair or do not meet code (where wall and ceiling covering is removed, members that are over-spanned, over-spaced, not being carried properly, door and window openings that are not adequately supported, etc.) are to be reconstructed in an approved manner. SPLC 34.34 (1)
- 5. Air-seal and insulate attic/access door. MN Energy Code Ch 1322.1102.4
- 6. Install Smoke Detectors/Carbon Monoxide Detectors per MN Conservation Code and the MN Dept. of Labor and Industry: Install per code where feasible. MNRC Ch 1309 Sect 313.2.1
- 7. Provide major clean-up of premises. SPLC 34.34 (4)
- 8. Install water-proof enclosure in shower area. MNRC Ch 1309 Sect. 307
- 9. Provide weather sealed, air sealed and vermin sealed exterior. SPLC 34.32 (2)
- 10. Replace or repair landing and stairway per code. SPLC 34.09 (2)
- 11. Repair siding, soffit, fascia, trim, etc. as necessary. SPLC 34.09 (1)
- 12. Weather seal basement bulk head using approved materials. SPLC 34.09 (1b)
- 13. Install downspouts and a complete gutter system. SPLC 34.33 (1d)
- 14. Repair chimney in an approved manner. SPLC 34.09 (1)
- 15. Provide durable, dustless parking surface as specified in the zoning code. SPLC 34.08 (7)
- 16. Install handrails (34 inches 38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment. MNRC Ch 1309 Sect. 311 & 312
- 17. Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary. SPLC 34.09 (3)
- 18. Provide functional hardware at all doors and windows. SPLC 34.09 (3f)
- 19. Exit doors shall be capable of being opened from the inside, easily and without the use of a key. Remove all surface bolts. SPLC 34.09 (3h)
- 20. Repair or replace damaged doors and frames as necessary, including storm doors. SPLC 34.09 (3f)
- 21. Weather seal exterior doors, threshold and weather-stripping. SPLC 34.09 (3f)
- 22. Install floor covering in bathroom and kitchen that is impervious to water. SPLC 34.10 (4)
- 23. A building permit is required to correct the above deficiencies. All work is to be done in a workmanship like manner. SPLC 33.03 (a)

ELECTRICAL Inspector: Randy Klossner Phone: 651-266-9032

- 1. Ensure/rewire all electrical associated with NM cables dated after 2000 to current NEC. An electrical permit was never purchased for that wiring. SPLC 33.03 (d)
- 2. Remove and/or rewire all illegal, improper or hazardous wiring to current NEC.
- 3. Repair damaged electrical to current NEC.
- 4. Repair the electrical service grounding conductor to the metallic water piping system. Install a conductor sized to Table 250.66 (NEC) from the electrical service to within 5' of the entrance point of the water service, and bond around

Re: 521 York Ave February 18, 2021

Page 3

the water meter. Article 250, NEC

- 5. Verify that fuse/circuit breaker amperage matches wire size in panel. Replace improperly sized overcurrent devices. Article 240.4, NEC
- 6. Close openings in service panel/junction boxes with knockout seals, breaker blanks, proper cable clamps, and/or junction box covers. Article 110.12 (A), NFC
- 7. Properly strap and support cables and/or conduits. Chapter 3, NEC
- 8. Repair or replace all broken, painted over, corroded, missing or loose receptacles, luminaires (light fixtures), switches, covers and plates to current code. Article 406.4(D) & Article 410, NEC
- 9. Check all receptacles for proper polarity (including 2-prong) and verify ground on 3-prong receptacles. Ensure all GFCI receptacles are functioning properly. Rewire and/or replace receptacles that are improperly wired or not functioning properly. Article 406.4(D), NEC
- 10. Install box extensions on devices mounted in wood paneling. Article 314.20, NEC
- 11. Install hard-wired, battery backup, Carbon Monoxide smoke detector as specified in Chapter 58 of the Saint Paul Legislative Code, and other smoke detectors and carbon monoxide detectors as required by the Minnesota State Building Code. SPLC 58, IRC
- 12. All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

PLUMBING Inspector: Paul Zellmer Phone: 651-266-9048

- 1. Basement -Gas Piping -(MFGC 411) Install an approved shut off; connector and gas piping for the dryer.
- 2. Basement -Gas Piping -(MFGC 614.1-614.7) Vent clothes dryer to code.
- 3. Basement -Laundry Tub (MPC .0100 & 901) Install a proper fixture vent to code.
- 4. Basement -Laundry Tub (MPC 701) Install the waste piping to code.
- 5. Basement -Laundry Tub (MPC .0100 B) Provide the proper potable water protection for the faucet spout.
- 6. Basement -Soil and Waste Piping -(MPC 709.1) Install a front sewer clean out.
- 7. Basement -Soil and Waste Piping -(MPC .0100 M) Replace all corroded cast iron, steel waste or vent piping.
- 8. Basement -Water Heater (MPC 507.5) Correct the pressure and temperature relief valve discharge.
- 9. Basement -Water Heater (MFGC 409) Install the gas shut off and the gas piping to code.
- 10. Basement Water Heater (MFGC 503) Install the water heater gas venting to code.
- 11. Basement Water Heater (MPC 501) Install the water piping for the water heater to code.
- 12. Basement -Water Heater -(MPC .0100 Q)The water heater must be fired and in service.

Re: 521 York Ave February 18, 2021 Page 4

- 13. Basement Water Meter (MPC 609.11) Support the water meter to code.
- 14. Basement Water Meter (MPC 606.2) The service valves must be functional and installed to code.
- 15. Basement Water Piping (SPRWS 93.07) Provide a one (1) inch water line to the first major take off.
- 16. Basement Water Piping (MPC 301.1 (3)) Repair or replace all the corroded, broken, or leaking water piping.
- 17. Basement Water Piping (MPC 603.5.10) Install a proper backflow assembly or device for the boiler fill water line.
- 18. Exterior Lawn Hydrants (MPC 301.1) Repair or replace the lawn hydrants that are broken or have parts missing.
- 19. First Floor -Sink -(MPC .0100 E & 901) Install a proper fixture vent to code.
- 20. First Floor -Sink (MPC 701) Install the waste piping to code.
- 21. Second Floor -Toilet Facilities (MPC 402.6) Install a proper flanged fixture connection on a firm base.
- 22. Second Floor -Tub and Shower -(MPC .0100 P & Q & 419.2) Install the water piping to code.
- 23. Second Floor Tub and Shower (MPC 408.3) Install scald and thermal shock protection, ASSE Standard 1016.
- 24. Second Floor Tub and Shower (MPC 409.4) Install a hot water temperature limiting device, ASSE Standard 1070.
- 25. All the above corrections to waste, vent, water, and gas piping shall be per the Minnesota Plumbing Code Chapter 4714, Minnesota Rules Chapter 326, 4716, 1300, the Minnesota Mechanical Code, the Minnesota Fuel Gas Code, and Saint Paul Regional Water Services Water Code. All plumbing must be done by a plumbing contractor licensed in the State of Minnesota and the City of St. Paul by a plumber licensed in the State of Minnesota who also possess a City of Saint Paul Competency Card and after obtaining an approved City of Saint Paul Plumbing Permit.

Heating Inspector: Aaron Havlicek Phone: 651-266-9043

- 1. Install approved level handle manual gas shutoff valve on furnace/boiler and remove unapproved valve.
- 2. Clean and Orsat test furnace/boiler burner. Check all controls for proper operation. Check furnace heat exchanger for leak; provide documentation from a licensed contractor that the heating unit is safe.
- 3. Connect furnace/boiler and water heater venting into chimney liner.
- 4. Vent clothes dryer to code and provide approved gas piping and valve (plumbing or mechanical gas permit is required).
- 5. Provide support for gas lines to code.
- 6. Plug, cap and/or remove all disconnected gas lines, non-conforming gas lines and unapproved valves.
- 7. Remove or abate all friable asbestos material. Provide documentation that this work was performed by a state licensed asbestos abatement contractor.
- 8. Mechanical permits are required for the above work.

Re: 521 York Ave February 18, 2021

Page 5

Notes:

- 1. See attachment for permit requirements and appeals procedure.
- 2. This property is designated by the Vacant Buildings Department as a Category #3 which requires a \$5,000.00 Performance Bond or Deposit at the time the permit is issued.
- 3. Roof, sidewalks, etc. snow covered and could not be inspected. All must meet appropriate codes when completed.
- 4. There was considerable storage/clutter within property at the time of the inspection. Property is to meet appropriate codes when complete.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected in accordance with the Minimum Housing Standards of the St. Paul Legislative Code (Chapter 34) and all required permits must receive final approval within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Nathan Bruhn between 7:30 - 9:00 AM at 651-266-9033 or leave a voice mail message.

Sincerely,

Nathan Bruhn Code Compliance Officer Department of Safety and Inspections City of Saint Paul 375 Jackson Street, Suite 220 Saint Paul MN 55101

Phone: 651-266-9033

Email: nathan.bruhn@ci.stpaul.mn.us

Attachments