

NFIRS-1 Basic

^									
62210	MN	02	07	2021	Station #18 (18)	SPFD210207	7005303	0	
FDID	State	Month	Day	Year	Station	Number		Exposure	
B Location Type							l	Census t	ract: 8.00
Street Address Intersection In Front Of Rear Of Adjacent To Directions US National Grid	331 Number	Prefix	LAWSO Street	N or Highway			/E-Avenue eet Type	W- West Suffix	
			Saint Pa	ul		MN	5511	17	
	Apt./Suite/		City			State	Zip C	ode	
С				F1	1		F2 au 6	1.41	
Incident Type 111-Building fire				E1 Dates a Alarm Arrival Controlle	02 07 2021 02 07 2021 02 07 2021 02 07 07 000 000 000 000 000 000 000 00	22:49	Shifts a	1 D2	rict
D Aid Given Or Recei	ived			Last Unit Cleared	02 08 2021	02:22			
1 Mutual Aid Rece 2 Auto. Aid Rece 3 Mutual Aid Give 4 Auto. Aid Giver 5 Other Aid Give None	eived L ived The	ir FDID	Their State umber				E3 Special 9244 ID#	Studies 4 - Unknow Value	wn
F Actions Taken			G1 Resou	ırces		G2			
11-Extinguishment b personnel Primary Action Take 12-Salvage & overhau Additional Action Ta	n Jl		Suppres	Apparatu	nel Module is used. s Personnel 0 0	Losses: Property Content	Required for known. Option non-fires. 7: \$ 42,100.00 5: \$ 10,000.00	all fires if onal for all	None
51-Ventilate			Resources		ude aid received		dent Values: ـ ا	Optional I	None
Additional Action Ta	iken						/: \$ 42,100.00 s:\$ 25,000.00		
						1			

Completed Modules 2 - Fire 3 - Structure Fire 4 - Civilian Fire Cas. 5 - Fire Service Cas. 6 - EMS 7 - HazMat 8 - Wildland Fire 9 - Apparatus 10 - Personnel 11 - Arson	H1 Casualties None Deaths Injuries Fire 0 0 Service 0 Civilian 0 0 H2 Detector Required for Confined Fires 1 - Detector Alerted Occupants 2 - Detector Did Not Alert Them 3 - Unknown	H3 Hazardous Materials Release 1 - Natural Gas 2 - Propane Gas 3 - Gasoline 4 - Kerosene 5 - Diesel Fuel / Fuel Oil 6 - Household Solvents 7 - Motor Oil 8 - Paint 0 - Other None	Mixed Use Property Not Mixed 10 - Assembly Use 20 - Education Use 33 - Medical Use 40 - Residential Use 51 - Row Of Stores 53 - Enclosed Mall 58 - Business and Residential 59 - Office Use 60 - Industrial Use 63 - Military Use 65 - Farm Use 00 - Other Mixed Use
---	---	--	--

Property Use None Structures 131 Church, Place of Worship 161 Restaurant or Cafeteria 162 Bar/Tavern or Nightclub 213 Elementary School, Kindegarten 215 High School, Junior High 241 College, Adult Education 311 Nursing Home 331 Hospital	341 Clinic, Clinic-Type Infirmary 342 Doctor/Dentist Office 361 Prison or Jail, Not Juvenile 419 1- or 2-Family Dwelling 429 Multifamily Dwelling 439 Rooming/Boarding House 449 Commerical Hotel or Motel 459 Residential, Board and Care 464 Dormitory/Barracks 519 Food and Beverage Sales	539 Household Goods, Sales, Repairs 571 Gas or Service Station 579 Motor Vehicle/Boat Sales/Repairs 599 Business Office 615 Electric-Generating Plant 629 Laboratory/Science Laboratory 700 Manufacturing Plant 819 Livestock/Poultry Storage (Barn) 882 Non-Residential Parking Garage 891 Warehouse
Outside 124 Playground or Park 655 Crops or Orchard 669 Forest (Timberland) 807 Outdoor Storage Area 919 Dump or Sanitary Landfill 931 Open Land or Field 936 Vacant Lot	938 Graded/Cared for Plot of Land 946 Lake, River, Stream 951 Railroad Right-of-Way 960 Other Street 961 Highway/Divided Highway 962 Residential Street/Driveway 981 Construction Site 984 Industrial Plant Yard	Property Use: Description Look up and enter a Property Use code and description only if you have NOT checked a Property Use box.

Owner				
Local Option	Person/Ent	ity Type Busine	ss Name (if applicable)	Phone Number
Mr., Ms., Mrs.	First Name	MI	Last Name	Suffix
Number	Prefix	Street or Highway	Street Type	Suffix
Post Office Box		Apt./Suite/Room	City	

L Remarks:

Fire crews responded to structure fires at 329 and 331 Lawson Avenue. These structures were duplexes built approximately 3 to 4 feet apart. It appears the fire started in 331 Lawson on the 1st floor extending to the 2nd floor, attic, and to 329 Lawson's siding, 1st floor, 2nd floor, and the attic.

Engine 22 on arrival deployed 1 3/4 inch hose line extinguishing exterior fire between the homes. Engine 22 then made entry into 329 Lawson extinguishing interior fire in the attic, 1st and 2nd floors. Ladder 22 completed a primary search of 329 Lawson and worked with Engine 22 on fire attack and overhaul.

Engine 18 deployed 1 3/4 inch attack line into the 1st floor of 331 Lawson extinguishing the fire. Squad 1 deployed a 2nd 1 3/4 inch hose line from Engine 18 to the 2nd floor and attic extinguishing the fire. Ladder 18 completed a primary search of the 331 Lawson Avenue.

Chief 3 was safety officer, Engine 8 secured a water supply for Engine 22 and Engine 18, Engine 8 was RIT, Engine 17 and Squad 3 were used for secondary searches, utility control, fire attack, overhaul, and ventilation in both structures. Ladder 22 deployed the aerial ladder to the roof of 331 Lawson.

Medic 5's Captain was the FIT. Medic 5 provided EMS coverage and assisted one resident to a local hotel at the conclusion of the incident.

MTC bus was secured for rehab. Water department shut water off to both structures and checked hydrant at conclusion of incident. Public works was notifi...

Full primary narrative can be found in NFIRS 1S - Supplemental $\,$

^M Authorization							
1835	Baumeister, Arthur	DC	C1	02/08/2021			
Officer In Charge ID	Signature	Position or Rank	Assignment	Date			
1835	Baumeister, Arthur	DC	C1	02/08/2021			
Member Making Report ID	Signature	Position or Rank	Assignment	Date			


NFIRS-2 Fire

Α										
62	2210	MN	02	07	2021	Station #18 (18)	SPFD2102070	005303	0	
FD	ID	State	Month	Day	Year	Station	Number		Exposure	
В						С				
Prop	erty Details					On-Site Materia	la (On-Site Mate	ei ale	
	1.	l				Or Products		Storage Use	:11015	
В1	4]	esidential							
	Estimated number of origin whether									
В2	2	Buildir	ngs Not Inv	olved						
	Number of buildin	ı ıas involved	i							
В3		ī	Less th	nan 1 acre						
	Acres burned (out									
	7,6765 50,11160 (000									
D				E1			E3			
Igni	tion				of Ignition			ctors Contri	buting to	
	21- Bedroom - < 5	persons:	ĺ	1 - Intentional Ignition						
D1	included are jail or				nintentional ailure of Equ	ipment or Heat	applicable boxes			
	Area of Fire Origin	n	•	Source 4 - A	ct of Nature		1 - Asle 2 - Poss	leep ssibly impaired by alcohol or		
D2	61- Cigarette			5 - C	ause Under I	Under Investigation Undetermined After		ss - Unattended person		
	Heat Source		•	Investig		ermined Arter	4 - Poss	ssibly Mentally Disabled		
99- Multiple items first D3 ignited							ysically Disabled Itiple Persons Involved e Was A Factor ed Age of			
	Item First Ignited	1	_	Factors Contributing to Ignition 7 - Ag Estimat						
D4			1							
٥.	Type of Material I	First lanite	<u>_</u>	10- Mi	suse of materia	l or product, other	Person Inv		Female	
Type of Material First Ignited			Factor Contributing to Ignition			- Iviate		emate		
F1				F2				G		
Equi	pment Involved	In Ignitio	n	Equipme	ent Power S	ource		Fire Supp	ression Factors	
⊻ N	one			11				I Name I		
Ш				L Equipme	nt Power Sour	-ce		None Fire Suppression Factor		
Equi	oment Involved		-					-		
Вга	nd			F3	ent Portabili	itv				
Мо	del					icy				
	al#			1 - Portable						
	1 1			2 - Stationary Portable equipment normally can be moved by one or two						
Yea	r			persons.						
							ı			
H1	ila Danashy lav	ماييمط		H2	ila Deanach	. Tupo and Make		Local Use		
	oile Property Invo - Not involved in i		ut hurned	MOD	Mobile Property Type and Make			Pre-Fire F	Plan Available	
2	- Involved in ignit	ion, but di	d not burn	∐ Mobi	le Property Ty	ype		Arson Rep	port Attached	
□ 3 ☑ N	- Involved in ignit one	ion and bu	ırne d	1					port Attached Report Attached	
= None				Mobile Property Make					ports Attached	
L										
Mobile Property Model Year										
State License Plate Number VIN										

NFIRS-3 Structure Fire

	14L1K2-2 2C1 ACCA	reine		
I1 Structure Type 1 - Enclosed Building 2 - Portable/Mobile Structure 3 - Open Structure 4 - Air-Supported Structure 5 - Tent 6 - Open Platform 7 - Underground Structure 8 - Connective Structure 0 - Other J1 Fire Origin 1 Below Grade Story of Fire Origin Confined to Object of Origin 2 - Confined to Room of Origin	Building Status 1 - Under Construction 2 - In Normal Use 3 - Idle, Not Routinely Used 4 - Under Major Renovation 5 - Vacant and Secured 6 - Vacant and Unsecured 7 - Being Demolished 0 - Other U - Undetermined 3 Number of Stories Damaged By Number of Stories w/Minor E Number of Stories w/Signific Number of Stories w/Extrem *Count the roof as part of the higher	Building Height 2	800 STOTAL Square Feet OR	
3 - Confined to Floor of Origin 4 - Confined to Building of Origin 5 - Beyond Building of Origin L1 Presence of Detectors N - None Present 1 - Present U - Undetermined	L3 Detector Power Supply 1 - Battery Only 2 - Hardwire Only 3 - Plug-In 4 - Hardwire With Battery 5 - Plug-In With Battery 6 - Mechanical 7 - Multiple Detectors	Only Only Only 2 - Alerted Occupants, Occupants Respond 3 - There Were No Occupants With Battery With Battery U - Undetermined U - Undetermined		
L2 Detector Type 1 - Smoke 2 - Heat 3 - Combination of Smoke and Heat 4 - Sprinkler, Water Flow Detection 5 - More Than One Type Present 0 - Other U - Undetermined	A Power Supplies 0 - Other U - Undetermined L4 Detector Operation 1 - Fire Too Small To Activate 2 - Operated 3 - Failed To Operate U - Undetermined	2 - Improper Insta 3 - Defective 4 - Lack of Mainte	Shutoff, or Disconnect llation or Placement nance, Dirty g or Disconnected rged or Dead	
M1 Presence of Automatic Extinguishing System N - None Present 1 - Present 2 - Partial System Present U - Undetermined M2 Type of Automatic Extinguishing System 1 - Wet-Pipe Sprinkler 2 - Dry-Pipe Sprinkler 3 - Other Sprinkler System 4 - Dry Chemical System 5 - Foam System 6 - Halogen-Type System 7 - Carbon Dioxide System 0 - Other U - Undetermined Required if fire was within designed range of AES	Extinguishing System 1 - Operated/Effective 2 - Operated/Not Effective 3 - Fire Too Small To Activa 4 - Failed To Operate 0 - Other U - Undetermined Required if fire was within designed range M4 Number of Sprinkler Heads Operating Required if system operated	System Failur 1 - System S 2 - Not Enou a - Agent Di ate 4 - Wrong Ty 5 - Fire Not 6 - System C 7 - Lack of N 8 - Manual Ir 0 - Other U - Undeter	hut Off gh Agent Discharged scharged But Did Not Reach Fire pe of System n Area Protected components Damaged naintenance titervention	

NFIRS-1S Supplemental



Primary Narrative:

Fire crews responded to structure fires at 329 and 331 Lawson Avenue. These structures were duplexes built approximately 3 to 4 feet apart. It appears the fire started in 331 Lawson on the 1st floor extending to the 2nd floor, attic, and to 329 Lawson's siding, 1st floor, 2nd floor, and the attic.

Engine 22 on arrival deployed 1 3/4 inch hose line extinguishing exterior fire between the homes. Engine 22 then made entry into 329 Lawson extinguishing interior fire in the attic, 1st and 2nd floors. Ladder 22 completed a primary search of 329 Lawson and worked with Engine 22 on fire attack and overhaul.

Engine 18 deployed 1 3/4 inch attack line into the 1st floor of 331 Lawson extinguishing the fire. Squad 1 deployed a 2nd 1 3/4 inch hose line from Engine 18 to the 2nd floor and attic extinguishing the fire. Ladder 18 completed a primary search of the 331 Lawson Avenue.

Chief 3 was safety officer, Engine 8 secured a water supply for Engine 22 and Engine 18, Engine 8 was RIT, Engine 17 and Squad 3 were used for secondary searches, utility control, fire attack, overhaul, and ventilation in both structures. Ladder 22 deployed the aerial ladder to the roof of 331 Lawson.

Medic 5's Captain was the FIT. Medic 5 provided EMS coverage and assisted one resident to a local hotel at the conclusion of

MTC bus was secured for rehab. Water department shut water off to both structures and checked hydrant at conclusion of incident. Public works was notified to sand and salt Lawson street /sidewalks between Virginia and Farrington. Xcel Energy locked out gas and pulled electrical meters to both addresses. Board up was called to secure both properties. DSI Inspector 12 condemned the properties as not habitable. Chief 3 made contact with all occupants on scene and connected them with Red Cross.

Captain Blank is the fire investigator for this incident. Call #5303.