

CITY OF SAINT PAUL

375 Jackson Street, Suite 220 Saint Paul, MN 55101-1806

Telephone: 651-266-8989 Facsimile: 651-266-9124 www.stpaul.gov/dsi

Code Compliance Report

December 22, 2022

* * This Report must be Posted on the Job Site * *

Dylan Kersting 295 Stinson St Apt 2 St Paul MN 55117

Re: 593 Cook Ave E File#: 22 062688 VB2

Dear Property Owner:

The following is the Code Compliance report you requested on November 04, 2022.

Please be advised that this report is accurate and correct as of the date December 22, 2022. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from December 22, 2022. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected. A Legislative Code exemption (Chapter 33.03(f)) allows a Category 2 Vacant Building to be sold "as is" providing the buyer, prior to closing, completes an approval process. For further information, call Robert Humphrey at 651-266-9123.

Please note that permits cannot be issued online. Permits must be applied for in person, via fax or mail.

ZONING

- 1. This property is in a(n) RT1 zoning district.
- 2. The property was inspected as a Duplex.

BUILDING Inspector: Clint Zane Phone: 651-266-9029

Re: 593 Cook Ave E December 22, 2022 Page 2

- 1. Remove mold, mildew and moldy or water damaged materials. SPLC 34.10 (1)
- 2. Weather seal exterior doors, threshold and weather-stripping. SPLC 34.09 (3f)
- 3. Install floor covering in bathroom and kitchen that is impervious to water. SPLC 34.10 (4)
- 4. Repair walls, ceiling and floors throughout, as necessary. SPLC 34.34 (6)
- 5. Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present. SPLC 34.33 (1)
- 6. Air-seal and insulate attic/access door. MN Energy Code Ch 1322.1102.4
- 7. Install Smoke Detectors/Carbon Monoxide Detectors per MN Conservation Code and the MN Dept. of Labor and Industry: Install per code where feasible. MNRC Ch 1309 Sect 313.2.1
- 8. Replace or repair landing and stairway per code. SPLC 34.09 (2) ***Specifically entry stairs to porch and stairs leading to basement.
- 9. Repair siding, soffit, fascia, trim, etc. as necessary. SPLC 34.09 (1)
- 10. Provide proper drainage around house to direct water away from foundation of house. SPLC 34.08 (2)
- 11. Provide proper drainage around house to direct water away from foundation of garage. SPLC 34.08 (2)
- 12. Provide adequate access, ventilation and clearance in crawl space area. MNRC Ch 1309 Sect. 408
- 13. Provide general rehabilitation of garage. SPLC 34.32 (3) ***I was not able to gain entry to garage or shed, provide entry for inspection.
- 14. Remove trees which are against foundation of home and garage. SPLC 34.09 (1b)
- 15. Openings in stair risers must be less than 4 inches. MNRC Ch. 1309 Sect. 311/312 ***Entry steps, basement steps and rear deck.
- 16. Trade permits for electrical, warm air, mechanical and plumbing required as necessary.
- 17. Install handrails (34 inches 38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment. MNRC Ch 1309 Sect. 311 & 312
- 18. Strap or support top of stair stringers for structural stability. MNRC Ch 1309 Sect 311.1
- 19. Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary. SPLC 34.09 (3)
- 20. Provide complete storms and screens, in good repair for all door and window openings. SPLC 34.09 (3e)
- 21. Provide functional hardware at all doors and windows. SPLC 34.09 (3f)
- 22. Exit doors shall be capable of being opened from the inside, easily and without the use of a key. Remove all surface bolts. SPLC 34.09 (3h)
- 23. Repair or replace damaged doors and frames as necessary, including storm doors. SPLC 34.09 (3f)
- 24. A building permit is required to correct the above deficiencies. All work is to be done in a workmanship like manner. SPLC 33.03 (a)

Re: 593 Cook Ave E December 22, 2022

Page 3

ELECTRICAL Inspector: Randy Klossner Phone: 651-266-9032

- 1. Verify that fuse/circuit breaker amperage matches wire size in panel. Replace improperly sized overcurrent devices. Article 240.4, NEC
- Close openings in service panel/junction boxes with knockout seals, breaker blanks, proper cable clamps, and/or junction box covers. Article 110.12 (A), NEC
- 3. Repair or replace all broken, painted over, corroded, missing or loose receptacles, luminaires (light fixtures), switches, covers and plates to current code. Article 406.4(D) & Article 410, NEC
- 4. Check all receptacles for proper polarity (including 2-prong) and verify ground on 3-prong receptacles. Ensure all GFCI receptacles are functioning properly. Rewire and/or replace receptacles that are improperly wired or not functioning properly. Article 406.4(D), NEC
- 5. Install box extensions on devices mounted in wood paneling. Article 314.20, NFC
- 6. Remove and/or rewire all illegal, improper or hazardous wiring to current NEC.
- 7. Install listed ceiling boxes on all lighting fixtures.
- 8. No access to the garages at the time of inspection. Insure garages are wired to NEC standards.
- 9. All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

PLUMBING Inspector: Paul Zellmer Phone: 651-266-9048

- 1. Basement -Laundry Tub (MPC .0100 B) Provide the proper potable water protection for the faucet spout.
- 2. Basement -Plumbing General -(MPC .0101 Subp. 6) Remove all unused waste, vent, water and gas piping to the main and cap or plug to code.
- 3. Basement -Soil and Waste Piping (MPC .0100 L & M & 708.1) Plug all open piping and properly pitch all piping.
- 4. Basement -Soil and Waste Piping -(MPC 704 & 706) Replace all improper connections, transitions, fittings or pipe usage.
- 5. Basement -Water Heater (MPC 507.5) Correct the pressure and temperature relief valve discharge.
- 6. Basement -Water Heater -(MPC .0100 Q)The water heater must be fired and in service.
- 7. Basement -Water Piping -(MPC 604) Replace all the improper fittings and fittings that have improper usage.
- 8. Basement -Water Piping -(SPRWS 93.07) Provide a one (1) inch water line to the first major take off.
- 9. Bathroom -Plumbing General -(MPC 402.2) Provide a water tight joint between the fixture and the wall or floor.
- 10. Bathroom -Plumbing General -(MPC .0100 R, 402.1, 402.5, & 408.6) Provide proper fixture spacing.
- 11. Exterior -Lawn Hydrants (MPC 301.1) Repair or replace the lawn hydrants that

Re: 593 Cook Ave E December 22, 2022 Page 4

are broken or have parts missing.

- 12. Exterior -Rain Leader (MPC .0100 L & M & 708.1) The rain leaders must be properly plugged or capped to code.
- 13. First Floor -Plumbing General -(MN Rules Chapter 1300.0120) Obtain permits and provide tests/inspections for any plumbing performed without permits.
- 14. First Floor -Sink -(MPC .0100 E & 901) Install a proper fixture vent to code.
- 15. First Floor -Sink -(MPC 701) Install the waste piping to code.
- 16. First Floor -Sink -(MPC .0100 P & Q & 419.2) Install the water piping to code.
- 17. First Floor -Toilet Facilities (MPC 402.6) Install a proper flanged fixture connection on a firm base.
- 18. First Floor -Tub and Shower -(MPC 408.3) Install scald and thermal shock protection, ASSE Standard 1016.
- 19. First Floor -Tub and Shower -(MPC 409.4) Install a hot water temperature limiting device, ASSE Standard 1070.
- 20. First Floor -Tub and Shower -(MPC 417.3) Install a vacuum breaker for the hand held shower.
- 21. Second Floor -Toilet Facilities (MPC 402.6) Install a proper flanged fixture connection on a firm base.
- 22. Second Floor -Tub and Shower -(MPC 408.3) Install scald and thermal shock protection, ASSE Standard 1016.
- 23. All the above corrections to waste, vent, water, and gas piping shall be per the Minnesota Plumbing Code Chapter 4714, Minnesota Rules Chapter 326, 4716, 1300, the Minnesota Mechanical Code, the Minnesota Fuel Gas Code, and Saint Paul Regional Water Services Water Code. All plumbing must be done by a plumbing contractor licensed in the State of Minnesota and the City of St. Paul by a plumber licensed in the State of Minnesota who also possess a City of Saint Paul Competency Card and after obtaining an approved City of Saint Paul Plumbing Permit.

Heating Inspector: Aaron Havlicek Phone: 651-266-9043

- Clean and Orsat test furnace/boiler burner. Check all controls for proper operation. Check furnace heat exchanger for leak; provide documentation from a licensed contractor that the heating unit is safe.
- 2. Provide a means of returning air from every habitable room to the furnace. Return air can not be taken from closets, bathrooms, toilet rooms, kitchen or mechanical rooms.
- 3. Vent clothes dryer to code.
- 4. Provide adequate combustion air and support duct to code.
- 5. Provide support for gas lines to code.
- 6. Plug, cap and/or remove all disconnected gas lines and unapproved valves.
- 7. Provide a window in the bathrooms with an aggregate glazing area of not less than 3 square feet, one-half of which must be openable or provide exhaust system vented to outside. A mechanical ventilation permit is required if an

Re: 593 Cook Ave E December 22, 2022

Page 5

exhaust system is installed.

- 8. All supply and return ducts for warm air heating system must be clean before final approval for occupancy. Provide access for inspection of inside of ducts or provide documentation from a licensed duct-cleaning contractor that the duct system has been cleaned.
- 9. Repair and/or replace heating registers as necessary.
- 10. Separate heating system is required for each dwelling unit. Furnace in basement can not be used for heating both 1st and 2nd floor units of duplex.
- 11. Mechanical permits are required for the above work.

Notes:

- 1. See attachment for permit requirements and appeals procedure.
- 2. Interior of garage not available for inspection. Repair per applicable codes.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected in accordance with the Minimum Housing Standards of the St. Paul Legislative Code (Chapter 34) and all required permits must receive final approval within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Clint Zane between 7:30 - 9:00 AM at 651-266-9029 or leave a voice mail message.

Sincerely,

Nathan Bruhn Code Compliance Officer Department of Safety and Inspections City of Saint Paul 375 Jackson Street, Suite 220 Saint Paul MN 55101

Phone: 651-266-9033

Email: nathan.bruhn@ci.stpaul.mn.us

Attachments