

4591 2-1/2 St NE Fridley, MN 55421 whiteeagleplumbing@gmail.com 612-275-8874

# White Eagle Plumbing

Estimate

For: LF Properties LLC

Estimate No:

3249

Date:

11/09/2023

\$3,500.00

Job Address

1971 Nortonia Ave St. Paul, Mn

Description Amount


We will be putting air on the entire plumbing system DWV and checking to make sure all piping is sized correctly and ran properly. Check out all water piping and make sure it's sized correctly. Check to make sure all fixtures are correctly installed. Pull all necessary permits and get all the plumbing inspected

 Subtotal
 \$3,500.00

 Total
 \$3,500.00

Total

\$3,500.00



and Kingle

North Side Electric northsideelectric@yahoo.com License ea686611 10831 Major Ave N Brooklyn Park Mn 55443 Cell 651 202 6556 Phone 612 521 8815



Lenny Frolov 1971 Norton is St Paul MN 3139771086

# INVOICE

Invoice #

0001227

**Invoice Date** 

11/14/2023

Due Date

11/14/2023

ltem	Description		Unit Price	Quantity	Amount
Service	Finish rewiring home done by others. Please note wiring was done by previous contractor.	all	5000.00	1.00	5,000.00
	2. Install outlets and lights and hook up all mechani	cals.			
		<u> </u>			
			Subtotal		5,000.00
			Total		5,000.00
			Amount Paid		0.00
			Balance Due	· · · · · · · · · · · · · · · · · · ·	\$5,000.00

# MESPO HEATING & COOLING, INC.

## Invoice

<b>Date:</b> 11/13/2023					
MESPO HEATING & COOLING, INC Bill to				Service address:	
1904 Glenwood Ave N	LF Holdings	s. LLC	1971 Nortonia Ave		
Minneapolis, MN 5540	Lenny Froid		St. Paul, MN 55119		
Contact: Busby Dasen	7040 Lakel		00.100,1111.00223		
Email: busbydasent@	Brooklyn Pa	<del>-</del>			
Phone: 763-360-4733		,	@lennyfrolov.com		
Fax: 612-353-6560		Ellian. Homes	@leilityii olov.com		
Service Type:					Total
		-			
Install all registers (supp	•				
Make connections for di	uct work				
Seal all duct work					
Seal exterior penetration					•
Lock caps installed on al					
Remove piping from old					
Inspection from the City	of St. Paul				
Dryer vent not included					
Note: No cosmetic work included No extra work included No warranty on all parts		N	upe		
Material					
Labor/service call		<u>-</u>	· · · · · ·		· <b>—·</b> —
Tax (7.5%)					
TOTAL					\$3,000.00
Down payment				<u> </u>	
Balance due					
AGREEMENT: I hereby authorize the work above have been completed. Unless explicitly agreed prior to commencement of work, payment will be due in full upon completion of the work or services provided. The full amount, less any payments already made, is payable. A lien against your property will be filed if full payment is not received wit in 30 days of invoice submission.			LIMITED WARRANTY: All materials, parts and equipment are warranted by the manufacturers' or suppliers' written warranty only. All labor performed by Mespo Heating and Cooling Inc is guaranteed for 30 days or as otherwise indicated in writing. Mespo Heating and Cooling Inc makes no other warranties, expressed or implied and its agents or technicians are not authorized to make any such warranties on behalf of Mespo Heating and Cooling Inc.		
Acceptable methods of payment are:  Cash Check DL# Credit cardMCVisaAMEX Exp date		REGULAR WARRANTY: 1 year on parts and labor. Heat exchange warranty by manufactory SERVICE CONTRACT		r. Heat	

## Air Express Inc.

PO Box 490400 BLAINE, MN 55449 (763)447-3999 Info@AirExpressHTG.com www.airexpressmn.com



**ADDRESS** 

Lenny Frolov 7040 Lakeland Ave N #112

Brooklyn Park, MN 55428

SHIP TO

Lenny Frolov 7040 Lakeland Ave N #112 Brooklyn Park, MN 55428 ESTIMATE

3136

DATE

11/03/2023

PROJECT ADDRESS 1971 Nortonia Ave, St Paul

CODE	DESCRIPTION		QΤΥ
23 22 00	Air Test for Gas Lines		1
Locks	A/C Safety Locks		1
23 22 00	Strap the Gas Line and Drain Tubing		1
23 22 00	Meet with the Inspector Twice		1
Note	If Needed, Cut the Sheetrock		1
WE HAVE MOVED!!! Our New Address		SUBTOTAL	3,000.00
PO BOX 490460 BLAINE MN 55449		TAX	0.00
		TOTAL	\$3,000.00

Accepted By

Accepted Date

#### REMODELING PROPOSAL

Date: 11/9/2023

Kaspars Kalnitis Contracting, LLC

License: BC639885

EPA Certification # NAT-121520-3

Address:

3455 Tyler Street NE Minneapolis, MN 55418

Phone: 612-868-4771

Project Type: Remodeling Submitted to: Lenny Frolov Phone: 612-242-9073

Project Address: 1971 Nortonia Ave

St Paul, MN

Approx. start date: TBD Approx. completion date: TBD

I hereby submit the following specifications and estimates:

## Work To Be Done (Materials Are Not Included)

### From the city of St Paul Code Compliance Report: `

- 1. Remove mold, mildewand moldy or water damaged materials. SPLC 34.10(1) Done
- 2. Weather seal exterior doors, thresholdand weather-stripping. SPLC 34.09 (3f)
- 3. Install floor covering in bathroom and kitchen that is impervious to water. S  $\mbox{\rm PLC}$

34.10(4)

- 4. Repair walls, ceiling and floorsthroughout, as necessary. SPLC 34.34 (6) 40h
- 5. Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present. SPLC 34.33 (1) Done
- 6. Any framingmembers that requiredrepair or do not meet code (wher ewall and ceiling covering is removed, members that are over-spanned, over-spaced, not being carried properly, door and window openings that are not adequately supported, etc.) are to be reconstructed in an approvedmanner. SPLC 3 4.34 (1)

- 7. Provide fire block construction as necessary and seal chases in basement ceiling. MNRC Ch 1309 Sect. 602.8
- 8. Where wall and ceiling covering is removed install full thickness or code-specified insulation. MN Energy Code Ch. 1322.1101 (exept. 4)
- 9. Air-seal and insulate attic/access door. MN Energy Code Ch 1322.1102.4
- 10. Install Smoke Detectors/Carbon Monoxide Detectors per MN Conservation Code and the MN Dept. of Labor and Industry: Install per code where feasible. MNRC Ch 1309 Sect 313.2.1 Done
- 11. Provide major clean-up of premises. SPLC 34.34 (4)
- 12. Install 20 minute fire rated doors, with self closing device, between common areas and individual units. All penetrations required to have property intumescent device or caulk (per current building codes). MNRC Ch 1309 Sect. 317 Done
- 13. Install water-proof enclosure in shower area. MNRC Ch 1309 Sect. 307
- 14. Provide weathersealed, air sealedand vermin sealedexterior. SPLC 34.32(2)
- \*\*\*Take note of the hole in the foundation near the front window. Check all other locations as well.
- 15. Replace or repair landingand stairway per code. SPLC 34.09 (2)
- 16. Repair siding, soffit, fascia, trim, etc. as necessary. SPLC 34.09 (1)
- 17. Provide proper drainage around house to direct water away from foundation of garage. SPLC 34.08 (2)
- 18. Install downspouts and a completegutter system. SPLC 34.33 (1d) Done
- 19. Install rain leaders to direct drainageaway from foundation. SPLC 34.33 (1d)
- 20. Replace house and garage roof covering and vents to code. SPLC 34.09 (1) Done
- 21. Install flashingin an approved manner at the intersection of the roof wit h walls, chimneys, and other conjoined surfaces. SPLC 34.09 (1)
- 22. Repair chimney in an approvedmanner. SPLC 34.09(1)

,e <sub>2e</sub>

- 23. Maintain one hour fire separation betweendwelling units and bet ween units and common areas. MNRC Ch 1309 Sect. 317 Done
- 24. Provide general rehabilitation of garage. SPLC 34.32 (3)
- 25. Remove trees which are against foundation of home and garage. SPLC 34.09 (1b) Done
- 26. Openings in stair risers must be less than 4 inches. MNRC Ch. 1309 Sect. 311/312
- 28. Remove and replace to code the front and rear deck/stair assemblies.
- 29. Replace garageoverhead door and service door.
- 30. Install handrails (34 inches -38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post orwall per attachment. MNRC Ch 1309 Sect. 311 & 312

- 31. Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary. SPLC 34.09 (3) Done
- 32. Provide complete storms and screens, in good repair for all door and window openings. SPLC 34.09 (3e)
- 33. Provide functional hardware at all doors and windows. SPLC 34.09 (3f)
- 34. Exit doors shall be capable of being opened from the inside, easily and without the use of a key. Remove all surface bolts. SPLC 34.09 (3h) Done
- 35. Repair or replace damageddoors and frames as necessary, including storm doors. SPLC 34.09 (3f)
- 36. A building permit is required to correct the above deficiencies. All work is to be done in a workmanship like manner. SPLC 33.03 (a)

Total project: \$32000

#### PRE-LIEN NOTICE

A) ANY PERSON OR COMPANY SUPPLYING LABOR OR MATERIALS FOR THIS IMPROVEMENT TO YOUR PROPERTY MAY FILE A LIEN AGAINST YOUR PROPERTY IF THAT PERSON OR COMPANY IS NOT PAID FOR THE CONTRIBUTIONS. (B) UNDER MINNESOTA LAW, YOU HAVE THE RIGHT TO PAY PERSONS WHO SUPPLIED LABOR OR MATERIALS FOR THIS IMPROVEMENT DIRECTLY AND DEDUCT THIS AMOUNT FROM OUR CONTRACT PRICE, OR WITHHOLD THE AMOUNTS DUE THEM FROM US UNTIL 120 DAYS AFTER COMPLETION OF THE IMPROVEMENT UNLESS WE GIVE YOU A LIEN WAIVER SIGNED BY PERSONS WHO SUPPLIED ANY LABOR OR MATERIAL FOR THE IMPROVEMENT AND WHO GAVE YOU TIMELY NOTICE.

#### CHANGE ORDERS

Any changes, deviation or unforeseen conditions from above specifications involving extra costs will be executed only upon written order, and will become an extra charge over and above the contract. All agreements contingents upon strikes, accidents, or delays beyond our control.

Acceptance of contract -

The above price, specifications and conditions are satisfactory and are hereby accepted. Kaspars Kalnitis is authorized to do the work as specified above, and payments will be made as detailed above.

Authorized person's signature	Date
Contractor's signature	Date 1/10/25