

□ Other

APPLICATION FOR APPEAL

RECEIVED

AUG 1 2 2011

CITY CLERK

RECEIVS aint Paul City Clerk

AUG 1310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 CITY CLERK Telephone: (651) 266-8560

The City Clerk needs the following to process y	our appeal:
\$25 filing fee payable to the City of Saint P (if cash: receipt number) Copy of the City-issued orders or letter wh are being appealed Attachments you may wish to include This appeal form completed Walk-In OR Mail-In	YOUR HEARING Date and Time:
Address Being Appealed:	
Number & Street: 1883 Hout A	Le E, City: St. Paul State: Mh Zip: 55/19 Email Joanelauson @ MSN. Com
Appellant/Applicant: Joan Lawson	Email Joanelauson @ msn. Com
Phone Numbers: Business	Residence 763, 444, 7065 Cell
Signature: Joan Huser	Date: 8/10/11
Name of Owner (if other than Appellant):	
Address (if not Appellant's):	
Phone Numbers: Business	Residence Cell
What Is Being Appealed a Vacate Order/Condemnation/ Revocation of Fire C of O Summary/Vehicle Abatement	nd Why? Attachments Are Acceptable
Fire C of O Deficiency List	
Fire C of O: Only Egress Windows	Jasking for a variance on the
Code Enforcement Correction Notice	is withou. The deferance is only
□ Vacant Building Registration	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

August 5, 2011

DARREN LAWSON JOAN E LAWSON 27056 FLAMINGO ST ISANTI MN 55040-5344

FIRE INSPECTION CORRECTION NOTICE

RE:

1883 HOYT AVE E

Ref. #109231

Residential Class: C

Dear Property Representative:

Your building was inspected on August 5, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A reinspection will be made on September 12, 2011 at 10:00 a.m..

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. Attic SPLC 34.10 (7), 34.33 (6) Repair and maintain the floor in an approved manner.-Repair or replace the floor tile. Repair ripped or torn tile.
- 2. BASEMENT MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.
- Basement Room West Side of House SPLC 34.23, MSFC 110.1 The Bedroom West Side of the Basement is condemned as unsafe or dangerous because there is no egress. This Bedroom must not be used for sleeping purposes until re-inspected and approved by this office.-Remove the bed from this room and bedding materials.

An Equal Opportunity Employer

Heavines ut me hour

Bedroom Room South East Side - MSFC1026.1 - Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.-Double Hung windows measured at 23 inches openable height . 27 inches openable width. Sill height was 27 inches . Glazed was 48 inches in height by 24 inches in width.

Hot water heater - MFGC 501.2 - Provide, repair or replace the fuel equipment vent or vent liner to develop a positive flow adequate to convey all products of combustion to the outside. This work will require a permit(s). Call DSI at (651) 266-9090.

Various Locations - MSFC 605.4 - Discontinue use of all multi-plug adapters.

Where missing - MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.

SPLC 34.11 (6), 34.34 (3) - Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.

SPLC 34.10 (4), 34.33 (3) - Provide a bathroom floor impervious to water. Caulk the base of the tub.

UMC 504.6 - Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work WILL require a permit(s). Call DSI at (651) 266-8989.

MSFC 315.2.3 - Remove combustible storage from the fuel burning equipment rooms. For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: james.thomas@ci.stpaul.mn.us or call me at 651-266-8983 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

James Thomas Fire Inspector

Reference Number 109231

Straw gov

50 6. 50 4.

J.N. 9.