

APPLICATION FOR APPEAL

Saint Paul City Clerk

RECEIVED
SEP 1 0 2010

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

CITY CLERK

The City Clerk needs the following to process your appeal:

\$25 filing fee payable to the City of Saint Paul

(if cash: receipt number_____)

Copy of the City-issued orders or letter which are being appealed

Attachments you may wish to include

This appeal form completed

YOUR HEARING Date and Time:		
Tuesday, Sept-21		
Time_ / 130		
Location of Hearing:		
Room 330 City Hall/Courthouse		

Address Being Appealed:

Number & Street: <u>857 Gra</u>	and Avecity:	5+ Paul State: MN Zip: 55/05
Appellant/Applicant: Welliam	Wengler 1	Email
Phone Numbers: Business 651-292-9	7/40Residence	Cell 6/2-799-1994
Signature: A Renglo		Date: 9-10-10
Name of Owner (if other than Appellant): _		
Address (if not Appellant's):		
Phone Numbers: Business	Residence	Cell
What Is Being appealed	l and why?	Attachments Are Acceptable
Vacate Order/Condemnation/ Revocation of Fire C of O		
□ Summary/Vehicle Abatement		
Fire C of O Deficiency List		
☐ Fire C of O: Only Egress Windows	·	
□ Code Enforcement Correction Notice		
□ Vacant Building Registration		
□ Other		
□ Other		
□ Other		



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

September 2, 2010

EAST MALL ASSOC/BILL WENGLER 857 GRAND AVE ST. PAUL MN 55105

FIRE INSPECTION CORRECTION NOTICE

RE:

857 GRAND AVE

Ref. #39818

Dear Property Representative:

Your building was inspected on August 31, 2010 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A reinspection will be made on October 12, 2010 at 9:30 AM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. ALLEY ADDRESS SPLC 71.01 Provide address numbers on building.-Provide at least four inch numbers.
- 2. BASEMENT NFPA 13 2-6.1.7 Remove all objects, equipment or storage hanging from the fire sprinkler piping and/or fire sprinkler heads.
- 3. BASEMENT MSFC 315.2.1 Provide and maintain a minimum of 18 inches clearance between the top of the storage and the sprinkler heads throughout the space.-Remove top shelf storage along the wall.
- 4. BASEMENT MSFC 901.6 Contact a fire sprinkler contractor to replace all painted or damaged fire sprinkler heads. All sprinkler work must be done by a licensed contractor under permit.-Replace painted sprinkler head in lunch room cave.

- 5. BILLYS MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.-Remove all extension cords. All power strips must plug directly into an outlet and not into one another or an extension cord. **LOCATIONS:** Miller clock, TVs, coffee area.
- 6. BILLYS MSFC 1010.3 Provide and maintain approved external or internal lighting of the exit sign.-Replace burnt out light bulbs and or batteries in exit signs.
- 7. BILLYS MSFC 605.4 Discontinue use of all multi-plug adapters.-Remove multi-plugs from outlets. LOCATIONS: TVs, back bar area, mezzanine storage.
- 8. BILLYS SPLC 34.10 (3), 34.33(2) Repair or replace the unsafe stairway in an approved manner.-Repair loose stair.
- 9. BILLYS KITCHEN MSFC 901.6 Contact a fire sprinkler contractor to replace all painted or damaged fire sprinkler heads. All sprinkler work must be done by a licensed contractor under permit.-Replace corroded and greasy sprinkler heads in the kitchen. Work requires a permit.
- 10. BILLYS MSFC 605.5 Remove electrical cords that extend through walls, ceiling, floors, under doors, or floors coverings, or are subjected to environmental or physical damage.-Remove electrical cords running through the ceiling on Boulevard sign.
- 11. BILLYS MSFC 901.6 Contact a fire sprinkler contractor to replace all painted or damaged fire sprinkler heads. All sprinkler work must be done by a licensed contractor under permit.-Replace painted cover plates.
- 12. BILLYS NFPA 13 6.2.7.2 Escutcheons and cover plates shall be part of a listed sprinkler assembly.-Replace missing cover plates and escutcheons.
- 13. BILLYS MSFC 904.11.6.3 Contact a qualified hood and duct cleaning service company to clean and service grease duct vent for commercial cooking equipment. Provide documentation as proof of compliance. Maintain venting system in a clean and sanitary condition.
- 14. BILLYS UMC 1346.703 Provide 30 inches clearance around all mechanical equipment.-Remove liquor from in front of water heater.
- 15. CAFE ROOM BILLYS MSFC 1010.3 Provide and maintain approved external or internal lighting of the exit sign.-Provide additional sign for the side hinged egress doors.
- 16. DESIGN PLATE NFPA 13 16.5.1 Provide a hydraulic design information sign for the sprinkler system.
- 17. ELECTRICAL ROOM MSFC 605.3.1 Doors into electrical control panel rooms shall be marked with a plainly visible and legible sign stating ELECTRICAL ROOM or similar wording.

- 18. EXIT DOORS MSFC 1003.3.1.8 Remove unapproved locks from the exit doors. The door must be open able from the inside without the use of keys or special knowledge or effort.-Remove double sided key deadbolt, change to a thumb lock. **LOCATIONS**: Tradewind's, Billy's.
- 19. FIRE ALARM TEST MSFC 907.20 as amended Provide required annual maintenance of the fire alarm system by a qualified person and provide written documentation to this office as proof of compliance.
- 20. GREEN ROOM BILLYS NFPA 13 (2002) 4.1 Provide sprinkler coverage in the missing room or area.-Contact a licensed electrician to provide coverage. Work requires a permit.
- 21. JUUT SALON COVER PLATES MSFC 901.6 Contact a fire sprinkler contractor to replace all painted or damaged fire sprinkler heads. All sprinkler work must be done by a licensed contractor under permit.-Replace painted cover plates.
- 22. JUUT SALON NFPA 13 (2002) 4.1 Provide sprinkler coverage in the missing room or area.-Contact a licensed sprinkler contractor to provide coverage outside of janitors closet. Work requires a permit.
- 23. JUUT SALON NFPA 13 (2002) 8.6.3.4.1 Relocate the sprinklers so that they are at least 6' apart.-Contact a licensed sprinkler contractor to relocate sprinkler heads on second floor in spa. Work requires a permit.
- 24. JUUT SALON NFPA 13 6.2.7.2 Escutcheons shall be part of a listed sprinkler assembly.-Replace missing escutcheons in the vestibule and in the mixing room.
- 25. JUUT SALON MSFC 901.6 Contact a fire sprinkler contractor to replace all painted or damaged fire sprinkler heads. All sprinkler work must be done by a licensed contractor under permit.-Replace corroded sprinkler head on the third level in waxing room.
- 26. MEZZANINE STORAGE BILLYS MSFC 315.2.1 Provide and maintain a minimum of 18 inches clearance between the top of the storage and the sprinkler heads throughout the space.
- 27. PAINTED SPRINKLER HEADS MALL HALL MSFC 901.6 Contact a fire sprinkler contractor to replace all painted or damaged fire sprinkler heads. All sprinkler work must be done by a licensed contractor under permit.-Replace painted sprinkler heads.
- 28. POOL TABLE STORAGE NFPA 13 (2002) 4.1 Provide sprinkler coverage in the missing room or area.-Contact a licensed sprinkler contractor to provide coverage. Work requires a permit.
- 29. SIDE HINGED DOORS BILLYS MSFC 1008.1.2 Egress doors shall be side hinged swinging.-Provide side hinged doors swinging in the way of egress for the green and cafe rooms.

- 30. SPRINKLER SYSTEM NFPA 13 7.1.1.1 A listed pressure gage shall be installed in the riser.-Contact a licensed sprinkler contractor to provide a pressure gage on the sprinkler riser.
- 31. SPRINKLER VALVES MSFC 903.4.4 Provide approved physical security of all fire sprinkler control valves.
- 32. SPRINKLER VALVES MSFC 508.5.4 Provide and maintain a minimum of 3 feet unobstructed access around all fire sprinkler valves.
- 33. STEEL NFPA 13 6.2.7.2 Escutcheons shall be part of a listed sprinkler assembly.- Replace missing escutcheon in janitor's closet.
- 34. TRADEWINDS MSFC 906.1, MN Stat. 299F.361 Provide approved fire extinguishers in accordance with the following types, sizes and locations.-Provide minimum 2A10BC fire extinguishers spaced not more than 75 feet travel distance from any point in the building to an extinguisher. They must be permanently mounted between 3 and 5 feet high in readily visible and easily accessible locations.

For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: **Kris.Skow-Fiske@ci.stpaul.mn.us** or call me at 651-266-8949 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Kris Skow-Fiske Fire Inspector

Reference Number 39818