



CITY OF SAINT PAUL  
Christopher B. Coleman, Mayor

375 Jackson Street., Suite 220  
Saint Paul, MN 55101-1806

Telephone: 651-266-8989  
Facsimile: 651-266-1919  
Web: [www.stpaul.gov/dsi](http://www.stpaul.gov/dsi)

361

July 31, 2013

06-075506

Robert Casselman  
670 Pelham Blvd #201  
St Paul MN 55114-1719

Meridian Residential Mortgage Inc  
6200 Excelsior Blvd #104  
St Louis Park, MN 55416

MERS  
PO Box 2026  
Flint, MI 48501-2026

## Order to Abate Nuisance Building(s)

Dear Sir or Madam:

**The Vacant/Nuisance Buildings Unit, Department of the Department of Safety and Inspections, Division of Code Enforcement, hereby declares the premises located at:**

**838-840 GOODRICH AVE**

With the following Historic Preservation information: NONE

**and legally described as follows, to wit:**

Summit Park Addition Tost Pa Lot 10 Blk 15

**to comprise a nuisance condition in violation of the Saint Paul Legislative Code, Chapter 45.02, and subject to demolition under authority of Chapter 45.11.**

On July 29, 2013 a Building Deficiency Inspection Report was compiled and the following conditions were observed.

**This list of deficiencies is not necessarily all the deficiencies present at this time. This building(s) is subject to the restrictions of Saint Paul Ordinance Chapter 33.03 and shall not again be used for occupancy until such time as a Certificate of Compliance or a Certificate of Occupancy has been issued. All repairs must be in accordance with appropriate codes. Changes or additions to the electrical system, mechanical system, or the plumbing system may necessitate updating or upgrading the systems involved.**

This is a two-story, wood frame, duplex with a two-stall detached wood frame garage.

### **BUILDING**

- Insure basement cellar floor is even, is cleanable, and all holes are filled.
- Tuck Point interior/exterior of foundation as necessary.
- Remove or encapsulate asbestos in an approved manner.
- Install 20 minute fire rated doors, with self closing device, between common areas and individual units. All penetrations required to have property intumescent device or caulk (per current building codes).
- Maintain one hour fire separation between dwelling units and between units and common areas.
- Install handrails (34 inches - 38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment.
- Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary.
- Provide complete storms and screens, in good repair for all door and window openings.
- Provide functional hardware at all doors and windows
- Exit doors shall be capable of being opened from the inside, easily and without the use of a key. Remove all surface bolts.
- Repair or replace damaged doors and frames as necessary, including storm doors.
- Weather seal exterior doors, threshold and weather-stripping.
- Install floor covering in bathroom and kitchen that is impervious to water.
- Repair walls, ceiling and floors throughout, as necessary.
- Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present.
- Where wall and ceiling covering is removed install full thickness or code-specified insulation.
- Air-seal and insulate attic/access door.
- Install Smoke Detectors/Carbon Monoxide Detectors per MN Co Conservation Code and the MN Dept. of Labor and Industry.
- Habitable rooms with new usage and replaced windows shall have glass area equal to 8% of floor area, one-half of which shall operate.
- Provide major clean-up of premises.
- Repair siding, soffit, fascia, trim, etc. as necessary.
- Provide proper drainage around house to direct water away from foundation of house.
- Provide proper drainage around house to direct water away from foundation of garage.
- Install rain leaders to direct drainage away from foundation.
- Provide general rehabilitation of garage.
- Install address numbers visible from street and on the alley side of garage.
- Review all applicable codes & policies when replacing windows including egress windows for sleeping rooms.
- Install one hour rated assembly under basement stairs at rear stairway in basement.
- Install tempered glass in front landing to second floor.
- Remove stump at front of garage.

- Call for framing inspection before covering walls and before insulation inspection.
- A building permit is required to correct the above deficiencies.

### **ELECTRICAL**

- Ground the electrical service to the water service with a copper conductor within 5 feet of the entrance point of the water service
- Bond around water meter with a copper wire sized for the electrical service per Article 250 of the NEC
- Provide a complete circuit directory at service panel indicating location and use of all circuits
- verify/install a separate 20 ampere laundry circuit and a separate 20 ampere kitchen appliance circuit
- Install hard-wired, battery backup smoke detector per bulletin 80-1 and other smoke detectors as required by the IRC. Also, Install carbon monoxide detector(s) within 10 feet of all bedrooms
- Check building write-up for fire resistance requirements if both panels are in the common area in a basement or move 2nd unit electrical panel board to the second unit
- All new wiring must be done to current code with electrical permit and appropriate inspections.
- All added receptacles must be grounded, tamper-resistant and be on an Arc-Fault Circuit Interrupter-protected circuit.
- Any open walls or walls that are opened as part of this project must be wired to the standards of the 2008 NEC.
- All buildings on the property must meet the St. Paul Property Maintenance Code (Bulletin 80-1).
- All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

### **PLUMBING**

- Basement - Gas Piping - BACK: dryer gas shutoff; connector or piping incorrect (IFGC 402.1)
- Basement - Gas Piping - BACK: run dryer vent to code (IFGC 613.1 - IMC 604.1)
- Basement - Laundry Tub - provide a vacuum breaker for the spout (MPC 2000 B)
- Basement - Laundry Tub - unvented (MPC 0200 E)
- Basement - Soil and Waste Piping - BACK: All waste and vent removed
- Basement - Soil and Waste Piping - BACK: no front sewer clean out (MPC 1000)
- Basement - Soil and Waste Piping - BACK: unplugged or open piping; back pitched piping (MPC 1000)
- Basement - Toilet Facilities - incorrectly vented (MPC 2500)
- Basement - Water Heater - BACK: No gas shut off or gas piping incorrect (IFGC 402.1)
- Basement - Water Heater - BACK: Vent must be in chimney liner (IFGC 501.12)
- Basement - Water Heater - BACK: not fired or in service (MPC 2180)
- Basement - Water Heater - Front: No gas shut off or gas piping incorrect (IFGC 402.1)
- Basement - Water Heater - Front: Vent must be in chimney liner (IFGC 501.12)
- Basement - Water Heater - Front: Water piping incorrect (MPC 1730 Subp. 1)

- Basement - Water Heater - Front: not fired or in service (MPC 2180)
- Basement - Water Meter - BACK: raise meter to a minimum 12 inches above floor (MPC 2280)
- Basement - Water Piping - BACK: boiler fill water line requires backflow assembly or device (MPC 2100)
- Basement - Water Piping - Front: boiler fill water line requires backflow assembly or device (MPC 2100)
- Exterior - Lawn Hydrants - Requires backflow assembly or device (MPC 2000)
- First Floor - Gas Piping - range gas shut off; connector or piping incorrect (IFGC 411 1.3.3)
- First Floor - Laundry Tub - Replace waste vent and fixture
- Second Floor - Gas Piping - range gas shut off; connector or piping incorrect (IFGC 411 1.3.3)
- Second Floor - Laundry Tub - Replace all waste vent and fixtures
- Obtain plumbing permits prior to commencement of work.

### **HEATING**

- Install approved lever handle manual building shutoff gas valve in an accessible location ahead of the first branch tee.
- Clean and Orsat test both boiler burners. Check all controls for proper operation. Provide documentation from a licensed contractor that the heating units are safe.
- Verify that the metal chimney liner is adequately sized for the connected load.
- Connect boilers and water heaters venting into chimney liner.
- Provide adequate clearance from flue vent pipe on boiler to combustible materials or provide approved shielding according to code.
- Vent clothes dryer to code.
- Provide adequate combustion air and support duct to code.
- Provide support for gas lines to code.
- Plug, cap and/or remove all disconnected gas lines.
- Provide a window in the bathrooms with an aggregate glazing area of not less than 3 square feet, one-half of which must be openable or provide exhaust system vented to outside. A mechanical ventilation permit is required if an exhaust system is installed.
- Provide heat in every habitable room and bathrooms.
- Attach metal tag to expansion tank valve stating that this valve must be OPEN at all times except when draining the expansion tank.
- Support supply and return piping for heating system according to code.
- Conduct witnessed pressure test on hot water heating system and check for leaks.
- Install boiler pressure relief valve and pipe discharge to within eighteen inches of the floor.
- Install back flow preventer on city water fill line to hot water heating system and pipe vent as required.
- Repair or replace radiator valves as needed.
- Submit documentation from a licensed contractor that the wood burning fireplaces are clean and safe for use or permanently seal openings.
- Run condensate drain from A/C unit coils in attic to an approved location and secure as needed.

- Seal openings to incinerator in basement.
- There was no access to the attic at the time of inspection. All the equipment must be brought up to code and access provided for inspection.
- Abate or encapsulate asbestos pipe insulation. Work must be performed by a licensed abatement contractor.
- Gas and hydronic mechanical permits are required for the above work.

As owner, agent or responsible party, you are hereby notified that if these deficiencies and the resulting nuisance condition is not corrected by **August 30, 2013** the Department of Safety and Inspections, Division of Code Enforcement, will begin a substantial abatement process to demolish and remove the building(s). The costs of this action, including administrative costs and demolition costs will be assessed against the property taxes as a special assessment in accordance with law.

As first remedial action, a Code Compliance Inspection Report must be obtained from the Building Inspection and Design Section, 375 Jackson Street, Suite 220, (651) 266-8989. This inspection will identify specific defects, necessary repairs and legal requirements to correct this nuisance condition. You may also be required to post a five thousand dollar (\$5,000.00) performance bond with the Department of Safety and Inspections before any permits are issued, except for a demolition permit. Call the Department of Safety and Inspections for more information at 651-266-8989.

If this building is located in a historic district or site (noted on page 1, above, just below the property address) then you must contact Heritage Preservation (HPC) staff to discuss your proposal for the repairs required by this order and compliance with preservation guidelines. Copies of the guidelines and design review application and forms are available from the Department of Safety and Inspections web site (see letterhead) and from the HPC staff. No permits will be issued without HPC review and approval. HPC staff also can be reached by calling 651-266-9078.

As an owner or responsible party, you are required by law to provide full and complete disclosure of this "Order to Abate" to all interested parties, all present or subsequent renters and any subsequent owners. The property shall not be sold, transferred or conveyed in any manner until the Nuisance Conditions have been abated and the Certificate of Code Compliance or Certificate of Occupancy has been issued.

The Enforcement Officer is required by law to post a placard on this property which declares it to be a "nuisance condition", subject to demolition and removal by the City. This placard shall not be removed without the written authority of the Department of Safety and Inspections, Division of Code Enforcement. The department is further required to file a copy of this "Order to Abate" with the City Clerk's Office.

If corrective action is not taken within the time specified in this order, the Enforcement Officer will notify the City Council that abatement action is necessary. The City Clerk will then schedule dates for Public Hearings before the City Council at which time testimony will be heard from interested parties. After this hearing the City Council will adopt a resolution stating what action if any, it deems appropriate.

If the resolution calls for abatement action the Council may either order the City to take the abatement action or fix a time within which this nuisance must be abated in accordance with the

July 31, 2013  
838 GOODRICH AVE  
page 6

provisions of Chapter 33 of the Saint Paul Legislative Code and provide that if corrective action is not taken within the specified time, the City shall abate this nuisance. The costs of this action, including administrative costs will be assessed against the property as a special assessment in accordance with law.

If you have any questions or request additional information please contact **Matt Dornfeld** between the hours of 8:00 and 9:30 a.m. at **651-266-1902**, or you may leave a voice mail message.

Sincerely,

Matt Dornfeld  
Vacant Buildings Enforcement Inspector

cc: Legistar Approval list and City Council

ota60135 5/11