18.62

We need the following to process your appeal:

(if cash: receipt number 8200 89

\$25 filing fee (non-refundable) (payable to the City of Saint Paul)

Copy of the City-issued orders/letter being appealed



APPLICATION FOR APPEAL

Saint Paul City Council - Legislative Hearings RECEIVED

HEARING DATE & TIME

(provided by Legislative Hearing Office) Tuesday, MAY 1, 2018

APR 24 2018

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

Revised 8/11/2014

CITY CLERK

This appeal form completed	Time
Walk-In OR □ Mail-In	Location of Hearing:
	Room 330 City Hall/Courthouse
for abatement orders only: Email OR Fax	
Address Being Appealed:	
Number & Street: 383 York Ave City: St. Paul State: MW Zip: 55130	
Appellant/Applicant: Samrawit me konnen Email Sme Konnen 53@ gmail Com	
Phone Numbers: Business Residence	Cell 651-528-4525
Signature:	Date: 4/24/18
Name of Owner (if other than Appellant):	
Mailing Address if Not Appellant's:	
Phone Numbers: Business Residence	Cell
What Is Being Appealed and Why? Attachments Are Acceptable Vacate Order/Condemnation/ Revocation of Fire C of O Summary/Vehicle Abatement Fire C of O Deficiency List/Correction Code Enforcement Correction Notice Vacant Building Registration	
Other (Fence Variance, Code Compliance, etc.)	



CITY OF SAINT PAUL

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

April 11, 2018

RENTERS WAREHOUSE 13200 PIONEER TRAIL #100 EDEN PRAIRIE MN 55347-4121

FIRE INSPECTION CORRECTION NOTICE

RE:

383 YORK AVE

Ref. #125041

Residential Class: C

Dear Property Representative:

Your building was inspected on April 11, 2018 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on May 15, 2018 at 2:30pm.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. Exterior SPLC 34.08 (1), 34.32 (1) All exterior property areas shall be maintained free from any accumulation of refuse, garbage or feces.
- 2. Exterior SPLC 34.08 (10) Repair, replace and maintain exterior sidewalks, walkways and stairs.-Repair broken area of front steps.
- 3. Interior Basement MSFC 605.1 -Provide a grounding jumper around the water meter.
- 4. Interior Basement MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.

- 5. Interior Basement SPLC 34.10 (6), 34.34 (5) Exterminate and control insects, rodents or other pests. Provide documentation of extermination.-Mice and cat feces in basement.
- 6. Interior Basement MMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter and installed in accordance with the mechanical code. This work will require a permit(s). Call DSI at (651) 266-8989.-Have a licensed contractor pull a permit and provide a code complaint dryer vent. Current material is not code compliant.
- 7. Interior Basement Steps SPLC 34.10 (3) 34.34(2) Provide an approved guardrail. Intermediate balustrade must not be more than 6 inches apart. Intermediate rails must be provided if the height of the platform is more than 30 inches.-
- 8. Interior MSFC 807.2 Provide documentation that decorative materials have been treated and maintained with an approved flame retardant or remove decorative materials that do not meet the flame retardant requirements.-Remove flags and blankets from walls.
- 9. Interior MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.-

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: daniel.klein@ci.stpaul.mn.us or call me at 651-266-8988 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely.

Daniel Klein Fire Inspector

Reference Number 125041



April 24, 2018

Samrawit Mekonnen 232 Cottage Avenue W Saint Paul, MN 55117

Dear Samrawit:

This letter confirms the details of your current employment with York Solutions:

Dates of Employment: 4/9/2018 - current

Current Position: Barriers to Entry Training Program Participant

Current hourly rate: \$15/hour

2018 YTD Gross Earnings: \$450,00

If you have any questions regarding the terms of employment, please do not hesitate to contact me at jskinner@yorksolutions.net. Thank you for your cooperation and assistance with this matter.

Sincerely

Jen Skinner

Sr. Director, Human Resources

York Solutions