

# APPLICATION FOR APPEAL

4 RECEIVED SEP 0 9 2010 CITY CLERK

## Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

The City Clerk needs the following to process your appeal:	YOUR HEARING Date and Time:
\$25 filing fee payable to the City of Saint Paul	
(if cash: receipt number)	Tuesday, Sept. 21
Copy of the City-issued orders or letter which	
are being appealed	Time_ 1.30
□ Attachments you may wish to include	<u>Location of Hearing:</u> Room 330 City Hall/Courthouse
This appeal form completed	
	mailed on 9-9-10 JF
Address Being Appealed:	

C = C = C = C = C = C = C = C = C = C =
Number & Street: 147 Cook Ave & City: St. Paw   State: MN Zip: 55   +
Appellant/Applicant: for Phyllis Evans Email rh(00per2010 C
Appellant/Applicant: for Phyllis Wans Email MCOOperCOID
651-602-5683 V
Appellant/Applicant: tor Physis DVW) Email VV)(100pl/C010 GANOO) COM Phone Numbers: Business (Repecca 100) Residence A Cell (051-278-5179)
Signature:
Name of Owner (if other than Appellant): Phyllis Evans
Address (if not Appellant's): 1397 Scheffer
Phone Numbers: Business 1/A Residence (051-1098- Cell 19/1A
0495

V	<b>Vhat Is Being appeale</b>	ed and why? Attachments Are Acceptable
	Vacate Order/Condemnation/	
	Revocation of Fire C of O	The property @ 147 Cook
	Summary/Vehicle Abatement	Are E which was inspected
	Fire C of O Deficiency List	on Sept. I was found to have
X	Fire C of O: Only Egress Windows	windows that did not meet
	Code Enforcement Correction Notice	egress standards. The owner
	Vacant Building Registration	of the home is Phyllis Evans.
	Other	In 1997 Raymond and
	Other	Phyllis Evans (my parents).
	Other	bought the home Je 147 Cook
		Revised 8/20/2010

for me (Rebecca (ooper) to rent. In 1998, Wellington Windows completed an entire double hung windows. My mother was under the impression a permit was obtained to complete the job through the company. permit cost included. We ca s has become comp Hhough I was assi Hained (Wellington g can be 4 is vacant the dome for 14 years nd have downsizeda partment. The proper never be gented again the correct owner Rly mother is 84 years old and has failing eath. Once the fire marshall inspection is complete nt housing repor completed and the home will be sold-(or placed on the market). We are asking for a variance for the reasons that the home is not non will be a rental property and hardship (over)



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

September 1, 2010

PHYLLIS H EVANS 1397 Scheffer Ave St Paul MN 55116-2245

#### FIRE INSPECTION CORRECTION NOTICE

RE:

147 COOK AVE E

Ref. #109578

Residential Class: C

### Dear Property Representative:

Your building was inspected on September 1, 2010 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

### A re-inspection will be made on October 14, 2010 at 1:00 PM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

#### **DEFICIENCY LIST**

- 1. Basement Northside SPLC 34.09 (3), 34.32 (3) Repair and maintain the window in good condition.
- 2. Basement UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work may require a permit(s). Call DSI at (651) 266-8989.

- 3. Basement steps MSFC 901.6 Provide required annual maintenance of the fire extinguishers by a qualified person and tag the fire extinguishers with the date of service.
- 4. Bedroom Northeast SPLC 34.12 (2), 34.35 (1) Repair and maintain all required and supplied equipment in an operative and safe condition.-Repair closet door
- 5. Hallway Closet door SPLC 34.09 (3), 34.32 (3) Repair and maintain the door in good condition.
- 6. Kitchen SPLC 34.10 (7), 34.33 (6) Repair and maintain the cabinets in an approved manner.-Repair or replace the damaged or missing door. And counter top.
- 7. Northeast Bedroom MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Height 17 in, Width 37 in. Window does not stay open.
- 8. Northeast Bedroom and Basement MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.
- 9. Northwest Bedroom MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.- Height 17 in, Width 28 in.
- 10. South Bedroom MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Height 17 in, width 28 in.
- 11. Southside SPLC 34.09 (3), 34.32 (3) Repair and maintain the window frame.-Scrape and paint.
- 12. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.

For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse,

15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: mike.cassidy@ci.stpaul.mn.us or call me at 651-266-8984 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Mike Cassidy Fire Inspector

Reference Number 109578