

APPLICATION FOR APPEAL

Saint Paul City Council – Legislative Hearings

RECEIVED

MAY 15 2020

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

1854	MAT 15 ZU	20	Telephone: (651) 266-8585	
	CITY CLE	RK		
\$25 filing fee (non-refundable) (payable (if cash: receipt number	to the City of Saint Paul)) r being appealed de I OR □ Fax	Time Location of Hear Room 330 City I	gislative Hearing Office) AY 26,2020 BO a.M. Tring: Hall/Courthouse AS 11:30 a.M. Call Call	
Number & Street: 870 Cook		Paul Stat	re: <u>MN</u> Zip: <u>S\$ (06</u>	
Appellant/Applicant: Nate Steve	ns Ema	ail <u>nate</u> , St	evens@ Wits ingund	· C
Phone Numbers: Business 612-219	1-4120 Residence 1/1	4 Cell	612-219-4120	
Signature: Mah Sterr	· Cra	Date:	5/15/2020	
Name of Owner (if other than Appellant):	Konrad Lyghtner	VIa 870 0	Cark Ave Trust	
Mailing Address if Not Appellant's: 13	V			
Phone Numbers: Business	Residence//	A Cell	763-202-3351	
What Is Being Appeals Vacate Order/Condemnation/ Revocation of Fire C of O Summary/Vehicle Abatement Fire C of O Deficiency List/Correction Code Enforcement Correction Notice Vacant Building Registration Other (Fence Variance, Code Compliance, etc.)	DIFFICULTES for.	dry vendar	s/contractors willing instry pandemic. where the stems for and of the stems for ish	
-	WE WILL HAVE	The rest o	Revised 8/11/2014	Z

Ricardo X. Cervantes, Director

SAINT PAUL

CITY OF SAINT PAUL

375 Jackson Street. Suite 220 St Paul, Minnesota 55101-1806

Telephone: 651-266-8989 Facsimile: 651-266-9124 Web: www.stpaul.gov/dsi

May 5, 2020

WITS PROPERTY MANAGEMENT 1330 LAGOON AVE SUITE 400 MINNEAPOLIS MN 55408USA

Revocation of Fire Certificate of Occupancy and Order to Vacate

RE:

870 COOK AVE E

Ref. # 16923

Dear Property Representative:

Your building was inspected on May 5, 2020, for the renewal of the Certificate of Occupancy. Since you have failed to comply with the applicable requirements, it has become necessary to revoke the Certificate of Occupancy in accordance with Section 40.06 of the Saint Paul Legislative Code. A reinspection will be made on May 22, 2020 at 12Noon or the property vacated.

The Saint Paul Legislative Code further provides that no building shall be occupied without a Certificate of Occupancy. Failure to immediately complete the following deficiency list or the building vacated may result in a criminal citation.

DEFICIENCY LIST

- 1. Exterior - House - SPLC 34.09 (1)(2), 34.33 (1) - Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.-There is a section of the soffit and fascia that is open and damaged.
- 2. Exterior - Key Box - MSFC 506.2 - Install a fire department key box near the main entry at 7 feet high-
- 3. Exterior - Stairs & Walkway - SPLC 34.08 (10) - Repair, replace and maintain exterior sidewalks, walkways and stairs. The stairs to the basement are chipped, cracked and damaged. There is also a section of the retaining wall that has a piece of the block broken off. The pavers on the side of the house are in disrepair and has sunken into the ground.
- 4. Exterior - Windows - SPLC 34.09 (4), 34.33 (3) - Repair and maintain the window in good condition.-There is a window on the East side of the house that has a broken window. There are windows that have chipping and peeling paint on the sides

An Equal Opportunity Employer

- 5. Interior Basement MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.-There are junction boxes in the basement that is missing the covers.
- 6. Interior Basement SPLC 34.10 (7), 34.17 (5) Repair and maintain the ceiling in an approved manner.-One hour. There is an opening in the ceiling above the electrical panels. Properly seal the openings with approved fire rated material.
- 7. Interior Basement MMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter and installed in accordance with the mechanical code. This work may require a permit(s). Call DSI at (651) 266-8989.-The dryer exhaust duct is no longer maintained and is no longer properly connected and a section of the duct is damaged. The duct is not properly supported. Contact a licensed contractor to properly repair the duct.
- 8. Unit 4 SPLC 34.23, MSFC 110.1 This occupancy is condemned as unsafe or dangerous. This occupancy must not be used until re-inspected and approved by this office.-
- 9. Unit 1 Kitchen SPLC 34.10 (7) Repair and maintain the cabinets in an approved manner.-The base of the kitchen cabinet is water damaged and has mildew or mold developing on the surface.
- 10. Unit 2 Ceilings SPLC 34.10 (7), 34.17 (5) Repair and maintain the ceiling in an approved manner.-There are some cracks and damages on the bathroom and kitchen ceiling. Properly finish the repair to the kitchen ceiling.
- 11. Unit 2 Front Bedroom MSFC 1030.3 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exit path..-The television is partially blocking the bedroom window.
- 12. Unit 2 Walls SPLC 34.10 (7), 34.17 (5) Repair and maintain the walls in an approved manner.-The panel or piece of wall underneath the kitchen sink has come off and there is now an opening underneath.

 Properly finish the repair to the wall behind the back bedroom wall.
- 13. Unit 2 Window SPLC 34.09 (4), 34.33 (3) Repair and maintain the window in good condition.-The window in the back bedroom does not stay up and slides down.
- 14. Unit 3 CO Alarm MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.-The carbon monoxide alarm is missing.
- 15. Unit 3 Kitchen SPLC 34.14 (2) c Repair or replace the duplex convenience outlet with ground fault protection within 3 feet of the basin on an adjacent wall in all bathrooms. This work may require a permit(s). Call DSI at (651) 266-8989.-The kitchen

GFCI outlet on the far-left does not work properly and makes a buzzing sound when tested.

- 16. Unit 3 Window SPLC 34.09 (4), 34.33 (3) Repair and maintain the window in good condition.-The glass for the bathroom window is broken.
- 17. Unit 4 Bathroom SPLC 34.10 (7), 34.17 (5) Repair and maintain the walls in an approved manner.-The wall around the bathroom light switch is damaged and is sunken in.
- 18. Unit 4 Both Bedrooms SPLC 34.23, MSFC 110.1 This occupancy is condemned as unsafe or dangerous. This occupancy must not be used until re-inspected and approved by this office. The back bedroom has been condemned because the bedroom egress window does not stay and comes out of the frame when raised creating a safety hazard to the person opening the window. The front bedroom has been condemned because the headboard is completely blocking the bedroom egress window. Discontinue sleeping in the bedrooms until the life-safety hazards have been resolved.
- 19. Unit 4 Entry Door MSFC 703.1 Provide, repair or replace the fire rated door and assembly. The minimum rating must be:-20 minutes. The entry door is in disrepair with cracked and damaged frame and trim, the door does not self-close and the door does not fit properly within its frame leaving gaps and openings around the door. The door must be replace.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: james.thomas@ci.stpaul.mn.us or call me at 651-266-8983 between 7:30 - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

James Thomas Fire Safety Inspector

Ref. # 16923