

## **APPLICATION FOR APPEAL**

## Saint Paul City Council - Legislative Hearings

RECEIVED

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

JUL 01 2014

CITY CLERK

W	e need the following to process your a	ippeal:		
X O X	Copy of the City-issued orders/lette Attachments you may wish to inclu	3553) er being appealed	(provided Tuesday, Time	IG DATE & TIME If by Legislative Hearing Office)  July 8, 2014
ġ <b>⋌</b>	Walk-In OR □ Mail-In			of Hearing: 0 City Hall/Courthouse
	for abatement orders only:   □ Emai	il OR 🗆 Fax	Koom 55	o City Hutti Courthouse
Address Being Appealed:				
Number & Street: 586 Edmund Ave City: St. Paul State: MN Zip: 55104				
Appellant/Applicant: Twin Oak Management, L.L.C. Email twin oak @ twin oak mgt. com				
Phone Numbers: Business 651-776-6630 Residence NA Cell turned off  Juni Oak Management, h.h.C.  Signature: by Patricia Whiting Date: 6130/14				
Name of Owner (if other than Appellant): MFO Properties, LLC  2197 Silver Lake Road NW				
Mailing Address if Not Appellant's: Yo Twin Oak Management @ New Brighton, MN 55/12  Jacqueline Ricks				
Ph	one Numbers: Business	Residence		
What Is Being Appealed and Why? Attachments Are Acceptable				
×	Vacate Order/Condemnation/ Revocation of Fire C of O	Tenants caused and life - threa	damag	e to property safety issues
	Summary/Vehicle Abatement	by over-crowd		
	Fire C of O Deficiency List	to maintain	Xcel 1	Energy service
	Vacant Building Registration	77-1 (7 7%)	Regues	
	Other	1 , 1 1	ancy o	a i de de des
		utilities and r	repair	damage Revised 5/31/2013
		1 . 1 . 1 . 1 . 1 . 1 . 1 . 1 . 1 . 1 .	1 1 1 1 1 1 1	CHESCOSE MAN OF

fees.



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

June 23, 2014

TWIN OAK MANAGEMENT LLC 2197 SILVER LAKE ROAD SUITE 207 NEW BRIGHTON MN 55112-5331USA

## NOTICE OF CONDEMNATION UNFIT FOR HUMAN HABITATION ORDER TO VACATE

RE:

586 EDMUND AVE

Ref. # 107617

Dear Property Representative:

Your building was inspected on June 23, 2014.

The building was found to be unsafe, unfit for human habitation, a public nuisance, a hazard to the public welfare or otherwise dangerous to human life. A Condemnation Placard has been posted on the building.

The following deficiency list must be completed or the building vacated by the re-inspection date.

CONDEMNATION OF THE BUILDING REVOKES THE CERTIFICATE OF OCCUPANCY.

Failure to complete the corrections may result in a criminal citation. The Saint Paul Legislative Code requires that no building be occupied without a Fire Certificate of Occupancy.

## **DEFICIENCY LIST**

- 1. Exterior SPLC 45.03 (6) Cut and maintain the grass/weeds less than 8 inches tall.-
- 2. Exterior SPLC 34.08 (1), 34.31 (1) All exterior property areas shall be maintained free from any accumulation of refuse, garbage or feces.

Porceals

- 3. Exterior SPLC 163.03, 163.01 (2), (3) Currently license (tabs) all vehicles on the property and return the vehicles to an operative mechanical condition or remove vehicles from the property.-Green Camry lic SNK 042 exp.5/14
- 4. Front common hallway SPLC 34.10 (7), 34.34 (6) Repair and maintain the walls in an approved manner.
- 5. Front porch SPLC 34.09 (3), 34.32 (3) Repair and maintain the door frame.-
- 6. Front porch SPLC 34.09 (3), 34.32 (3) Repair and maintain the window glass.-
- 7. Front sleeping room MSFC 1026.1 Provide and maintain an approved escape window from each sleeping room or area, or discontinue use of area as a sleeping room. This work may require permit(s). Call DSI at (651) 266-8989.-Window exits into an enclosed porch. Side window sill is higher than 5 feet.
- 8. Lower unit Basement Ext. Door SPLC 34.09 (3), 34.33 (3) Repair and maintain the door in good condition.
- 9. Lower unit Basement MSFC 1003.3.1.8 Remove unapproved locks from the unit doors. The door must be openable from the inside without the use of keys or special knowledge or effort.-Deadbolt lock will lock people into the basement.
- 10. Lower unit SPLC 34.23, MSFC 110.1 This occupancy is condemned as unfit for human habitation. This occupancy must not be used until re-inspected and approved by this office.-Unit has no electricity.
- 11. Lower unit SPLC 34.13 (2), (3), SPLC 34.17 (2) Reduce and maintain the number of occupants in the unit to: 1
- 12. Lower unit MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.-Inoperative due to electricity being out. No battery backup.
- 13. Lower unit MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- 14. Multiple locations SPLC 34.09 (3), 34.33 (3) -Provide or repair and maintain the window screen.
- 15. Upper unit Holes in walls SPLC 34.10 (7), 34.34 (6) Repair and maintain the walls in an approved manner.
- 16. Upper unit Living room MSFC 605.4 Discontinue use of all multi-plug adapters.-
- 17. Upper unit Throughout MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.-Smoke detectors beeping.

- 18. Upper unit living room MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.
- 19. Upper unit multiple locations Ext. Door SPLC 34.09 (3), 34.33 (3) Repair and maintain the door in good condition.
- 20. Upper unit multiple locations MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.
- 21. Upper unit SPLC 34.23, MSFC 110.1 This occupancy is condemned as unfit for human habitation. This occupancy must not be used until re-inspected and approved by this office.-Condemnation is resulting from, but not limited to: overcrowding, smoke detectors, and sanitation.
- 22. Upper unit SPLC 34.10 (5), 34.33 (4), 34.16 Provide and maintain interior in a clean and sanitary condition.
- 23. Upper unit SPLC 34.11, MSBC 2902.1, SPLC 34.17, MSPC 415.0220 Repair or replace and maintain all parts of the plumbing system to an operational condition.-Toilet does not flush.
- 24. Upper unit SPLC 34.13 (2), (3), SPLC 34.17 (2) Reduce and maintain the number of occupants in the unit to: 4-8 adults and 5 plus children at time of inspection.
- 25. Upper unit SPLC 34.13 (3), SPLC 34.17 (2) Reduce and maintain the number of occupants in the sleeping rooms to: 0-Remove the bed from the closet. Immediately discontinue using the closet for a sleeping room.
- 26. Upper unit MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.-
- 27. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 28. SPLC 34.11 (4), 34.34 (1), MPC 4715.022.E Repair and maintain sewer vent.-There is a strong smell of sewer gas on the 3rd floor.
- 29. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of the original orders.

If you have any questions, email me at: leanna.shaff@ci.stpaul.mn.us or call me at 651-266-8980 between 7:30 - 9:00 a.m. Please help make Saint Paul a safer place in which to live and work.

Sincerely,

Leanna Shaff Fire Inspector Ref. # 107617