

Saint Paul Fire Department FIRE INCIDENT DISPOSITION



INCIDENT NUMBER:	15-41910	DATE OF INCIDENT: 12/28/2015	
TIME OF INCIDENT:	2335 hrs.	POLICE CASE #: Unassigned	
INVESTIGATOR(s):	Brian Kroeger		
INCIDENT ADDRESS:	670 Western Ave. N.		
OCCUPANT NAME:	See below	PHONE:	
OWNER NAME:	Roseann Ryan	PHONE: Not listed	
ADDRESS OF OWNER:	Same		
PROPERTY DAMAGED:	SFD	AREA OF ORIGIN: Living room	
DAMAGE ESTIMATE:	Building \$80,000	Vehicle \$	Other (Describe) \$
VALUE:	Building \$105,000	Vehicle \$	Other (Describe) \$
Damage Estimate CONTENTS ONLY:	\$30,000		
INJURY/DEATH (if yes, explain)	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes		
SMOKE DETECTOR, SPRINKLER, and CARBON MONOXIDE INFORMATION:	Smoke Detector Present: <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Unknown Detector Functioning: <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Unknown Sprinkler System Present: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown Sprinkler Heads activated: <input type="checkbox"/> Yes # <input type="checkbox"/> No <input type="checkbox"/> Unknown C.O Detector Present: <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Unknown		
FIRE CAUSE CLASSIFICATION:	<input type="checkbox"/> Accidental <input type="checkbox"/> Juvenile/Incendiary <input type="checkbox"/> Incendiary <input type="checkbox"/> Child (under 10 years old) <input type="checkbox"/> Natural <input type="checkbox"/> Undetermined <input checked="" type="checkbox"/> Under Investigation		
SYNOPSIS:	Fire department was called to a report of a dwelling fire. On arrival, crews found and extinguished a fire that began in the first floor living room and caused damage throughout the structure. No one was home at the time of the fire, although the structure appeared to be lived in. Crews report forcing entry. There were multiple electrical outlets in the area of origin, and no evidence of candle use or cigarette use was discovered. It appears likely that an electrical defect ignited flammable items in the living room (e.g. Christmas tree). The ignition source is unknown, but appears likely to be electrical. The first materials ignited were ordinary household items. Unknown factors brought these together. The classification of fire cause is under investigation, pending interviewing the resident for more information.		
DISPOSITION:	<input type="checkbox"/> E-mail only <input type="checkbox"/> Hold Scene until approved <input type="checkbox"/> DO NOT DEMOLISH until approved <input checked="" type="checkbox"/> Scene Released <input type="checkbox"/> Analysis of Evidence Pending <input checked="" type="checkbox"/> Report to Follow		