

APPLICATION FOR APPEAL

Saint Paul City Council - Legislative Hearings

Location of Hearing:

Room 330 City Hall/Courthouse

RECEIVED JUL 17 2014 CITY CLERK 310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

Fax: (651) 266-8574

Email: legislativehearings@ci.stpaul.mn.us

	\$25 filing fee payable to the City of Saint Paul	HEARING DATE & TIME	
P	(if cash: receipt number Check 4259)	(provided by Legislative Hearing Office) Tuesday, 「ムリノス2, 2014	
Ø	Copy of the City-issued orders/letter being appealed	Tuesday, July 22, 2014	

Attachments you may wish to include P

This appeal form completed Ø

فهر

Walk-In OR - Mail-In

for abatement orders only:

| Email OR □ Fax

Address Being Appealed:

We need the following to process your appeal:

Number & Street: 108 Charles	Avenue City:	St. Paul State: MN Zip: 55103
Appellant/Applicant: JOE SENE		nail genereux. joe @ dorsey. com
Phone Numbers: Business 612-340-380	88 Residence <u>651-</u>	429-0003 Cell 612-598-9029
Signature:	Perop	Date: July 17, 2014
Name of Owner (if other than Appellant): _		
Mailing Address if Not Appellant's:		
Phone Numbers: Business	Residence	Cell
What Is Being Appeale	ed and Why?	Attachments Are Acceptable
Vacate Order/Condemnation/ □ Revocation of Fire C of O		
□ Summary/Vehicle Abatement		
Fire C of O Deficiency List		
Code Enforcement Correction Notice	Item 5 on a	Hacked No fire dated July 7, 2014
□ Vacant Building Registration	See	a Hacked exploration
□ Other (Fence Variance, Code Compliance, etc.)		

To whom it may concern :

I am appealing from the requirement for a fournaise in spection at this time (item 5 on the correction Notice).

The two furnaces of this property were inspected in 2012. The was no fundamental problem with the fornaces, the For the Second Bloor furnace, however, it was determined that there was no combastion air intake. We installed such an I showed that intake to the inspector on July 7, 2014.

I've a Hacked fee inspection for me for the first floor furnace, but I count find the one for the second floor furnace . I assume you have a copy in the Department of Sobety and Inspections Records. However, I've also attached the in voice from the burnace contractor showing the air intothe was installed. The invoice for the february, 2017 inspection is Note that the charge for the two furnace in spections was \$ 434. Given that the problem was not with the farnaces themselves but only with the air in take we hich is not part of the furnaces, I respectfully request that I not be required to pay for additional furnace in spection with this round of inspections et this property. All other requirements on the Conection Notice have been or will be complied with

Alouse contact me if you have questions - 612-599-9029 (c)



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

July 7, 2014

JOE GENEREUX 9777 JOLIET AVENUE NORTH STILLWATER MN 55082-8409

FIRE INSPECTION CORRECTION NOTICE

RE:

208 CHARLES AVE

Ref. #107781

Residential Class: B

Dear Property Representative:

Your building was inspected on July 7, 2014 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on August 8, 2014 at 9:30 AM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. Exterior Garage SPLC 34.09 (1) e, 34.32 (1) d Provide and maintained the roof weather tight and free from defects. Repair garage roof in an approved manner.
- 2. Interior Multiple Locations SPLC 34.11, MSBC 2902.1, SPLC 34.17, MSPC 415.0220 Repair or replace and maintain all parts of the plumbing system to an operational condition. Resecure toilet to bathroom floor.

- 3. Interior Unit 2 MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.-
- 4. Unit 1 Throughout MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.-Replace extension cords with approved surge protected devices.
- 5. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 6. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: jeremy.hall@ci.stpaul.mn.us or call me at 651-266-8987 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Jeremy Hall Fire Inspector

Reference Number 107781



EXISTING FUEL BURNING EQUIPMENT SAFETY TEST REPORT

(Use separate form for each Appliance)

Department of Safety & Inspections Fire Prevention Division

375 Jackson Street - Suite 220 Saint Paul MN 55101

Fax: 651-266-8951

Address: 208 Charles	15+ Floor Date: 2-10-2012
Owner: JoE General	-
Type of Heat:	
Gravity Air Forced Air Gravity Ho	t Water Forced Hot Water
Steam Unit Heater Space Heat	erOther
Type of Fuel: Gas X Oil Oth	er
A	nversion
Make of Burner AMANA Ma	ce
Model <i>GUIO70B30A</i> Mo	the state of the s
Serial 8907104835 Mar	x. BTU Rating 70,000
Input 70,000 BEU Mai	ke of Furnace Amano
Equipment venting type: Atmospheric Induced Fan	Other
Total BTU input of all vented gas appliances p	
Type of Chimney: Masonry X Class B	Other
Type of Liner: None Metal	Clay Tile
Combustible Air Supply Required?: Yes_X	
·	Analysis/Flue Gas Analysis: Yes No
	nts Properly without Spillage me Stays Inside/Doesn't Roll Out mer Lights Smoothly
	ner Lights Smoothly ×
Low Water Cut-Off Operating Properly	
All Controls Operating Properly	u .
- Company of the Comp	Visual Inspection Yes No
	Fuel Piping System – Okay
Oxygen 9,9 % 9,9 %	Vent Systems—Drafthood, Connector, Vent Chimney Okay 'X
Carbon Dioxide 6.18 % 6.18 %	
Carbon Monoxide 3 %/ppm 3 %/ppm	Heating Unit – Okay <u>X</u>
Carbon Monoxide Detector (tube type) Positive Nega	tive_X
Look At Total Heating System Before You Leave:	
Does system operate safely and properly? Yes X	lo
COMMENTS:	
Name of	
Licensed Contractor: NASSEFF Methanical Address 12	2 5 Wabasha st Phone # 651-777-000/
Person Doing Test (Print) JAMES ECK (signature)	I tel
Cartificate of Competency Number from City of Point Boul for Americanists I	_

Nasseff Mechanical Contractors 122 South Wabasha St. Ste. 101 St Paul, MN 55107



Invoice No:	39954
Page	1

"redefining mechanical service"

Phone: (651) 777-0001 Fax: (651) 602-9296

JOE GENEREUX 9777 JOLIET AVE N STILLWATER MN 55082 208 CHARLES AVE

ST. PAUL MN

Invoice Date	Invoice No.	Customer No.	Payment Terms Contract No:
08/24/12	39954	GEN006	NET 10 DAYS
Ticket#	Qty	Unit Meas Descript	Unit Extended On Price Price

W/O # - B20813016

8/16/12 Jim Eck Service Requested: Combustion air.

Service Performed:

- 1. Found that a combustion air intake is now installed for the 2nd floor furnace.
- 2. Recommend flex duct be installed to the intake head.

B20813016

1.00 HR PIPEFITTER LABOR 1.00 EA TRIP CHARGE

129.00

129.00 40.00

40.00

TO PAY BY CREDIT CARD, GO TO nasseff.com AND CLICK "ONLINE PAYMENT" AT THE BOTTOM OF THE HOME PAGE.

Past due invoices may be subject to a finance charge of 1.5% per month (18% annually). WE APPRECIATE YOUR BUSINESS!

> Gross 169.00

Net Amount Tax 169.00 .00

Nasseff Mechanical Contractors 122 S. Wabasha St. Suite 101 St. Paul, MN 55107

651.777.0001 Office 651.602.9296 Fax * nasseff.com



ATE: 02

02/28/12

NET

285.00

PAGE: 1

GEN006 JOE GENEREUX 9777 JOLIET AVE N STILLWATER MN 55082

STATEMENT

INVOICE #	DATE	AMOUNT	PAYMENTS	SITE	BALANCE DUE
37364	02/17/12	285.00		208 CHARLES AVE *	285.00
			(
				, i	
	-				,
				·	
		·			
				, ·	

OVER

90

.00

RETENTION

.00

60

.00

OVER

30

.00

OVER

CURRENT

285.00