



RLH WP 1123
APPLICATION FOR APPEAL

✓ Scanned

RECEIVED

MAY 20 2011

CITY CLERK

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd.

Saint Paul, Minnesota 55102

Telephone: (651) 266-8560

The City Clerk needs the following to process your appeal:

- \$25 filing fee payable to the City of Saint Paul (if cash: receipt number _____)
- Copy of the City-issued orders or letter which are being appealed
- Attachments you may wish to include
- This appeal form completed

YOUR HEARING Date and Time:

Tuesday, 6-7-11

Time 1:30

Location of Hearing:

Room 330 City Hall/Courthouse

called and let him know of mtg.

Address Being Appealed:

Number & Street: 995 Burgess City: St Paul State: MN Zip: 55103

Appellant/Applicant: SMR Real Estate Email: INFO@SYNERGYREI.COM

Phone Numbers: Business _____ Residence _____ Cell 612 670 0321

Signature: *[Signature]* (Sam Riesgraf) Date: 5/15/11

Name of Owner (if other than Appellant): _____

Address (if not Appellant's): _____

Phone Numbers: Business _____ Residence _____ Cell _____

What Is Being appealed and why? Attachments Are Acceptable

- Vacate Order/Condemnation/Revocation of Fire C of O
- Summary/Vehicle Abatement
- Fire C of O Deficiency List
- Fire C of O: Only Egress Windows
- Code Enforcement Correction Notice
- Vacant Building Registration
- Other
- Other
- Other

CAT 2 list BR Egress wdws



CITY OF SAINT PAUL
INTERDEPARTMENTAL MEMORANDUM

EGRESS WINDOW NON-COMPLIANCE DETERMINATION

TO: CITY CLERK
15 KELLOGG BLVD. WEST
310 CITY HALL
SAINT PAUL, MN 55102

PHONE: 651-266-8688
FAX: 651-266-8574

DATE: 5-26-11

APPEAL PROPERTY ADDRESS: 995 Burgess

APPLICANT NAME: Sam Riesgraf

PHONE NUMBER: 612-670-0321

PERMIT NUMBER: 10-019687

TYPE OF WINDOW D.H.

NUMBER OF WINDOWS 2

Total Glazed Area	6.5	Difference from Required Area	+ 1.5
Width of Opening	34.5	Difference from Required Opening	+ 14.5
Height of Opening	17.5	Difference from Required Opening	- 6.5
Height of Opening to Finished Floor	_____	Difference from Maximum Height	_____

COMMENTS:

Reviewed by:



CITY OF SAINT PAUL
Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220
Saint Paul, Minnesota 55101-1806

Telephone: 651-266-8989
Facsimile: 651-266-9124
Web: www.stpaul.gov/dsi

August 26, 2010

JOHN MALENSEK - FANNIE MAE
425 9TH ST S
SOUTH ST PAUL MN 55075

Re: 995 Burgess St
File#: 10 019687 VB2

Dear Property Owner:

The following is the Code Compliance report you requested on August 11, 2010.

Please be advised that this report is accurate and correct as of the date August 26, 2010. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from August 26, 2010. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected:

BUILDING **Inspector: Jim Seeger** **Phone: 651-266-9046**

- Install plinth blocks as needed under posts in basement & ensure adequate footing for load imposed.
- Tuck Point interior/exterior of foundation as necessary.
- Dry out basement and eliminate source of moisture.
- Remove mold, mildew and moldy or water damaged materials.
- Permanently secure top and bottom of support posts in an approved manner.
- Cover water meter pit with concrete or decay resistant, screwed-down cover. Cleanouts to be flush with floor slab.
- Provide adequate access, ventilation and clearance in crawl space area.
- Install handrails (34 inches - 38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment.
- Strap or support top of stair stringers for structural stability.
- Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary.
- Provide complete storms and screens, in good repair for all door and window openings.
- Provide functional hardware at all doors and windows
- Exit doors shall be capable of being opened from the inside, easily and without the use of a key. Remove all surface bolts.

BUILDING **Inspector: Jim Seeger** **Phone: 651-266-9046**

- Repair or replace damaged doors and frames as necessary, including storm doors.
- Weather seal exterior doors, threshold and weather-stripping.
- Install floor covering in bathroom and kitchen that is impervious to water.
- Repair walls, ceiling and floors throughout, as necessary.
- Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present.
- Air-seal and insulate attic/access door.
- Install Smoke Detectors/Carbon Monoxide Detectors per MN Co Conservation Code and the MN Dept. of Labor and Industry.
- Provide major clean-up of premises.
- Repair siding, soffit, fascia, trim, etc. as necessary.
- Provide proper drainage around house to direct water away from foundation of house.
- Provide proper drainage around house to direct water away from foundation of garage.
- Install downspouts and a complete gutter system.
- Install rain leaders to direct drainage away from foundation.
- Provide general rehabilitation of garage.
- Review all applicable codes & policies when replacing windows including egress windows for sleeping rooms.
- Remove trees which are against foundation of home and garage.
- Openings in stair risers must be less than 4 inches.
- Grade must drain away from foundation of dwelling. Maintain 6 inch clearance between wood and soil.
- Replace landing and steps to code at rear entry.
- Install swales around garage to get drainage and clearance for siding at grade.
- Install tempered glass in window at bottom of stairs on first floor to code.
- Replace lower set of basement steps, rise not uniform.
- Re-install missing post at front support beam in basement.
- Provide support for rear retaining wall in crawl space.
- Repair foundation wall under basement stairs and install floor.
- Repair flooring in hall at top of second floor stairs.
- Second south and east bedrooms on second floor do not meet egress requirements.
- A building permit is required to correct the above deficiencies.

ELECTRICAL **Inspector: Dan Jambor** **Phone: 651-266-9032**

- Ground the electrical service to the water service with a copper conductor within 5 feet of the entrance point of the water service
- Provide a complete circuit directory at service panel indicating location and use of all circuits
- verify/install a separate 20 ampere laundry circuit and a separate 20 ampere kitchen appliance circuit
- Install S type fuse adapters and proper size S fuses listed circuit breakers

ELECTRICAL **Inspector: Dan Jambor** **Phone: 651-266-9032**

- Verify that fuse amperage matches wire size
- Install globe-type enclosed light fixture on all closet lights
- Repair or Replace all broken, missing or loose light fixtures, switches and outlets, covers and plates
- Check all outlets for proper polarity and verify ground on 3-prong outlets
- Remove any 3-wire ungrounded outlets and replace with 2-wire or ground 3-wire to code
- Install exterior lights at side door
- Remove and or/ re-wire all illegal, improper or hazardous wiring in basement/garage
- Throughout building, install outlets and light fixtures as specified in Bulletin 80-1.
- Remove damaged overhead wires to garage
- All added receptacles must be grounded, tamper-resistant and be on an Arc-Fault Circuit Interrupter-protected circuit.
- Any open walls or walls that are opened as part of this project must be wired to the standards of the 2008 NEC.
- All buildings on the property must meet the St. Paul Property Maintenance Code (Bulletin 80-1).
- All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

PLUMBING **Inspector: Tom Schweitzer** **Phone: 651-266-9055**

- Basement - Laundry Tub - Anchor to floor
- Basement - Gas Piping - dryer gas shutoff; connector or piping incorrect (IFGC 402.1)
- Basement - Gas Piping - run dryer vent to code (IFGC 613.1 - IMC 604.1)
- Basement - Laundry Tub - provide a vacuum breaker for the spout (MPC 2000 B)
- Basement - Laundry Tub - unvented (MPC 0200 E)
- Basement - Soil and Waste Piping - improper connections, transitions, fittings or pipe usage (MPC 2420)
- Basement - Soil and Waste Piping - no front sewer clean out (MPC 1000)
- Basement - Soil and Waste Piping - no soil stack base clean out
- Basement - Water Heater - not fired or in service (MPC 2180)
- Basement - Water Meter - support meter properly (MPC 2280)
- Basement - Water Piping - run 1 inch water line from meter to first major take off (SPRWS Water Code)
- Exterior - Lawn Hydrants - Requires backflow assembly or device (MPC 2000)
- First Floor - Lavatory - unvented (MPC 0200. E)
- First Floor - Sink - unvented (MPC 0200. E)
- First Floor - Toilet Facilities - unvented (MPC 0200. E)
- Second Floor - Tub and Shower - Provide access (MPC 0900)
- Second Floor - Tub and Shower - provide anti-scald valve (MPC 1380. Subp. 5)
- Second Floor - Tub and Shower - replace waste and overflow (MPC 1240)
- Second Floor - Tub and Shower - waste incorrect (MPC 2300)
- Obtain plumbing permits prior to commencement of work.

August 26, 2010
995 Burgess St
Page 4

HEATING **Inspector: Kevin Chapdelaine** **Phone: 651-266-9042**

- Clean and Orsat test furnace burner. Check all controls for proper operation. Check furnace heat exchanger for leaks; provide documentation from a licensed contractor that the heating unit is safe.
- Vent clothes dryer to code.
- All supply and return ducts for warm air heating system must be clean before final approval for occupancy. Provide access for inspection of inside of ducts or provide documentation from a licensed duct-cleaning contractor that the duct system has been cleaned.
- Repair and/or replace heating registers as necessary.
- A gas mechanical permit is required for the above work.

ZONING

1. This property is in a(n) R4 zoning district.
2. This property was inspected as a Single Family Dwelling.

Notes:

- See attachment for permit requirements and appeals procedure.
- Most of the roof covering could not be inspected from grade. Recommend this be done before rehabilitation is attempted.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Jim Seeger between 7:30 - 9:00 AM at 651-266-8989 or leave a voice mail message.

Sincerely,

James L. Seeger
Code Compliance Officer

JLS:ml

Attachments



CITY OF SAINT PAUL
Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220
Saint Paul, Minnesota 55101-1806

Telephone: 651-266-8989
Facsimile: 651-266-1919
Web: www.stpaul.gov/dsi

May 19, 2011

SMR Real Estate LLC
9785 Bechtold Road
Rogers MN 55374

Re: 995 BURGESS ST

Chapter 33 of the Saint Paul Legislative Code restricts the sale of Category II Registered Vacant Buildings. Sale of the above referenced address to SMR Real Estate LLC is approved based on the City's review of the following requirements:

1. Application Fee Paid.
2. Zoning Status Approved.
3. Registration of Ownership Updated.
4. Vacant Building Fees Current.
5. Code Compliance Inspection Report Issued.
6. Cost Estimates from Licensed Contractors for Code Compliance Work Submitted.
7. Schedule for Completion of Code Compliance Work Submitted.
8. Proof of Financial Capability Verified.

NOTE: This Category II Registered Vacant Building MAY NOT be reoccupied until all of the repairs required by the Code Compliance Inspection Report have been completed and a Certificate of Code Compliance has been issued by the City's Building Official.

If you have any questions regarding this matter, you may contact me at 651-266-9120.

Sincerely,

Reid Soley
CSO CE Staff