
RLH FCO 18-181



APPLICATION FOR APPEAL

Saint Paul City Council – Legislative Hearings

RECEIVED

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

OCT 15 2018

001 10 2010

We need the following to process your app	beal: CITY CLEF	RK
\$25 filing fee (non-refundable) (payable to (if cash: receipt number (X + 343)) Copy of the City-issued orders/letter has appeal form completed Walk-In OR Mail-In	the City of Saint Paul) ceing appealed	HEARING DATE & TIME (provided by Legislative Hearing Office) Tuesday, OCT- 23, 2018 Time
Address Being Appeale	1@ hotmail.com	
Address Being Appeale	ea:	
Number & Street: 697 Euclid	St City: St	t Paul State: MN Zip: 55106
Appellant/Applicant: Jinghan Qu		quecompjen@hotmail.com
Phone Numbers: Business 651-428-79		Cell
Signature:		Date: 10-11-2018
Name of Owner (if other than Appellant): _		
Mailing Address if Not Appellant's: 410	3 E Lake	St. Minneapolis, MN 55406
Phone Numbers: Business		
What Is Being Appeale	d and Why?	Attachments Are Acceptable
Vacate Order/Condemnation/	Comments:	
Revocation of Fire C of O	Request to extension	for correction order#11 & 14 actor the project can be done next year
O Summary/Vehicle Abatement O Fire C of O Deficiency List/Correction	may or June since the long waiting list & weather	
• Fire C of O Deficiency List/Correction		son voluntary moving out the house and difficult to find a new place to moving
O Code Enforcement Correction Notice O Vacant Building Registration		r already started. I'll reduce a person

SAINT PAUL CITY OF SAINT PAUL

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

September 25, 2018

JINGHAN QU 4103 E Lake St Minneapolis MN 55406-2259

FIRE INSPECTION CORRECTION NOTICE

RE:

697 EUCLID ST

Ref. #119308

Residential Class: C

Dear Property Representative:

Your building was inspected on September 20, 2018 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior-to-the-re-inspection date.

A re-inspection will be made on October 18, 2018 at 1:30 pm

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

and produced by the control of the control

1. 2nd Floor - Hallway - SPLC 34.10 (7), 34.17 (5) - Repair and maintain the ceiling in an approved manner. Repair the water damage and all other damage to the ceiling in a professional manner.

- 2. 2nd Floor Hallway, North End SPLC 34.12 (2), SPLC 34.36 (1) Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code. The smoke detector is 10 years of age and needs to be replaced.
 - 3. 2nd Floor North Bedroom NEC 440.13 For cord-connected equipment such as: room air conditioners, household refrigerators and freezers, drinking water coolers, and beverage dispensers, a separable connector or an attachment plug and receptacle shall be permitted to serve as the disconnecting means. The appliance must plug directly into a permanent outlet. The A/C unit is plugged onto a power tap, all major appliances need to be plugged into an outlet.
 - 4. 2nd Floor Northeast Bedroom MSFC 1030.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exit path. Remove the A/C unit that is blocking the emergency egress window.
 - 5. 2nd Floor Hallway SPLC 34.10 (7), 34.17 (5) Repair and maintain the walls in an approved manner. Repair the water damage and all other damage to the walls in an a professional Manner.
- 6. 2nd Floor Northeast Bedroom SPLC 34.10 (7), 34.17 (5) Repair and maintain the walls in an approved manner. Repair all damage to the walls including cracks, holes and all other damage.
- 7. 2nd Floor South Bedroom NEC 440.13 For cord-connected equipment such as: room air conditioners, household refrigerators and freezers, drinking water coolers, and beverage dispensers, a separable connector or an attachment plug and receptacle shall be permitted to serve as the disconnecting means. The appliance must plug directly into a permanent outlet. The A/C unit is plugged into a power tap.
- 8. Basement Southeast Room SPLC 34.10 (1) Abate and maintain the basement reasonably free from dampness and free of mold and mildew. Repair the water damage behind the door.
- 9. Exterior Throughout SPLC 34.09 (2), 34.33 (3) Provide and maintain foundation elements to adequately support this building at all points. Replace the spray foam sealing the cracks and repair the cracks in an approved manner.
- 10. Exterior Throughout SPLC 34.09 (2), 34.33 (1) Provide and maintained the roof weather tight and free from defects. Repair the holes in the soffit and any other damage to them in an approved manner.

- Exterior SPLC 34.08 (7) All parking spaces shall be paved with asphalt, concrete, or durable dustless surfacing. Before any existing spaces may be paved, site plan approval must be obtained as specified in the St. Paul Zoning Code. Contact DSI Zoning at 651-266-8989. Repair or replace the driveway in an approved manner.
- 12. Garage MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing. Provide an outlet cover plate for the garage door opener.
- 13. Garage SPLC 34.08(5), 34.32(3) All accessory structures including, but not limited to, detached garages, sheds and fences shall be maintained structurally sound and in good repair. Provide and maintain exterior unprotected surfaces painted or protected from the elements. Repair the threshold for the service door to the garage.
- 14. Interior SPLC 34.13 (2), (3), SPLC 34.17 (2) The unit is overcrowded. Reduce and maintain the number of occupants in the unit to: This unit is only allowed to have 4 or less unrelated adults living in it, reduce the number of occupants or apply for the proper license.
- 15. Main Level Bedroom MSFC 605.4 Discontinue use of all multi-plug adapters.
- 16. Main Level Bedroom MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.
- 17. Main Level Bedroom SPLC 34.12 (2), SPLC 34.36 (1) Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code. The north bedroom window will not open.
- 18. North Bedroom MSFC 1030.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exit path. The emergency egress windows are blocked, allow access to one of the windows for egress in case of an emergency.
- 19. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: brian.schmidt@ci.stpaul.mn.us or call me at 651-266-8981 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Brian Schmidt Fire Inspector

Reference Number 119308