Inspections Detail

| Inspection Number | 79625 | Tenant | Burns,Tatiania | Requested Date | 12/12/2024 |
|--------------------------|-------------------|------------------|------------------------|-----------------------|------------|
| Inspection Protocol | HCV ANN 7 | Phone | (651) 503-877 | Schedule Date | 01/16/2025 |
| Inspector | Patrick Rucci | Address | 1009 MAGNOLIA AVE E | Inspection Date | 01/16/2025 |
| Inspector Email | | City, State, Zip | SAINT PAUL,MN 55106 | Followup Date | |
| | | | | Scheduled Time | 09:00 |
| Inspection Type | Initial | | | | |
| Status | Inspection Failed | | | | |
| Inspection Start Time | 18:30 | | | | |
| Inspection End Time | : | | | | |

| Area | Item | Deficiency | Severity | Approved Date | Comment |
|----------------------------|-------------------------|--|----------|---------------|--|
| Bathroom 2 | Wall Condition | Miscellaneous Deficiency | Fail | | Upper bathroom closet doors are off track. |
| Bedroom 2 | Smoke Detectors | Bedroom smoke detector did not test as working | Fail | | Middle bedroom. |
| Bedroom 2 | Window Condition | Lacks hold open hardware (must stay open in all positions) | Fail | - | Middle bedroom right window lacks hold open hardware. |
| Bedroom 1 | Window Condition | Lacks hold open hardware (must stay open in all positions) | Fail | | Both front bedroom windows lack hold open hardware. |
| Bedroom 1 | Floor Condition | Miscellaneous Deficiency | Fail | | Upper front bedroom floor is unsanitary with garbage & debris. |
| Bedroom 1 | Wall Condition | Miscellaneous Deficiency | Fail | | Upper front bedroom door is damaged beyond repair. |
| Hallways and entry ways | Wall Condition | Miscellaneous Deficiency | Pass | - | |
| Hallways and entry ways | Wall Condition | Hole(s) or crack(s) | Fail | | Upper hailway wall has a large hole. |
| Hallways and entry ways | Wall Condition | Parts loose/missing | Fail | - | Upper staircase handrail bracket is broken. |
| All Secondary Rooms | Other Potential Hazards | Basement smoke detector is constantly chirping | Fail | - | |
| All Secondary Rooms | Other Potential Hazards | Miscellaneous Deficiency | Fail | - | Basement floor has excessive clutter, trash & debris. |
| Kitchen | Stove/Range with Oven | Miscellaneous Deficiency | Fail | - | Stovetop front burner knob stem is loose. |

| Kitchen | Wall Condition | Miscellaneous Deficiency | Fail | - | Kitchen east wall tiles are melted by air fryer. |
|--------------------------------|--|--|------|-------|---|
| Dining Room and Dining Area | Wall Condition | Deteriorated paint-under 2 sq feet | Fail | - | Dining room door frames. |
| Kitchen | Electrical Hazards | Lightswitch(es) broken | Fail | ····· | Kitchen light switch toggle is broken. |
| Dining Room and Dining Area | Floor Condition | Miscellaneous Deficiency | Fail | - | Dining room/kitchen threshold is missing. |
| Bathroom | Wall Condition | Parts loose/missing | Fail | - | Main floor bathroom toilet paper holder lacks the roll rod |
| Bathroom | Tub and Shower in Unit | Slow drain | Fail | - | Main floor bathtub drains slow |
| Bathroom | Flush Toilet in Enclosed Room | Miscellaneous Deficiency | Fail | - | Main floor toilet seat is loose. |
| Building Exterior | Stairs, Rails, Porches, Balconies and Decks | Miscellaneous Deficiency | Fail | - | Rear screen door screen is torn. Patch or repair. |
| General Health and Safety | Site and Neighborhood Conditions | Yard has discarded debris- remove | Fail | - | Refrigerator, pile of brush, trash & debris from front & rear yard. |
| Building Exterior | Condition of Exterior Surfaces | Miscellaneous Deficiency | Fail | - | Overhead garage door is off track. |
| Building Exterior | Lead-Based Paint | Remove any paint chips and dust | Fail | - | |
| Building Exterior | Lead-Based Paint | Provide a valid EPA Lead Safe certification | Fail | - | |
| Building Exterior | Lead-Based Paint | Complete post-work lead paint checklist (Exterior) | Fail | - | |
| Building Exterior | Lead-Based Paint | Complete pre-work lead paint checklist | Fail | - | |
| Building Exterior | Condition of Exterior Surfaces | Exterior has deteriorating paint-over 20 sq feet | Fail | - | Garage siding and trim. |
| General Health and Safety | Evidence of Infestation | The unit has evidence of a mice/rodent infestation | Fail | - | |

. "

Approved by Connor Kirchert on Apr 10, 2025

Approved



78 10th St E • Saint Paul, MN 55101-2247 • Phone: 5072799923

Kirchert LLC Cell: +16512337331

261 7th St W St. Paul, MN 55102 Job Address: 1009 Magnolia Ave E St. Paul, MN 55108

Print Date: 4-15-2025

Proposal for Magnolia Refresh

Thank you for the opportunity to provide a bid for your upcoming project. We understand that this is an important investment for you, and we are committed to delivering high-quality work that meets your vision and expectations.

Our proposal includes a detailed breakdown of costs and materials for each phase of the project. We have taken into consideration your needs and preferences to ensure that our plan aligns with your goals. Throughout the bidding process, our team will be available to answer any questions and provide updates to keep you fully informed. Below is the estimate for your project.

| Items | Description | Qty/Unit | Price |
|---|--|----------|------------|
| Overhead 01.30 Project Management, Mobilization, Site Preparation | Profit and Overhead | 1 | \$1,000.00 |
| Demo 01.15 Demo | Demo kitchen, and bathroom tile, and drywall over. Trash out items to dump. | 1 | \$1,925.00 |
| Lights - Electrical - Switches 08.05 Lighting | Install 2 new ceiling lights Add GFI in kitchen Covers and switches as needed. | 1 | \$715.00 |
| Garage door - Glass 11.00 Glass | Fix garage door, Replace glass in 4 windows. | 1 | \$1,430.00 |
| Vanity 12.20 Vanity Install | Install a new vanity. | 1 | \$550.00 |

| Doors 14.30 Interior Doors | Replace doors, hardware, locks - 4 | 1 | \$2,035.00 |
|--------------------------------|---|---|-------------|
| Paint & Drywall 15.00 Paint | Patch all holes and gouges in walls and ceilings. Paint walls, porch, kitchen ceiling, and all white trim. | 1 | \$14,960.00 |

Total Price: \$22,615.00

Thank you for considering our proposal for your project. We are confident that our experience, attention to detail, and dedication to quality will deliver results that meet and exceed your expectations. Our team is committed to creating a project that matches your vision and stands the test of time.

If you have any questions or need more information, please feel free to reach out. We are excited about the chance to work with you and turn your vision into a reality.

Thank you again for this opportunity. We hope to partner with you soon!

I confirm that my action here represents my electronic signature and is binding.

Signature:

Jor 762 4/10/15

Date:

Print Name:

Joshua Kirchert



























































