

Saint Paul Fire Department FIRE INCIDENT DISPOSITION



INCIDENT NUMBER:	20-06260	DATE OF INCIDENT: 2-17-2020	
TIME OF INCIDENT:	1833	POLICE CASE #: n/a	
INVESTIGATOR (s):	B. Riewe		
INCIDENT ADDRESS:	1362 Palace Ave		
OCCUPANT NAME:	Angela Y Weber	PHONE: 612-819-7222	
OWNER NAME:	Angela Y. Weber	PHONE: 612-819-7222	
ADDRESS OF OWNER:	1455 Wellesley Ave St. Paul, MN 55105		
PROPERTY DAMAGED:	Single Family Home	AREA OF ORIGIN: Kitchen Ceiling	
DAMAGE ESTIMATE:	Building \$50,000	Vehicle \$n/a	Other (Describe) \$n/a
VALUE:	Building \$122,700	Vehicle \$n/a	Other (Describe) \$n/a
Damage Estimate CONTENTS ONLY:	\$5,000		
INJURY/DEATH (if yes, explain)	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes		
SMOKE DETECTOR, SPRINKLER, and CARBON MONOXIDE INFORMATION:	Smoke Detector Present: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown Detector Functioning: <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Unknown Sprinkler System Present: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown Sprinkler Heads activated: <input type="checkbox"/> Yes # <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown C.O Detector Present: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown		
FIRE CAUSE CLASSIFICATION:	<input type="checkbox"/> Accidental <input type="checkbox"/> Juvenile/Incendiary <input type="checkbox"/> Incendiary <input type="checkbox"/> Child (under 10 years old) <input type="checkbox"/> Natural <input type="checkbox"/> Undetermined <input checked="" type="checkbox"/> Under Investigation		
SYNOPSIS:	The Saint Paul Fire Department was dispatched to the report of a house fire in a home that is under construction. Firefighters arrived on scene of a 1 1/2 story, single family residence to find smoke showing from the attic vents and eaves. Fire crews used preconnected hose lines to extinguish the fire, completed ventilation and conducted overhaul. Investigation and interviews conducted on scene determined the home was in the process of a complete remodel. The fire started in the main floor kitchen area, spread up into the knee wall above and into the attic space. The ignition source is under investigation. The first fuel ignited is under investigation. The act that brought these two together is under investigation. The classification of fire cause is under investigation but most likely accidental.		
DISPOSITION:	<input type="checkbox"/> E-mail only <input type="checkbox"/> Hold Scene until approved <input type="checkbox"/> DO NOT DEMOLISH until approved <input checked="" type="checkbox"/> Scene Released <input type="checkbox"/> Analysis of Evidence Pending <input checked="" type="checkbox"/> Report to Follow		

