

# APPLICATION FOR APPEAL

RECEIVED JAN 03 2011 CITY CLERK

# Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

The City Clerk needs the following to pro	ocess your appeal:		
\$25 filing fee payable to the City of S (if cash: receipt number)  Copy of the City-issued orders or let are being appealed  Attachments you may wish to includ This appeal form completed  Walk-In OR Mail-In	ter which	YOUR HEARING Date and Time:  Tuesday, 1-10-12  Time 1:30  Location of Hearing: Room 330 City Hall/Courthouse	
Address Being Appeal	ed:		•
Number & Street: 1058 5	+n St. E City:	St. Paul State: MN Zip: 5516	6
Appellant/Applicant: Mark SY	RSTAD E	mail MARK. SYRSTAD@ PEN	tain. con
Phone Numbers: Business	Residence	Cell 805-990-83	<u> </u>
Signature: Mal Sy	ted	Date: 12/29/11	- Anny manara.
		Actual Address)	
Address (if not Appellant's): 49	94 SHADY TO	RAIL St. Simi VALLEY, CA	#93063
Phone Numbers: Business	Residence	Cell	tanksisje ogw
What Is Being Appeale	ed and Why?	Attachments Are Acceptable	
Vacate Order/Condemnation/ Revocation of Fire C of O	1) Appeal o	F Egress (oughel	when)
☐ Summary/Vehicle Abatement  ★ Fire C of O Deficiency List	2 BECAUSE	,	(CA)
□ Fire C of O: Only Egress Windows	I would	LIKE AN EXTENSION FOI	2
□ Code Enforcement Correction Notice		BE MADE	acromodianomic
□ Vacant Building Registration		HACE GARAGE DOOR Wha	14/ Retain
□ Other	1120	Danite di di	and design and report of the second of the s

premits

weather

DEPARTMENT OF SAFETY AND INSPECTIONS
Fire Inspection Division
Ricardo X. Cervantes, Director



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 
 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

December 16, 2011

APPLEGATE PROPERTY MANAGEMENT 1940 GREELEY ST # 202 STILLWATER MN 55082-5097

#### FIRE INSPECTION CORRECTION NOTICE

RE:

1058 5TH ST E Ref. #113043

Residential Class: C

# Dear Property Representative:

Your building was inspected on December 9, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

# A re-inspection will be made on January 20, 2012 at 1:30pm.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

# **DEFICIENCY LIST**

- 1. Basement Floor SPLC 34.10 (7), 34.33 (6) Repair and maintain the floor in an approved manner.
- 2. Basement Walls SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls in an approved manner.-Remove the mold like substance from the basement walls. Maintain the walls in a good state of repairs.

- 3. Basement Water Heater MSFC 105.1.1 Permits are required for the new installation of a water heater.-There is an open permit for the installation of the water heater. Contact plumbing inspector, Steve Fernlund 651-266-9052, for final inspection.
- 4. Basement SPLC 34.09 (3), 34.32 (3) Repair and maintain the door in good condition.Provide a weather tight seal around the basement walk out door.
- 5. Basement MSFC 315.2.5 Fueled equipment, including but not limited to motorcycles, mopeds, lawn-care equipment and portable cooking equipment, shall not be stored, operator or repaired within a building.-Remove the lawnmower from the basement.
- Basement SPLC 34.09 (3) i Provide and maintain an approved one-inch throw single cylinder deadbolt lock.-Repair/replace the inoperable dead-bolt lock on the basement walk out door.
- 7. Building Exterminate SPLC 34.10 (6), 34.33 (5) Exterminate and control insects, rodents or other pests. Provide documentation of extermination.-Inspector saw mice dropping throughout the property. Contact licensed exterminator to inspect and evaluate the building for insects/rodents. Provide the inspector copy of the exterminator's report. Extermination of the building shall be done if indicated by the extermination report.
- 8. Egress Windows MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651) 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.

#### Main Floor

# East Bedroom (Double-hung)

22h x 24w - Openable

49h x 24w - Glazed

#### Northwest Bedroom (Double-hung)

Note: This window was inoperable so inspector was unable to take measurements.

#### Southwest bedroom (Double-hung)

20h x 24w - Openable

41h x 24w - Glazed

9. Exterior - Chain Link Fence - SPLC 34.08 (5), 34.31 (3) - Repair, replace and maintain all fences free from damage and deterioration.-Repair/replace the damaged chain link fence.

- 10. Exterior Driveway SPI.C 34.08 (7) All parking spaces shall be paved with asphalt, concrete, or durable dustless surfacing. Before any existing spaces may be paved, site plan approval must be obtained as specified in the St. Paul Zoning Code. Contact DSI Zoning at 651-266-9090.-Provide an approved parking surface for the driveway.
- 11. Exterior Retaining Wall SPLC 34.09 (1) b,c, 34.32 (1) b,c Provide and maintain all exterior rotaining walls free from holes and deterioration.-Repair/replace the retaining wall.
- 12. Garage Overhead Door SPLC 34.09 (3), 34.32 (3) Repair and maintain the door in good condition.-Repair/replace the damaged overhead garage door.
- Garage Provide Access SPLC 34.19 Provide access to the inspector to all areas of the building.-Provide the inspector access to the detached garage.
- Main Floor Bathroom SPLC 34.09 (3), 34.32 (3) Repair and maintain the window in good condition.
- Main Floor East Bedroom SPLC 34.09 (3), 34.32 (3) Repair and maintain the window in good condition.-Repair/replace the window that is not staying in the up position.
- 16. Main Floor East Bedroom MSFC 605.4 Discontinue use of all multi-plug adapters.
- Main Floor East Bedroom SPLC 34.09 (3), 34.32 (3) Repair and maintain the window lock.
- 18. Main Floor Kitchen SPLC 34.12 (2), 34.35 (1) Repair and maintain all required and supplied equipment in an operative and safe condition.-Repair/replace the oven door on the range that is not operating correctly.
- 19. Main Floor North Entry Door and East Bedroom SPLC 34.09 (3), 34.32 (3) Repair and maintain the door in good condition.-Repair/replace the loose/missing strike-plate on the entry door frame.
- 20. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo.

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: wayne.spiering@ci.stpaul.mn.us or call me at 651-266-8993 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Wayne Spiering Fire Inspector

Reference Number 113043

City of St. Paul, To whom it may CONCERN,

ORIGINAL FIRE INSpection notice was sent to our property management company (Applegate) It should mus been sent directly to us. WE DID NOT RECEIVE ANY WORD OF DEFICIECIES WE ARE ASKING WAYNE S. FOR AN EXTENSION until Now. (12/29/11) to produce any deficencies.

PLEASE CALL ME with any questions or concerns.

Flank you, mark Syntad 805-990-8550