



CITY OF SAINT PAUL
Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220
Saint Paul, Minnesota 55101-1806

Telephone: 651-266-8989
Facsimile: 651-266-8951
Web: www.stpaul.gov/dsi

February 15, 2013

JOSEPH V. ADOLPH
1406 WESTERN AVE
SEATTLE WA 98101-2064

Revocation of Fire Certificate of Occupancy and Order to Vacate

RE: 988 ARGYLE ST

Dear Property Representative:

Your building was determined to be a registered vacant building on February 15, 2013. Since certificates are for the occupancy of buildings, it has become necessary to revoke the Certificate of Occupancy.

Saint Paul Legislative Code provides that no building shall be occupied without a Certificate of Occupancy. In order to re-occupy the building, the following deficiencies (if applicable) must be corrected and a complete Certificate of Occupancy inspection will be required.

DEFICIENCY LIST

1. Exterior - SPLC 34.09 (3), 34.32 (3) - Repair and maintain the window glass.-Replace all cracked windows.
2. Exterior - SPLC 34.09 (3), 34.32 (3) - Provide or repair and maintain the window screen.
3. Exterior - SPLC 71.01 - The address posted is not visible from street.-Provide reflective numbers or background or illuminate at night.
4. Exterior - Remove the accumulation of snow or ice from the public and private sidewalk abutting this property.
5. Exterior - SPLC 34.09 (3), 34.32 (3) - Repair and maintain the door in good condition.
6. Exterior - MSFC 1011.2 - Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.-Side door will not open as it is damaged. Repair or replace.

7. Interior - throughout - MSFC 605.1 - Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-9090.-Hire a licensed electrician to repair all damaged or exposed wiring and replace all lighting installed without permits.
8. Interior - UMC 504.6 - Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work requires a permit(s). Call DSI at (651) 266-8989.
9. Interior - NFPA 211,9-2 - Have the chimneys, fireplaces, and vents inspected for soundness, freedom from deposits, and correct clearances. Cleaning, maintenance, and repairs shall be done if indicated by the inspection.
10. Interior - SPLC 34.10 (1) - Abate and maintain the basement reasonably free from dampness and free of mold and mildew.
11. Interior - MSFC 605.6 - Provide electrical cover plates to all outlets, switches and junction boxes where missing.
12. Interior - MSFC 605.1 - Remove unapproved exposed wiring and install in accordance with the electrical code. This work may require a permit(s). Call DSI at (651) 266-9090.
13. Interior - SPLC 34.11 (5), 34.34 (2) - Contact a licensed contractor to repair or replace the water heater. This work may require a permit(s). Call DSI at (651) 266-9090.
14. Interior - SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 4715.0200.C - Provide an approved number and type of plumbing fixtures.-Hire a licensed plumber to repair all damaged plumbing fixtures and certify the basement shower that was installed without permit.
15. Interior - SPLC 34.09 (3), 34.32 (3) - Repair and maintain the window locks.
16. Interior - SPLC 34.10 (7), 34.33 (6) - Repair and maintain the ceilings in an approved manner.
17. Interior - SPLC 34.10 (7), 34.33 (6) - Repair and maintain the cabinets in an approved manner.-Repair or replace the damaged or missing doors.
18. Interior - SPLC 34.10 (7), 34.33 (6) - Repair and maintain the floors in an approved manner.
19. Interior - MN Stat. 299F.362 - Immediately provide and maintain a smoke detector located outside each sleeping area.-Hire a licensed electrician to repair or replace the hard wired smoke detector that is damaged.
20. Interior - SPLC 34.10 (3), 34.33(2) - Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.

21. SPLC 34.11 (6), 34.34 (3) - Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
22. SPLC 39.02(c) - Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: <http://www.stpaul.gov/cofo>

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: lisa.martin@ci.stpaul.mn.us or call me at 651-266-8988 between 6:30 - 8:30 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Lisa Martin
Fire Inspector