

Case Number	Case Name	Location Street Number	Incident Disposition	Fire Fire Spread Materials	Investigation Case Background	Investigator	Case Status
					was fire in and around the dryer. Resident attempted to extinguish fire with dry chemical extinguisher, but was unable to suppress the fire. Resident called 911. Firefighters evacuated the structure, extinguished the fire, ventilated and conducted overhaul. Command was terminated and the scene was released.		
SPFD210207005303	N/A	331 Lawson	Accidental	Beyond building of origin	The Fire Department was called to a report of house fire. Firefighters arrived and found heavy fire conditions between two dwellings that were approximately three feet apart. The occupant of Unit #1 states that he was in the front room of his Unit and smelled smoke. The occupant states that he investigated the source of the smoke and found increased smoke and embers coming from his bedroom that was located midway to the back of the house and to the east of the dining room. The occupant also admitted to smoking in the house and disposing of the cigarettes in numerous plastic bottles around the house. The heavily fire damaged bedroom had a window that faced the exposure dwelling that had a similar window facing this window. Investigation revealed heavy fire damage in the southwest corner of the bedroom and around a window that failed during the fire event that exposed 329 Lawson to heavy fire conditions . In the area of heaviest fire damage a plastic bottle of cigarettes was located and other possible ignition sources were eliminated due to their absence or their distance from this area of origin.	Joseph Blank	Open
		329 Lawson	Accidental	Beyond building of origin	The Fire Department was called to a report of house fire. Firefighters arrived and found heavy fire conditions between two dwellings that were approximately three feet apart. The occupant of Unit #1 states that he was in the front room of his Unit and smelled smoke. The occupant states that he investigated the source of the smoke and found increased smoke and embers coming from his bedroom that was located midway to the back of the house and to the east of the dining room. The occupant also admitted to smoking in the house and disposing of the cigarettes in numerous plastic bottles around the house. The heavily fire damaged bedroom had a window that faced the exposure dwelling that had a similar window facing this window. Investigation revealed heavy fire damage in the southwest corner of the bedroom and around a window that failed during the fire event that exposed 329 Lawson to heavy fire conditions . In	Joseph Blank	Open

Case Number	Case Name	Location Street Number	Incident Disposition	Fire Fire Spread Materials	Investigation Case Background	Investigator	Case Status
					the area of heaviest fire damage a plastic bottle of cigarettes was located and other possible ignition sources were eliminated due to their absence or their distance from this area of origin.		
Count: 3							
Start Date: 02/08/2021							
SPFD210208005314	N/A	1019 Cumberland	Accidental	Confined to room of origin	Firefighters were dispatched to a possible basement fire in a structure. C3 arrived to find heavy smoke coming from the eaves and basement window. S1 and E8 arrived and pulled attack lines to the basement. E4 established a water supply to S1 & E8 and then assisted with fire attack on the first floor with a 2nd line. L8 preformed a primary on all floors (all Clear). S3 assisted with ventilation. L23 was IRIT and E23 assisted with fire attack. One occupant was displaced with no injuries. Car 20 was down the street from a earlier fire and reported to the scene to assist. Fire was contained to the basement with heavy content lost. Smoke damage through out the structure. Crews preformed overhaul after Car 20 was complete. Board up was on scene and all companies cleared.	Joseph Blank	Open
Count: 1							
Count: 7							

Report Criteria

Start Date: Is Between 2/5/2021 and Today