

### **Investigation Report**

### Case

SPFD211201052436	Johnson, Randall	Closed	N/A
Case Number	Lead Investigator	Status	Name
Confidential	Accidental		Candles
Confidentiality	Disposition		Fire Cause
12/01/2021	03:48		
Start Date	Start Time	End Date	End Time
Saint Paul Fire Department			Saint Paul Police Department
Primary Fire Department	Secondary Fire	Department	Law Enforcement
	<ul> <li>Firefighters evacuated the</li> </ul>		arrived and found flames showing from shed the fire and conducted overhaul.
The fire department was cal first floor alpha side window Command was terminated a	<ul> <li>Firefighters evacuated the</li> </ul>		
The fire department was cal first floor alpha side window Command was terminated a	<ul> <li>Firefighters evacuated the</li> </ul>		

## Fire

Candles	Bedroom - < 5 persons; included are jail or prison		
Fire Cause	Area of Origin	Equipment Power Source	Equipment Portability
L Area of Origin Comments	5		
Candle		Fabric, fiber, cotton, bl	ends, rayon, wool
Heat Source		Material Ignited	
Equipment Involved In Ignition	Equipment Make	Equipment Model	Equipment Serial Number
Confined to room of origin	n		
Confined to room of origin	n		
Confined to room of origing Fire Spread Material	n	Fire Spread Avenue	
	n	Fire Spread Avenue  Smoke Spread Avenue	
Fire Spread Material	n		
Fire Spread Material  Smoke Spread Material  Fire Comments	n		
Fire Spread Material  Smoke Spread Material			from the SSE
Fire Spread Material  Smoke Spread Material  Fire Comments	Relative Humidity (%)	Smoke Spread Avenue	
Fire Spread Material  Smoke Spread Material  Fire Comments  eather		Smoke Spread Avenue	from the SSE
Fire Spread Material  Smoke Spread Material  Fire Comments  eather  Visibility	Relative Humidity (%)	Smoke Spread Avenue	from the SSE

Property Details (1 of 1)

N/A 			
		11	
1213 Woodbridge Street Address		Apt/Suite/Room	
Saint Paul	Ramsey County	Minnesota	55117
ity	County	State	Postal Code
\$99,000.00	\$2,000.00	\$7,500.00	
re Fire Value	Content Loss Value	Structure Los	s Value
Property Description			
ea			
Structure	Urban		

		Occupied	
roperty Use		Structure Occupa	ancy
	Yes		
larm Type	Smoke Detector	Present	Smoke Detector Performance
None		Unknown	
prinkler Standpipes		Sprinkler Standp	ipes Performance
43	22	2	
cructure Length (Ft) St	ructure Height (Ft) Structur	e Width (Ft) Numl	per Of Stories Number Of Units
Wood Frame	Type V		
onstruction Type	Structure Type		Structure Material
Slab	Wood	Pitched	Asphalt
oundation	Exterior Covering	→ L———————— Roof Type	Roof Material
everywhere. Fire started n	nent was extremely unkept. Clo ear the floor along the bravo w		
everywhere. Fire started n monitoring. Iterior Exam Windows broken on alpha windows broken with inter	ear the floor along the bravo w	all, under the window	
everywhere. Fire started n monitoring. Iterior Exam Windows broken on alpha windows broken with inter	ear the floor along the bravo w	all, under the window	s. No accelerants noted when
everywhere. Fire started nonitoring.  terior Exam  Windows broken on alpha windows broken with inter  kterior Exam	ear the floor along the bravo w / bravo corner. Crews reported rior fire attack.	all, under the window	s. No accelerants noted when
everywhere. Fire started nonitoring.  terior Exam  Windows broken on alpha windows broken with inter  kterior Exam	ear the floor along the bravo w / bravo corner. Crews reported rior fire attack.	all, under the window	s. No accelerants noted when
everywhere. Fire started nonitoring.  terior Exam  Windows broken on alpha windows broken with interior Exam  cterior Exam  The and Security Service to the service of the	ear the floor along the bravo w  / bravo corner. Crews reported rior fire attack.	only one window bro	s. No accelerants noted when
everywhere. Fire started nonitoring.  terior Exam  Windows broken on alpha windows broken with interesterior Exam  rm and Security Service  None  prinkler Standpipes	/ bravo corner. Crews reported rior fire attack.	only one window bro	ken on arrival with fire showing. Other
everywhere. Fire started n monitoring. Iterior Exam Windows broken on alpha	/ bravo corner. Crews reported rior fire attack.  Tes  Smoke Detectors Present	only one window bro	ken on arrival with fire showing. Other

## Witness Statement (1 of 2)

Roark	Andrea	
Last Name	First Name	Middle Name
Owner/Occupant		
Туре	Employ	ver
Interviewed Date	Interviewed By	Interviewed By Other
1213 Woodbridge St.		
Street 1	Street 2	2
Saint Paul	Minnesota	55117
City	State	PostalCode
Race	Date of Birth	Driver's Liscense Number
- I have a roommate that oc - He is currently at my sister	ut the house. the front room. oor with my family and called 9-1-1. casionally stays in the involved room.	as sleeping and my kid(s) woke me up.

# Witness Statement (2 of 2)

Wricks	Pierre	
Last Name	First Name	Middle Name
Occupant		
Туре	Employ	er
Interviewed Date	Interviewed By	Interviewed By Other
1213 Woodbridge St.		
Street 1	Street 2	2
Saint Paul	Minnesota	55117
City	State	PostalCode
Race	Date of Birth	Driver's Liscense Number

#### Conclusion

#### **Case Conclusion**

After examination of the fire scene, observation of fire patterns of both movement and intensity and interviews conducted, it is my opinion the fire began in the alpha side bedroom, first floor. The area of origin was at the floor level, bravo side of room. The first fuel/material ignited was most likely fabric / clothing. The ignition source was most likely a candle. The oxidant was normal atmospheric air. The action that brought these items together was an unattended candle. No accelerants noted when monitoring. The classification of fire cause is accidental. This concludes my investigation and report.

Signature			
Johnson, Randall			
Lead Investigator	Signature	Date Submitted	

#### **Document Attachment List**

Photo Log