

(if cash: receipt number\_

are being appealed

\$25 filing fee payable to the City of Saint Paul

Copy of the City-issued orders or letter which

## **APPLICATION FOR APPEAL**

RECEIVED

DEC 28 2011

# 310 City Hall, 15 W. Kellogg Blvd.

YOUR HEARING Date and Time:

Tuesday, 1-10-12

Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

Saint Paul City Clerk

### CITY CLERK The City Clerk needs the following to process your appeal:

☐ Attachments you may wish to include  This appeal form completed	Time1:30
Walk-In OR   Mail-In	Location of Hearing: Room 330 City Hall/Courthouse
Address Being Appealed:	
Number & Street: 1004 Grand Are	_ City: St. Paul State: MV Zip: 55105
Appellant/Applicant: Kristen Gay	Email Kgay @ mpr-org
Phone Numbers: Business 65/-290/235 Residen	
Signature: Stat May	Date: Dec 28, 2011
Name of Owner (if other than Appellant):	
Address (if not Appellant's):	
Phone Numbers: Business Residence	ceCell
What Is Being Appealed and W	Vhy? Attachments Are Acceptable
Vacate Order/Condemnation/ Revocation of Fire C of O	
□ Summary/Vehicle Abatement	
□ Fire C of O Deficiency List	
Fire C of O: Only Egress Windows	
Code Enforcement Correction Notice	
□ Vacant Building Registration	
□ Other	
Matthews or processing and the second of the	



DEPARTMENT OF SAFETY AND INSPECTIONS Fire Inspection Division Ricardo X. Cervantes, Director

SAINT PAUL AAAA

CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

December 15, 2011

EGIDE RUZINDANA/KRISTEN GAY 1012 GRAND AVE ST.PAUL MN 55105

#### FIRE INSPECTION CORRECTION NOTICE

RE:

1004 GRAND AVE

Residential Class: C

#### Dear Property Representative:

Your building was inspected on December 14, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

## A re-inspection will be made on February 15, 2012 at 1:30 PM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

#### **DEFICIENCY LIST**

- 1. Basement MSFC 901.6 Provide required annual maintenance of the fire extinguishers by a qualified person and tag the fire extinguishers with the date of service.
- 2. Basement Main room MSFC 315.2 Provide and maintain orderly storage of materials.-Reduce storage of combustibles such as cardboard by 25 percent.
- 3. Interior MSFC 315.2.5 Fueled equipment, including but not limited to motorcycles, mopeds, lawn-care equipment and portable cooking equipment, shall not be stored,

- operator or repaired within a building. Discontinue storage of propane and charcoal lighter fluid. (Both removed during inspection)
- 4. Properly mount extinguishers MSFC 906.1, MN Stat. 299F.361 Provide approved fire extinguishers in accordance with the following types, sizes and locations.-Provide one minimum 1A10BC fire extinguisher within each apartment unit or a minimum 2A10BC not be more than 50' travel distance from each apartment entrance. They must be permanently mounted between 3 and 5 feet high in readily visible and easily accessible locations
- 5. Rear porch ceiling Second floor SPLC 34.09 (1) b,c, 34.32 (1) b,c Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.
- 6. Throughout Refrigerators NEC 440.13 For cord-connected equipment such as room air conditioners, household refrigerators and freezers, drinking water coolers, and beverage dispensers, a separable connector or an attachment plug and receptacle shall be permitted to serve as the disconnecting means. The appliance must plug directly into a permanent outlet.
- 7. Throughout SPLC 34.10 (6), 34.33 (5) Exterminate and control insects, rodents or other pests. Provide documentation of extermination.-Provide documentation of licensed pest control treatment for mice.
- 8. Unit 1 South room MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.
- 9. Unit 2 Front door MSFC MSFC 1003.3.1.8 The maximum number of locks on unit doors is two. Remove all locks in excess of two.
- 10. Unit 2 Rear hallway SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner. Patch the holes and/or cracks in the ceiling.
- 11. Unit 2 Rear hallway MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.-

Unit 1- North bedroom
22 h x 22.5 w Glazed 6.9 sq ft
Unit 1 - South bedroom
21.5 h x 24 w Glazed 7.1 sq ft
Unit 2 - North bedroom
21.5 h x 22.5 w Glazed 6.9 sq ft

Unit 3 - North bedroom 22 h x 22.5 w Glazed 6.9 sq ft Unit 4 - South bedroom 22.5 h x 32 w Glazed 11.3 sq ft

- 12. Unit 3 Bathroom SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls in an approved manner.-Patch the holes and/or cracks in the walls.
- 13. Unit 4 Rear hallway SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner. Patch the holes and/or cracks in the ceiling.
- 14. Unit 4 South bedroom SPLC 34.09 (3), 34.32 (3) Repair and maintain the window in good condition.-Repair window so it is easily openable.
- 15. MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- 16. UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work may require a permit(s). Call DSI at (651) 266-8989.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: rick.gavin@ci.stpaul.mn.us or call me at 651-266-8994. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Rick Gavin Fire Inspector