

□ Other

# **APPLICATION FOR APPEAL**

## Saint Paul City Clerk

Revised 8/20/2010


RECEIVED

OCT 25 2010

CITY CLERK

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

The City Clerk needs the following to pr	ocess your appeal:	YOUR HEARING Date and Time:
\$25 filing fee payable to the City of	Saint Paul	
(if cash: receipt number)		Tuesday, NOV. 3
Copy of the City-issued orders or let	tter which	
are being appealed		Time1:30
Attachments you may wish to include	de	Location of Hearing:
This appeal form completed		Room 330 City Hall/Courthouse
Address Being Appeal		
		T PAVL State: MV Zip: 55/14
		ail MCKMENSKY Q YAHOO-COM
Phone Numbers: Business 65/-246-	Residence	Cell
Signature: Malo Cineral		Date: <u>/ 6//2//0</u>
Name of Owner (if other than Appellant):		
Address (if not Appellant's): 2343.	SHAN DRIVE,	MENDOTA HRIGHTS
Phone Numbers: Business	Residence	Cell
What Is Being appealed and why? Attachments Are Acceptable		
Vacate Order/Condemnation/ Revocation of Fire C of O		
□ Summary/Vehicle Abatement		
□ Fire C of O Deficiency List		1.
☐ Fire C of O: Only Egress Windows		
Code Enforcement Correction Notice	PROBLEM WIT	+ THEDIRECTION OF SWING
	of Doxes	
□ Other		
□ Other		



STREET LEVEL FLOOR PLAN SCALE: 1/16"=1'-0"



#### CITY OF SAINT PAUL

Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Telephone: 651-266-8989 Saint Paul, MN 55101-1806

Fax: 651-266-8951

September 23, 2010

Mark Cemensky 2343 Swan Dr Mendota Heights MN 55120-1424

### CORRECTION NOTICE - RE-INSPECTION COMPLAINT

RE:

2418 UNIVERSITY AVE W

Ref. # 29405

Dear Property Representative:

A re-inspection was made on your building on September 20, 2010, in response to a referral. You are hereby notified that the following deficiencies must be corrected immediately. A reinspection will be made on or after October 20, 2010.

Failure to comply may result in a criminal citation or the revocation of the Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

#### DEFICIENCY LIST

- 1. Both levels - 280 Lounge - MSFC 906.1, MN Stat. 299F.361 - Provide approved fire extinguishers in accordance with the following types, sizes and locations.
- Rear Exit 280 Lounge & Grocery MSFC 1010.1, 1003.3.1.2 Exit doors must swing in the direction of travel. Change the swing of the door.-CODE CHANGE
- Rear Exit 280 Lounge & Grocery MSFC 1010.1, 1003.3.1.9 Provide and maintain approved panic release hardware on all exit doors.

For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

If you have any questions, email me at diane.mccabe@ci.stpaul.mn.us or call me at 651-266-8947 between 7:30 a.m - 9:00 a.m.

Please help to make Saint Paul a safer city in which to live and work.

Sincerely,

Diane McCabe Fire Inspector