

APPLICATION FOR APPEAL

Saint Paul City Clerk

Total Distriction of the Control of

000 93 2010

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

Community of the Commun	•
Wily	<u> ARRK</u>
The City Clerk needs the following to process your appeal:	YOUR HEARING Date and Time:
\$25 filing fee payable to the City of Saint Paul	1:21:21:1
(if cash: receipt number)	Tuesday, 13/3/10
Copy of the City-issued orders or letter which	
are being appealed	Time
□ /Attachments you may wish to include	Location of Hearing:
This appeal form completed	Room 330 City Hall/Courthouse
	mailed 12/13/10
Address Being Appealed:	
N 2142 (110111601) a. 6	FRANK MALTERING

Number & Street: <u>2192</u>	WAUKON City:	51 PAUL State: MA	Zip: 55 //9
Appellant/Applicant: MARK /	ANDERSON I	Email MDHKAN) G	AOL. CON
Phone Numbers: Business 612 41	48803 Residence <u>65</u>	1 450048&cell	
Signature: MC G A	Vorende anderson	Date: <u>/2-7</u> -	-10
Name of Owner (if other than Appel	lant): DOPINDA	ANDERSON	
Address (if not Appellant's): <u>269</u>	0 7/ST ST	E IGH m	N 55076
Phone Numbers: Business	Residence <u>65</u>	1-450048Kcell 6/2	-396 6614

What Is Being appealed and why? Attachments Are Acceptable

Vacate Order/Condemnation/ Revocation of Fire C of O	ON DEC 5-2010 I REVIE	wro
Summary/Vehicle Abatement	LETTER FROM TUSPECTO	OR WAYNE
Fire C of O Deficiency List	SAERING - ITEM 10 T	YPEO
Fire C of O: Only Egress Windows	SHOULD BE BEDROOM-	I THOUGT
Code Enforcement Correction Notice	THE & BEDROOM WINDOW	US WERE
Vacant Building Registration	OK. WINDOWS WE	REPLACED
Other	5 YEARS AGO THE F	ULL PAINS
Other	CAN BEREMOURD IN	SECONDS
Other	AS NOTED ON REPORT	
	THANK YOU	Revised 8/20/2010

DEPARTMENT OF SAFETY AND INSPECTIONS Fire Inspection Division Ricardo X. Cervantes, Director



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

November 12, 2010

DORINDA ANDERSON 2690 71ST ST E INVER GROVE HGTS MN 55076-2432

FIRE INSPECTION CORRECTION NOTICE

RE:

2142 WAUKON AVE

Ref. #112413

Residential Class: C

Dear Property Representative:

Your building was inspected on November 9, 2010 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on December 29, 2010 at 1:30pm.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

1. Basement - Bathroom - SPLC 34.11(4), 34.34(1) SPC 4715.0200A - Provide an adequate water supply to all water closets, sinks, showers and tubs.-The water supply to the basement bathroom sink is inadequate. Provide an adequate water supply to the basement bathroom sink.

- 2. Basement Dryer Vent UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work may require a permit(s). Call DSI at (651) 266-8989. The flexible metal dryer vent was replaced within the last week. Obtain the required warm air permit and contact warm air inspector, Gary Reinsberg 651-266-9064, for final inspection.
- 3. Basement Porch SPLC 34.12 (2), 34.35 (1) Repair and maintain all required and supplied equipment in an operative and safe condition.-Replace the missing handle on the sliding patio door.
- 4. Basement and Main Floor Globe Covers MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.-replace the missing globe covers on the kitchen light fixture and all basement ceiling florescent light fixtures.
- 5. Basement and Main Floor MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.-Remove and discontinue the use of the extension cords in the main floor living room and basement porch.
- 6. Garage Ceiling MSFC 703 Provide and maintain fire rated floor and/or ceiling construction with approved materials and methods. The minimum rating must be: 1-hour.-Seal the holes/penetrations in the ceiling in the tuck-under garage with approved 1-hour rated materials.
- 7. Garage Fire Door MSFC 703 The fire door must not be obstructed or impaired from its proper operation at any time.-Install the required automatic door closure on the door between the basement and the tuck-under garage.
- 8. Main Floor Bathroom SPLC 34.10 (4), 34.33 (3) Provide a bathroom floor impervious to water.-Caulk around the bathtub to ensure water tightness.
- 9. Main Floor Bathroom SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 415.0220 Repair or replace and maintain the plumbing fixture to an operational condition.-Repair/replace the missing/inoperable sink stopper.

10. Main Floor - Bathroom - MSFC1026.1 - Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651) - 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.

Main Floor Northeast Bedroom (Double-hung)

21h x 35w - Openable 48h x 35w - Glazed

Main Floor Southeast Bedroom (Double-hung)

21h x 24w - Openable 48h x 23w - Glazed

Main Floor Southwest Bedroom (Double-hung)

21h x 32w - Openable 48h x 30w - Glazed

Note: These windows are equipped with an option to slide two clips inward and the window rotates inward to a horizontal plane. With both windows in this position the openable height is approximately 40 inches in height.

11. SPLC 34.11 (6), 34.34 (3) - Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.-New furnace installed by licensed contractor under permit is accepted in lieu of the existing fuel burning equipment safety test report. Contact warm air inspector, Gary Reinsberg 651-266-9064, and mechanical inspector Maureen Hanson 651-266-9043, for final inspection of the furnace.

For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: wayne.spiering@ci.stpaul.mn.us or call me at 651-266-8993 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Wayne Spiering Fire Inspector