

The City Clerk needs the following to process your appeal:

APPLICATION FOR APPEAL

RECEIVED

FEB 0 4 2011

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

Revised 8/20/2010

YOUR HEARING Date and Time:

CITY CLERK

\$25 filing fee payable to the City of S (if cash: receipt number)	Saint Paul	Tuesday, Feb. 15, 2011 Time_1:30 p.m.
Copy of the City-issued orders or let	tter which	3,
are being appealed		Time_\.30 p.11
☐ Attachments you may wish to include	de	Location of Hearing:
This appeal form completed		Room 330 City Hall/Courthouse
Address Being Appeal	led:	mailed 2-4-11 *Couled 2-4-11
Number & Street: 2172 Rea	rney Ave City: St	Paul State: MN Zip: 55119
		ail nouyang \$3@ yahoo.com
		778-8654 Cell 651-442-1280
Signature: Thischue	non of	Date: 2-2-11
Name of Owner (if other than Appellant):		
Address (if not Appellant's): 3282	Largenteu	or Ave E. Maple 2000 5510
Phone Numbers: Business	Residence	Cell
What Is Being appeale	d and why?	Attachments Are Acceptable
□ Vacate Order/Condemnation/ Revocation of Fire C of O		
□ Summary/Vehicle Abatement		
Fire C of O Deficiency List	See these item	son attachment: 5,6,8
Fire C of O: Only Egress Windows	See Hems: 7	
□ Code Enforcement Correction Notice		
□ Vacant Building Registration		AND
		2/1/40/2002 100 100
a Oulti	re-inspection on	3/1/11@1:00fm is too soon, need to complete these above items
□ Other	good weather	To complete these above items
□ Other	V	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

January 28, 2011

NHIACHUE NOU YANG 2282 LARPENTEUR AVE E ST PAUL MN 55109-4912

FIRE INSPECTION CORRECTION NOTICE

RE:

2172 REANEY AVE

Ref. #115061

Residential Class: C

Dear Property Representative:

Your building was inspected on January 27, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on March 1, 2011 at 1:00pm.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. Basement Furnace and Water Heater UMC 1346.703 Provide 30 inches clearance around all mechanical equipment.
- 2. Basement Laundry Room NEC 440.13 For cord-connected equipment such as room air conditioners, household refrigerators and freezers, drinking water coolers, and beverage dispensers, a separable connector or an attachment plug and receptacle shall be permitted to serve as the disconnecting means. The appliance must plug directly into a permanent outlet.-The freezer is plugged into a power-strip. Power-strips are not an approved source of power for freezers. Plug the freezer directly into a permanent outlet.

An Equal Opportunity Employer

- 3. Basement Water Heater SPC 4715.1800.9, 2210 Provide pressure relief valve for hot water heater piped to within 18 inches of the floor.
- 4. Detached Garage Address Numbers SPLC 71.01 Provide address numbers on building per HN-1 handout.-Provide address numbers on the alley side of the detached garage. Address numbers must be at least 3 inches in height, contrast with the background, and be reflective or illuminated at night.
- 5. Detached Garage Siding, Fascia, and Soffits SPLC 34.08 (5), 34.31 (3) Repair, replace and maintain all exterior surfaces on fences, sheds, garages and other accessory structures free from holes and deterioration. Provide and maintain exterior unprotected surfaces painted or protected from the elements.-Replace all deteriorated, rotted, and/or missing siding on the detached garage. Scrape/paint all exterior surfaces. Maintain exterior surfaces free from flaking/chipped paint. Maintain garage in a good state of repairs.
- 6. Detached Garage SPLC 34.09 (3), 34.32 (3) Repair and maintain the door in good condition.-Replace the damaged service and overhead garage doors.
- 7. Egress Windows Main Floor Southeast and Southwest Bedrooms MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651) 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.

Main Floor Southeast and Southwest Bedrooms (Double-hung)

17h x 27w - Openable 40h x 27w - Glazed

- 8. Exterior North Entrance SPLC 34.09 (2), 34.32(2) Repair or replace the unsafe stairways, porch, decks or railings in an approved manner. This work may require a permit(s). Call DSI at (651) 266-9090.-Repair/replace the deteriorated concrete stoop at the north entrance. Maintain the concrete steps in a good state of repairs.
- 9. Main Floor Bedrooms SPLC 34.09 (3), 34.32 (3) Repair and maintain the window in good condition.-Remove the mold-like substance from the window frames. Maintain the window frames in a good state of repairs.
- 10. Main Floor Bedrooms MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- 11. Main Floor Southwest Bedroom SPLC 34.12 (2), 34.35 (1) Repair and maintain all required and supplied equipment in an operative and safe condition.-The test button on the smoke detector is broken so inspector was unable to test the operation of the smoke detector. Replace the broken smoke detector.

- 12. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 13. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.

For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: wayne.spiering@ci.stpaul.mn.us or call me at 651-266-8993 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Wayne Spiering Fire Inspector

Reference Number 115061