

### **Investigation Report**

### Case

SPFD211024046483	Bever, Thomas	Closed	N/A
Case Number	Lead Investigator	Status	Name
Confidential	Accidental		Careless Disposal Ashes
Confidentiality	Disposition		Fire Cause
10/24/2021	04:40		
Start Date	Start Time	End Date	End Time
Saint Paul Fire Department			Saint Paul Police Department
Primary Fire Department	Secondary Fire	Department	Law Enforcement
		'	
light smoke and flames seen	led to the report of a fire in to n on the A/D corner of the ho n. Command was terminated o	he front porch of th	ne home. Firefighters arrived and found vacuated the structure, extinguished the released.
The fire department was cal light smoke and flames seen	on the A/D corner of the ho	he front porch of th	vacuated the structure, extinguished the
The fire department was cal light smoke and flames seen fire and conducted overhaul	on the A/D corner of the ho	he front porch of th	vacuated the structure, extinguished the

### Fire

Careless Disposal S Ashes	tructural area, other		
Fire Cause Ar	ea of Origin	Equipment Power Source	Equipment Portability
Area of Origin Comments			
Cigarette		Cardboard	
Heat Source		Material Ignited	
Equipment Involved In gnition	Equipment Make	Equipment Model	Equipment Serial Number
Confined to building of origi	n		
Confined to building of origi	n	Fire Spread Avenue	
	n	Fire Spread Avenue	
Fire Spread Material Smoke Spread Material	n		
Fire Spread Material	n		
Fire Spread Material Smoke Spread Material	n		
Fire Spread Material  Smoke Spread Material  Fire Comments	n		NE
Fire Spread Material  Smoke Spread Material  Fire Comments	Relative Humidity (%)	Smoke Spread Avenue	NE Wind Direction
Fire Spread Material  Smoke Spread Material  Fire Comments  eather		Smoke Spread Avenue	

Property Details (1 of 1)

N/A Name			
901 Fuller Avenue		П	
address		Apt/Suite/Roo	m
Saint Paul	Ramsey County	Minnesota	55104
lity	County	State	Postal Code
\$52,200.00	\$10,000.00	\$45,000.00	
Pre Fire Value	Content Loss Value	Structure Lo	ss Value
Property Description			
ea			
Structure	Urban		
Агеа Туре	Area Description	Area Quality	

1 or 2 family dwelling	1	Occupied	
Property Use		Structure Occupa	ncy
	Unknown		Unknown
Alarm Type	Smoke Detector P	Present	Smoke Detector Performance
None	1	Unknown	
Sprinkler Standpipes		Sprinkler Standpi	pes Performance
50	30	2	
Structure Length (Ft) Struc	cture Height (Ft) Structure	Width (Ft) Numb	er Of Stories Number Of Units
Balloon	Type V		StructureMaterial_Wood
Construction Type	Structure Type		Structure Material
Basement	Wood	Pitched	Asphalt
Foundation	Exterior Covering	Roof Type	Roof Material
Nothing remarkable.			
Interior Exam			
The exterior of the home apport less.	peared to have newer siding wi	thin the last 10 years	s. Newer roof within the last few years
Exterior Exam			
larm and Security Services			
larm and Security Services	Unknown		
- -	1	Smoke Detector L	ocations Fire Suppression
None	Unknown		ocations Fire Suppression
None Sprinkler Standpipes	Unknown Smoke Detectors Present		Other Entrances

Electrical Status		Electrical Entrance	
	Natural	Xcel Energy	
Fuel Status	Fuel Type	Fuel Company	
		City of Saint Paul Municipal Water	
Water Status		Water Company	
Telephone Status			
Utility Comments			
Utility Comments			
Utility Comments			
	of 1)		
surance Information (1 c	of 1)		
	of 1)		
surance Information (1 o	of 1)  Claim Number	Policy Number	
surance Information (1 c		Policy Number	
surance Information (1 o Federated Insurance Company		Policy Number  Expiration Date	
surance Information (1 o			
surance Information (1 o Federated Insurance Company	Claim Number		

## Witness Statement (1 of 3)

Prince	Raynette	
Last Name	First Name	Middle Name
Owner		
Туре	Er	nployer
Interviewed Date	Interviewed By	Interviewed By Other
901 Fuller Ave.		
Street 1	St	reet 2
Saint Paul	Minnesota	
City	State	PostalCode
Black or African American	12/13/1974	
Race	Date of Birth	Driver's Liscense Number
- I was home at the time of the fir that the wall was warm and left t - I walked down the stairs and sav to get my cat and cell phone and I yelled for help and my neighbor	he room to call for my son.  If the fire coming from the porexited the structure out of the	- I was in my bedroom and heard loud noises and felt rch. I called for my son to wake him up. I went upstairs e bathroom window on the second floor Charlie "C" side. ut and called 911.

## Witness Statement (2 of 3)

Prince-Espinoza	Damon	Edward
Last Name	First Name	Middle Name
Occupant		
Туре	Empl	oyer
Interviewed Date	Interviewed By	Interviewed By Other
901 Fuller Ave.		
Street 1	Stree	t 2
Saint Paul	Minnesota	
City	State	PostalCode
Black or African American	01/31/1994	
Race	Date of Birth	Driver's Liscense Number
- I was home asleep in the basement help and I came upstairs and saw tha _ I used the coffee pot to carry wate	t the front porch was on fire.	- I heard my mom yelling for ut the fire out.
_ I was smoking earlier on the front palways have. I went to bed and I was		discarded the cigarette in the recycling bin as I nat the house was on fire.
- I went to the kitchen and used the o	offee pot to carry water to th	e fire in an attempt to put the fire out.
- had a hard time breathing and had inhalation.	to be assisted out of the home	e by my mother as I became over taken by smoke

# Witness Statement (3 of 3)

Last Name	First Name	Middle Name
Other		
Туре	Emplo	pyer
Interviewed Date	Interviewed By	Interviewed By Other
Street 1	Street	t 2
Saint Paul	Minnesota	
City	State	PostalCode
White		
Race	Date of Birth	Driver's Liscense Number
- I was home at the time of the help back roof of the house yelling f - I called 9-1-1.	fire I vor help saying that there was a fire i	was asleep in bed and heard someone yelling for - I ran outside and saw my neighbor on the in the front of the house.

#### Conclusion

#### **Case Conclusion**

After examination of the fire scene, observation of fire patterns of both movement and intensity and interviews conducted, it is my opinion the fire began in the A/D corner of the home. The area of origin was the recycling bin that was used to discard smoked cigarettes. The first fuel/material ignited was most likely the cardboard that lined the recycling bin. The ignition source was most likely the improperly discarded smoking material. The oxidant was normal atmospheric air. The action that brought these items together was an improperly discarded cigarette placed in a combustible recycling bin. The classification of fire cause is accidental. This concludes my investigation and report.

Si	gnature			
	Bever, Thomas			
	Lead Investigator	Signature	Date Submitted	

#### **Document Attachment List**

Photo Log