

APPLICATION FOR APPEAL

APR 2 1 2011 CITY CLERK

Saint Paul City Clerk

Revised 8/20/2010

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

The City Clerk needs the following to proces \$25 filing fee payable to the City of Sain (if cash: receipt number)	
Copy of the City-issued orders or letter v	which
are being appealed	The state of the s
Attachments you may wish to include This appeal form completed	Location of Hearing: Room 330 City Hall/Courthouse
2 mis appear form completed	Walkin
Address Being Appealed	
	water City: St. Parl State: MW Zip: 55109
Appellant/Applicant: Charles KN	udser Email mbierbach@yffro.com
Phone Numbers: Business 65/-465-06	0 00 dence 5/-418-00 00 Cell
· ·	Date:
Name of Owner (if other than Appellant):	lay wood Projecties
Address (if not Appellant's):	
Phone Numbers: Business	Residence Cell
What Is Being appealed a	and why? Attachments Are Acceptable
Vacate Order/Condemnation/ Revocation of Fire C of O	
Summary/Vehicle Abatement	
□ Fire C of O Deficiency List	
Fire C of O: Only Egress Windows	
Code Enforcement Correction Notice	
Vacant Building Registration	11 000
Other CA	n't Afford toput in new drinew
Other	
Other	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

April 12, 2011

CHARLES KNUDSEN 194 BURKE LANE LITTLE CANADA MN 55117-1007

FIRE INSPECTION CORRECTION NOTICE

RE:

2085 STILLWATER AVE

Ref. #104096

Residential Class: C

Dear Property Representative:

Your building was inspected on April 8, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on May 13, 2011 at 1:30pm.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional re-inspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. Basement Dryer NEC 440.13 For cord-connected equipment such as room air conditioners, household refrigerators and freezers, drinking water coolers, and beverage dispensers, a separable connector or an attachment plug and receptacle shall be permitted to serve as the disconnecting means. The appliance must plug directly into a permanent outlet.-Remove and discontinue the use of the extension cord used to supply power to the gas dryer. Dryers must be plugged directly into a permanently grounded outlet. Any newly installed electrical wiring/outlets must be done by licensed contractor under permit.
- 2. Basement Stairway SPLC 34.10 (3) 34.33(2) Provide an approved guardrail. Intermediate balustrades must not be more than 4 inches apart. Intermediate rails must be provided if the height of the platform is more than 30 inches.
- Basement Water Heater SPC 4715.1800.9, 2210 Provide pressure relief valve for hot water heater piped to within 18 inches of the floor.

An Equal Opportunity Employer

- 4. Exterior Driveway SPLC 34.08 (7) All parking spaces shall be paved with asphalt, concrete, or durable dustless surfacing. Before any existing spaces may be paved, site plan approval must be obtained as specified in the St. Paul Zoning Code. Contact DSI Zoning at 651-266-9090.- Replace the deteriorated asphalt driveway.
- 5. Exterior MSFC 605.1 Repair or replace damaged electrical fixtures.-Replace the weather-proof cover on the exterior outlet on the garage.
- Garage MSFC 605.1 Remove unapproved exposed wiring and install in accordance with the electrical code. This work may require a permit(s). Call DSI at (651) 266-9090.
- 7. Unit 1 Bathroom SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner.
- 8. Unit 1 Hallway MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.-Replace the inoperable hard-wired smoke detector in the hallway.
- 9. Unit 1 Kitchen SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 4715.0200.C Provide an approved number and type of plumbing fixtures.-Repair/replace the broken kitchen sink faucet.
- 10. Unit 1 West Entry Door SPLC 34.09 (3) i Provide and maintain an approved one-inch throw single cylinder deadbolt lock.-Provide the required deadbolt lock on the west entry door on unit 1.
- 11. Unit 2 Bedroom MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this
 office.

For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: wayne.spiering@ci.stpaul.mn.us or call me at 651-266-8993 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Wayne Spiering Fire Inspector

Reference Number 104096

2195 Mohawk Avenue - Google Maps Address 2195 Mohawk Avenue

Address is approximate





neighor to West Dupley

2082 Stillwater Avenue - Google Maps Address 2082 Stillwater Avenue

Address is approximate















