

CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-9124

 Web:
 www.stpaul.gov/dsi

Code Compliance Report

March 17, 2011

RAMSEY COUNTY - AGENT FOR STATE OF MN TAX FORFEIT P O BOX 64097 90 PLATO BLVD W

Re: 922 Westminster St File#: 09 078913 VB2

Dear Property Owner:

The following is the Code Compliance report you requested on March 02, 2011.

Please be advised that this report is accurate and correct as of the date March 17, 2011. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from March 17, 2011. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected:

BUILDING Inspector: Jim Seeger Phone: 651-266-9046

- Tuck Point interior/exterior of foundation as necessary.
- Dry out basement and eliminate source of moisture.
- Remove mold, mildew and moldy or water damaged materials.
- Install handrails (34 inches 38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment.
- Strap or support top of stair stringers for structural stability.
- Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary.
- Provide complete storms and screens, in good repair for all door and window openings.
- Provide functional hardware at all doors and windows
- Exit doors shall be capable of being opened from the inside, easily and without the use of a key. Remove all surface bolts.
- Repair or replace damaged doors and frames as necessary, including storm doors.
- Weather seal exterior doors, threshold and weather-stripping.
- Install floor covering in bathroom and kitchen that is impervious to water.
- Repair walls, ceiling and floors throughout, as necessary.

March 17, 2011

Page 2

BUILDING Inspector: Jim Seeger Phone: 651-266-9046

- Install Smoke Detectors/Carbon Monoxide Detectors per MN Co Conservation Code and the MN Dept. of Labor and Industry.
- Provide major clean-up of premises.
- Repair siding, soffit, fascia, trim, etc. as necessary.
- Provide proper drainage around house to direct water away from foundation of house.
- Install downspouts and a complete gutter system.
- Install rain leaders to direct drainage away from foundation.
- Provide ground cover capable of controlling sediment and erosion.
- Review all applicable codes & policies when replacing windows including egress windows for sleeping rooms.
- Openings in stair risers must be less than 4 inches.
- Replace front retaining wall.
- Replace all siding on front porch.
- Replace all broken, decayed and missing siding and trim.
- Re-level rear entry roof.
- Install handrail at front steps at street.
- Remove carpet from basement.
- Remove all wall covering and all ceiling covering from basement.
- Install tempered glass in rear stairway windows.
- Install steps to code at front door.
- Insure risers to code on basement stairs.
- Install guardrail at top of second floor stairs minimum 36 inch height.
- A building permit is required to correct the above deficiencies.

ELECTRICAL Inspector: Jamie McNamara Phone: 651-266-9037

- Provide a complete circuit directory at service panel indicating location and use of all circuits
- verify/install a separate 20 ampere laundry circuit and a separate 20 ampere kitchen appliance circuit
- Properly strap cables and conduits in basement/ service conduit on the exterior of the house.
- Ground bathroom light in basement bathroom
- Install globe-type enclosed light fixture on all closet lights
- Repair or Replace all broken, missing or loose light fixtures, switches and outlets, covers and plates
- Check all outlets for proper polarity and verify ground on 3-prong outlets
- Remove any 3-wire ungrounded outlets and replace with 2-wire or ground 3-wire to code
- Install hard-wired, battery backup smoke detector per bulletin 80-1 and other smoke detectors as required by the IRC. Also, Install carbon monoxide detector(s) within 10 feet of all bedrooms

March 17, 2011

Page 3

ELECTRICAL Inspector: Jamie McNamara Phone: 651-266-9037

- Replace all painted-over receptacles.
- In basement install 30 amp breaker on number 10 wire.
- If room in basement remains finished rewire rooms to code.
- Second floor east room install 3rd receptacle.
- Count service and 3 circuits on permit.
- All added receptacles must be grounded, tamper-resistant and be on an Arc-Fault Circuit Interrupter-protected circuit.
- Any open walls or walls that are opened as part of this project must be wired to the standards of the current NEC.
- All buildings on the property must meet the St. Paul Property Maintenance Code (Bulletin 80-1).
- All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

PLUMBING Inspector: Denny Watters Phone: 651-266-9051

- Basement Water Heater Vent must be in chimney liner (IFGC 501.12)
- Basement Water Heater not fired or in service (MPC 2180)
- Basement Water Meter meter is missing.
- Basement Gas Piping run dryer vent to code (IFGC 613.1 IMC 604.1)
- Basement Soil and Waste Piping no front sewer clean out (MPC 1000)
- Basement Soil and Waste Piping no soil stack base clean out
- Basement Soil and Waste Piping unplugged or open piping; back pitched piping (MPC 1000)
- Basement Toilet Facilities fixture is broken or parts missing (MPC 0200 0.)
- Basement Toilet Facilities unvented (MPC 0200. E)
- Basement Toilet Facilities waste incorrect (MPC 2300)
- Basement Toilet Facilities water piping incorrect (MPC 0200 P.)
- Basement Tub and Shower provide anti-scald valve (MPC 1380. Subp. 5)
- First Floor Gas Piping range gas shut off; connector or piping incorrect (IFGC 411 1.3.3) cap or hook-up
- First Floor Sink faucet parts missing (MPC 0200.P.)
- First Floor Sink waste incorrect (MPC 2300)
- Second Floor Lavatory faucet parts missing (MPC 0200.P.)
- Second Floor Tub and Shower Provide access (MPC 0900)
- Second Floor Tub and Shower replace waste and overflow (MPC 1240)
- Exterior Lawn Hydrants Requires backflow assembly or device (MPC 2000)
- Obtain plumbing permits prior to commencement of work.

March 17, 2011

Page 4

HEATING Inspector: Maureen Hanson Phone: 651-266-9043

- Install approved lever handle manual building shutoff gas valve in a ready accessible location ahead of the first branch tee.
- Clean and Orsat test boiler burner. Check all controls for proper operation. Provide documentation from a licensed contractor that the heating unit is safe.
- Install approved metal chimney liner.
- Replace boiler flue venting if excessive corrosion is present and provide proper pitch for all gas appliances.
- Connect boiler and water heater venting into chimney liner.
- Provide adequate clearance from flue vent pipe on boiler to combustible materials or provide approved shielding according to code.
- Vent clothes dryer to code.
- Provide support for gas lines to code. Plug, cap and/or remove all disconnected gas lines.
- Provide a window in the bathrooms with an aggregate glazing area of not less than 3 square feet, one-half of which must be openable or provide exhaust system vented to outside. A mechanical ventilation permit is required if an exhaust system is installed.
- Provide heat in every habitable room and bathrooms.
- Pipe boiler pressure relief valve discharge to within 18 inches of the floor.
- Repair or replace fin tube radiation and covers as needed.
- Install shut off valves (isolation) on both the supply and return piping for boiler.
- Repair or replace first floor thermostat.
- Mechanical GAS and/or HYDRONIC permit(s) is/are required for the above work.

ZONING

- 1. This property is in a (n) RT1 zoning district.
- 2. This property was inspected as a Single Family Dwelling.

Notes:

- See attachment for permit requirements and appeals procedure.
- Roof, sidewalks, etc. snow covered and could not be inspected. All must meet appropriate codes when completed.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected in accordance with the Minimum Housing Standards of the St. Paul Legislative Code (Chapter 34) and all required permits must receive final approval within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

March 17, 2011

Page 5

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Jim Seeger between 7:30 - 9:00 AM at 651-266-9046 or leave a voice mail message.

Sincerely,

James L. Seeger Code Compliance Officer Department of Safety and Inspections City of Saint Paul 375 Jackson Street, Suite 220 Saint Paul MN 55101

Phone: 651-266-9046

Email: james.seeger@ci.stpaul.mn.us

JLS:ml Attachments