

# APPLICATION FOR APPEAL

RECEIVED
JUN 2 9 2011

CITY CLERK

## Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

The	City Clerk needs the following to process your appeal:	YOUR HEARING Date and Time:
w/	\$25 filing fee payable to the City of Saint Paul (if cash: receipt number	Tuesday, July 12, 2011
M	Copy of the City-issued orders or letter which	Time
	are being appealed	
	Attachments you may wish to include	Location of Hearing:
	This appeal form completed	Room 330 City Hall/Courthouse

walkin

Address	Being	Appeale	ed:
---------	-------	---------	-----

Number & Street: 1015 Byrns	Avenuecity: St. Paul State: MN Zip: 55106			
Appellant/Applicant: Martin R.	Russo Email Martin, russo ausbank com			
Phone Numbers: Business 60-973-0	303 Residence 612-518-6080 Cell 612-518-6080			
Signature:	Date: June 28, 2011			
Name of Owner (if other than Appellant):	N/a			
Address (if not Appellant's):	<u>a</u>			
Phone Numbers: Business \( \sqrt{\sqrt{a}}	Residence <u> </u>			
What Is Being appealed and why? Attachments Are Acceptable				
Vacate Order/Condemnation/ Revocation of Fire C of O				
☐ Summary/Vehicle Abatement				
▼ Fire C of O Deficiency List	see a Hacked			
☐ Fire C of O: Only Egress Windows	The windows are nearly at			
□ Code Enforcement Correction Notice	require wents - exceed some.			
□ Vacant Building Registration	The drivenay 15 class 5 grand			
□ Other	and so is the street it indersects-			
□ Other	Suburban Avenue. Thanks for			
□ Other	your consideration! Marty			



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

June 21, 2011

MARTIN R RUSSO JANE E RUSSO 1019 BURNS AVE ST PAUL MN 55106-6718

#### FIRE INSPECTION CORRECTION NOTICE

RE: 1015 BURNS AVE

Ref. #113246

Residential Class: C

### Dear Property Representative:

Your building was inspected on June 15, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

#### A re-inspection will be made on July 27, 2011 at 1:00pm.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

#### **DEFICIENCY LIST**

1. Basement - Wash Machine - SPLC 33.03 (b) - No person shall install, remove, alter, repair, or replace or cause to be installed, removed, altered, repaired or replaced any plumbing, gas or drainage piping work, standpipe system, sprinkler system, or any fixture or water heating or treating equipment in a building or premises without first obtaining a permit to do such work from the building official.-The wash machine discharges into a tub basin which drains into a floor drain. This plumbing is not installed in accordance with the plumbing code. Remove the incorrectly installed plumbing and install according to code. This work must be done by licensed plumbing contractor under permit.

- 2. Basement and Upper Floor Stairway SPLC 34.10 (3) 34.33(2) Provide an approved guardrail. Intermediate balustrades must not be more than 4 inches apart. Intermediate rails must be provided if the height of the platform is more than 30 inches.-Install the required guardrail on the basement and upper floor stairway.
- 3. Basement and Upper Floor Stairway SPLC 34.10 (3), 34.33(2) Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.-Install the required handrail on the basement and upper floor stairway.
- Egress Windows MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651) 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.

Main Floor Southwest Bedroom (Double-hung) 19.5h x 27w - Openable 41h x 25w - Glazed

Upper Floor Bedroom (Double-hung) 22h x 22w - Openable 49h x 20w – Glazed

- Appeal 5.
  - concrete, or durable dustless surfacing. Before any existing spaces may be paved, site plan approval must be obtained as specified in the St. Paul Zoning Code. Contact DSI Zoning at 651-266-9090.

Exterior - Driveway - SPLC 34.08 (7) - All parking spaces shall be paved with asphalt,

- 6. Exterior East Deck SPLC 34.09 (2), 34.32(2) Repair or replace the unsafe stairways, porch, decks or railings in an approved manner.-Replace the deteriorated deck.
- 7. Exterior East Deck SPLC 34.09 (2) 34.32 (2) Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.
- 8. Garage Address SPLC 71.01 Provide address numbers on building per HN-1 handout.-Provide address numbers on the alley side of the detached garage. The address numbers shall be of sufficient size to clearly read them from the alley. The address numbers shall contrast with their background and be reflective or illuminated at night.
- 9. Garage Provide Access SPLC 34.19 Provide access to the inspector to all areas of the building.-Provide the inspector access to the detached garage.
- 10. Main Floor Bathroom SPLC 34.12 (2), 34.35 (1) Repair and maintain all required and supplied equipment in an operative and safe condition.-Secure the loose toilet paper holder.

- 11. Main Floor Bathroom SPLC 34.14 (3), MPC 4715.200.T Provide and maintain a window or approved ventilation system in all bathrooms.-Repair/replace the inoperable vent fan.
- 12. Main Floor Dining Room SPLC 34.12 (2), 34.35 (1) Repair and maintain all required and supplied equipment in an operative and safe condition.-Replace the missing thermostat cover.
- 13. Main Floor Southeast Entry Door MSFC 1003.3.1.8 The maximum number of locks on unit doors is two. Remove all locks in excess of two.
- 14. Main Floor and Upper Floor Window Locks SPLC 34.09 (3), 34.32 (3) Repair and maintain the window lock.-Replace the missing locks on the windows in the main floor bathroom and dining room and upper floor bedroom.
- 15. Upper Floor Bedroom MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- 16. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 17. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.

For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: wayne.spiering@ci.stpaul.mn.us or call me at 651-266-8993 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Wayne Spiering Fire Inspector

Reference Number 113246