

The City Clerk needs the following to process your appeal:

APPLICATION FOR APPEAL

JUL 08 2011

CITY CLERK

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

\$25 filing fee payable to the City of (if cash: receipt number) Copy of the City-issued orders or leare being appealed Attachments you may wish to include This appeal form completed Walk-In OR Mail-In	etter which	YOUR HEARING Date and Time: Tuesday, 8-2-11 Time 1-30 Location of Hearing: Room 330 City Hall/Courthouse
Address Being Appealed:		
Number & Street: 929 W	TISON City: S	St. Paul State: MN Zip: 55106
Appellant/Applicant: Tra Yan	g and Lee Yangen	nail thias Vaj 64@hstanail.a
Phone Numbers: Business Residence Cell <u>651-592-9328</u>		
		Date: 7-6-11
Name of Owner (if other than Appellant):	
Address (if not Appellant's):		·
Phone Numbers: Business	Residence	Cell
What Is Being Appea Vacate Order/Condemnation/ Revocation of Fire C of O Summary/Vehicle Abatement	led and Why?	Attachments Are Acceptable
☐ Fire C of O Deficiency List	Double-hung wind	ow 1stfloor bedroon openable -
▼ Fire C of O: Only Egress Windows	17.5 inches Ht.	X 31.5 width and Double-hung
□ Code Enforcement Correction Notice	: Window 2ndfl	ood bedroom openable 21"htx27%.
□ Vacant Building Registration		
□ Other		
		Revised 3/7/2011



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

July 1, 2011

TIA YANG LEE YANG 8573 Timberwood Rd Woodbury MN 55125-7611

FIRE INSPECTION CORRECTION NOTICE

RE:

929 WILSON AVE

Ref. #115662

Dear Property Representative:

Your building was inspected on June 28, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on August 29, 2011 at 10:15 am.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. EXTERIOR SPLC 34.09 (3), 34.32 (3) Provide or repair and maintain the window screens.
- 2. EXTERIOR SPLC 34.09 (3), 34.32 (3) Repair and maintain the window frames.-Scrape and paint exterior window frames in a professional manner.
- 3. INTERIOR KITCHEN SPLC 34.10 (7), 34.33 (6) Repair and maintain the floor in an approved manner.-Repair or replace the floor tile.

- 4. INTERIOR MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Upon inspection, double-hung window in first floor bedroom measured 17.5 inches openable height x 31.5 inches openable width. Double-hung window in second floor bedroom measured 21 inches openable height x 27 inches openable width.
- 5. INTERIOR SPLC 34.09 (3), 34.32 (3) Repair and maintain the doors in good condition.-Replace damaged bedroom door.
- 6. INTERIOR SPLC 34.09 (3), 34.32 (3) Repair and maintain the door frames.-Repair interior frames on front and rear doors in a professional manner.
- 7. INTERIOR MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.
- 8. INTERIOR SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls in an approved manner.-Replace damaged bathtub surround, and re-caulk around bathtub. Remove damaged wallpaper in bathroom. Complete interior painting throughout,. All work must be done in a professional manner.
- 9. INTERIOR SPLC 34.10 (7), 34.33 (6) Repair and maintain the floor in an approved manner.-Replace the carpeting in the second floor bedroom.
- 10. INTERIOR SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner.-Replace missing ceiling tiles in second floor bedroom.
- 11. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 12. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.

For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: kelly.booker@ci.stpaul.mn.us or call me at 651-266-8985 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Kelly Booker Fire Inspector

Reference Number 115662