

CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

August 30, 2011

ADAM STROEBEL TERESA STROEBEL 6246 TENNISON WAY INDIANAPOLIS IN 46236-7390

- what has been as testified to done - as testified to done - as testified to - MM - MM 9-13-1/

Revocation of Fire Certificate of Occupancy and Order to Vacate

RE:

1889 MONTANA AVE E

Ref. # 105624

Dear Property Representative:

Your building was determined to be a registered vacant building on August 30, 2011. Since certificates are for the occupancy of buildings, it has become necessary to revoke the Certificate of Occupancy.

Saint Paul Legislative Code provides that no building shall be occupied without a Certificate of Occupancy. In order to re-occupy the building, the following deficiencies (if applicable) must be corrected and a complete Certificate of Occupancy inspection will be required.

#### DEFICIENCY LIST

- 1891 SPLC 34.09 (3), 34.32 (3) Repair and maintain the door in good condition. 1. Storm door
- 1891 MSFC 605.1 Repair or replace damaged electrical fixtures. This work will 2. require a permit(s). Call DSI at (651) 266-9090.-Electrical wiring done without a permit.
- 1891 MSFC1026.1 Provide and maintain an approved escape window from each 3. sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)-266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.-Remove dresser and or furniture from escape window that would prevent All obstructions have escape through escape window. Bedroom eastside been removed.

- 4. 1891 MSFC 605.1 Repair or replace damaged electrical fixtures. This work will require a permit(s). Call DSI at (651) 266-9090.
- 5. 1891 Front Entry Door MSFC 1011.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.-Remove all shoes clothes and other storage that prevent the exitway from being clear. All obstructions have been removed.
- 6. 1891 Garages MSFC 703 Provide and maintain fire rated wall construction with approved materials and methods. This work will require a permit(s). Call DSI at (651) 266-9090. The minimum rating must be: 1 HOUR
- 7. 1889 SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 415.0220 Repair or replace and maintain the plumbing fixture to an operational condition.-Repair or replace and maintain an approved private toilet. Provide approved hardware for toilet. Repair or replace and maintain an approved private tub or shower. This work may require a permit(s). Call LIEP at (651) 266-9090.
- 8. 1889 MN Stat 299F.18 Immediately remove and discontinue excessive accumulation of combustible materials.-Remove gas cans from basement. Can removed at time of inspection.

  Compiled the materials have been removed.
- 9. 1889 MSFC 1003.3.1.8 Remove unapproved locks from the unit doors. The door must be openable from the inside without the use of keys or special knowledge or effort.Remove sliding bolt lock from storm door. What proved locks have been removed.
- 1889 Shower Head SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 415.0220 Repair or replace and maintain the plumbing fixture to an operational condition.-Repair or replace and maintain an shower head. This work may require a permit(s). Call LIEP at (651) 266-9090.
- 11. 1889 and 1891 SPLC SEC 34.09 EXTERIOR STRUCTURE. All other exterior surfaces shall be maintained in a professional state of maintenance and repair. the retaining walls on the west side and on the east side of the building, are in need of repair.
- 12. 1889 and 1891 SPLC 34.09 (2) 34.32 (2) Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.
- 13. 1889 and 1891 UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work may require a permit(s). Call DSI at (651) 266-8989.-There is still a permit open from 2009
- 1889 and 1891 Steps SPLC SEC 34.09 Stairs and steps deemed hazardous by the enforcement officer shall be corrected so as to be in compliance with the Building Code.

- 15. 1889 and 1891 Garages MR, PART 4620.3435 A. To conduct and asbestos project without a permit posted at the worksite.-YOU CANNOT BEGIN YOUR PROJECT BEFORE YOU RECIEVE YOUR PERMIT. Work done on the garages could have produced Asbestos being airborne. Check with the Minnesota Department of Health to verify if there is or was a release of Asbestos released
- 1889 and 1891 Garages MSFC 703 Provide and maintain fire rated floor and/or ceiling construction with approved materials and methods. This work will require a permit(s).
   Call DSI at (651) 266-9090. The minimum rating must be: 1 HOUR
- 17. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 18. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.
- 19. NEC BULLENTIN 0-1 b. HAZARDOUS IMPROPER AND OR ILLEGAL WIRING shall be removed or rewired to the present ELECTRICAL CODE. This will also include other buildings on the property such as garages sheds etc.-The tenant 1891 has rewired electrical fixtures in the hallways and bedrooms and a hard-wired smoke detector.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.


If you have any questions, email me at: james.thomas@ci.stpaul.mn.us or call me at 651-266-8983 between 7:30 - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.


Sincerely,

James Thomas Fire Inspector

Ref. # 105624

# Deficiency list # 1







)xam-

## Info Main City Contact

## 1889 MONTANA AVE E -- Property Information --

PIN	Zoning/Use	HPC District
232922230004	R4 / R-Duplex Legal Non-Conforming-	1
	Vacant Building Category 3	

#### Information disclaimer...

Data Disclaimer.

The City of Saint Paul and its officials, officers, employees or agents does not warrant the accuracy, reliability or timeliness of any information published by this system, and shall not be held liable for any losses caused by reliance on the accuracy, reliability or timeliness of such information. Portions of such information may be incorrect or not current. Any person or entity that relies on any information obtained from this system does so at his or her own risk.

1.13.6					
	Activit		Item #2, #4, #19		
		Descriptio	n Details	Status	7
11 271462 ELC 00 E	1891 MONTANA AVE E		Electrical Permit Type: Electrical Residential Repair/Alter Issued Date: 09/02/2011 Contractor: Web Electric	Active/Issued	
	1889-1891 MONTANA AVE E	Vθ	Estimated Value: \$250.00 Complaint Date: 09/01/2011 Initia: Inspection: 09/01/2011 VB Category 3 - Euplex Next Inspection on or after: 09/15/2011 Inspector: 326	under Review	
			Inspection Results (most recent first):		
			09/02/2011: VB Monitoring (Recheck-Comply By: 09/15/11		
11 270364 RPR 0C B	1889 MONTANA AVE E		09/01/2011: VB Monitoring (Recheck) Building Permit Type: Single Family Divelling Repair Issued Date: 08/31/2011 Contractor: Adam Strober State Valuation: \$500.00	Active/Issued	Hove
11 258499 000 06 PA		PILES OF BRANCHES AT	Activity (most recent first Architectural (R) Review: 08/31,2011: Prolimatary Plan Check 08/31/2011: Approved Parks Summary Abatement Type: Garbage Ruppsh	ālosen.	
11 352610 TAL 00 CS		REAR FO PROPERTY TGW	Entered on: 08/03/2011 Closed on: 08/08/2011 Complaint Date: U7/19/2011 Initial Inspection: 07/25/2011 Closed on: 07/26/2011 Inspector: 356	Resolved	
11 249812 TAL 00 CS	1889 MONTANA AVE E	FGW	Inspection Results (most recent first) 07/25/2011. Grass/Weeds (Abated) Complaint Date: 07/13/2011 Initial Inspection: 07/19/2011 Closed on: 07/20/2011 Inspector: 356	Resolved	

inspection Results (most recent first)







#### Info Main City Contact

### 1889 MONTANA AVE E -- Property Information --

PIN	Zoning/Use	HPC District
232922230004	R4 / R-Duplex Legal Non-Conforming- Vacant Building Category 3	

#### Information disclaimer...

Data Disclaimer: -

The City of Saint Paul and its officials, officers, employees or agents does not warrant the accuracy, reliability or timeliness of any information published by this system, and shall not be held liable for any losses caused by reliance on the accuracy, reliability or timeliness of such information. Portions of such information may be incorrect or not current. Any person or entity that relies on any information obtained from this system does so at his or her own item #6 116

List of Activity...

Number	Address	Description	
--------	---------	-------------	--

D	0	T	а	1	ŀ	ς
-	_	-	-	•		-

Status

11 271462 1891 ELC 00 E MONTANA

Electrical Permit

vb

Active/Issued

Under Review

Active/Issued

Resolved

Resolved

AVE E

11 271104 1889-1891

VAC 00 CS MONTANA

AVE E

Type: Electrical Residential Repair/Alter

Issued Date: 09/02/2011 Contractor: Web Electric

Estimated Value: \$250.00 Complaint Date: 09/01/2011

Initial Inspection: 09/01/2011

VB Category 3 - Duplex

Next Inspection on or after: 09/15/2011

Inspector: 326

Inspection Results (most recent first):

09/02/2011: VB Monitoring (Recheck-Comply By:

09/15/11)

11 270364 1889 RPR 00 B MONTANA AVE E

11 258499

11 249812

09/01/2011: VB Monitoring (Recheck)

Building Permit Type: Single Family Dwelling Repair

Issued Date: 08/31/2011 Contractor: Adam Strobel

State Valuation: \$500.00

Activity (most recent first): Architectural (R) Review: 08/31/2011: Preliminary Plan

Check

08/31/2011: Approved Parks Summary Abatement Type: Garbage Rubbish

Closed

000 00 PA MONTANA AVE E 11 252610 1891 TGW

TAL 00 CS MONTANA

TAL 00 CS MONTANA

1889

AVE E

1889

AVE E

PILES OF BRANCHES AT REAR FO Entered on: 08/03/2011 PROPERTY

Closed on: 08/08/2011

Complaint Date: 07/19/2011 Initial Inspection: 07/25/2011 Closed on: 07/26/2011

Inspector: 356

TGW

Inspection Results (most recent first): 07/25/2011: Grass/Weeds (Abated) Complaint Date: 07/13/2011 Initial Inspection: 07/19/2011 Closed on: 07/20/2011

Inspector: 356

Inspection Results (most recent first):

# Delivery Agreement - Guest Copy Delivery Agreement # 3799097 | HM # 40, 46

CASHIER- Press 'Recall Trans' before scanning each of the barcodes below.
You must scan ALL of the barcodes on this page. If there are additional pages
of barcodes attached to this Delivery Agreement, each barcode on those sheets
must be scanned as well

De very Agreement # 3799097

Page 1 of 1

PICKING LISTS

TO BE DELIVERED 29

1891 Montana Ave E Saint Paul, MN 55119 Setup Date: 04/17/2011 DELIVERY ADDRESS

- TERMS AND CONDITIONS

  1. The delivery charge will be as per the "Delivery Charge Rate Card," plus fuel surcharge if applicable.
- Deliveries are during store operating hours. All efforts will be made to accommodate requested times.
- 3.All loads are taken off the truck and set/dumped (placed) on the driveway unless additional handling charges are paid
- 4. Adequate access and sufficent area is required to dump or unload materials on level grade. If the driver is instructed to unload the material in such a place that is likely to tear up a lawn, crack cement by driving over it, get the truck or material stuck, etc. the delivery service is not responsible and the delivery guest assumes complete responsibilty.
- 5.1 agree that the delivery will be provided by an independently owned delivery service. I agree that all disputes over any damages I may suffer due to this delivery including damaged merchandise or shortages will be resolved through the delivery service and therefore agree to hold Menards and its employees harmless due to such damages.

By purchasing this service and/or accepting product that is delivered, the purchaser agrees to the terms and conditions detailed above.

TOTAL 11328 \$106.20 \$106.20

	DELIVERY SERVICE	
	For Delivery Services Inquiries Please Contact:	ı 1
	Casci Trucking	
	Carlos Casci	
	10737 Knollwood Lane	
_	Woodbury,MN 55129	
	Business Phone:(651)485-1794	
	Cell Phone:(651)487-1794	
	Email:casci1@comcast.net	
	Insured through:	
	Star Insurance Agency	
	2682 East County Rd E	
	White Bear Lake, MN 55110	
	Agent:Cory Brrgman	
	(651)773-5393	
	c-brrgman@starins.com	

\$49.95	Mileage Charge Zone A Trip 1 Delivery Date: 04/18/2011 Delivery Time: 12 PM - 6 PM
Included	sheets 4x12 rock Quantity: 12 Placement: Garage Opening Only Comments: Guest will direct
DELIVERY CHARGES	DELIVERY PLACEMENT AND SPECIAL INSTRUCTIONS

PICKING LIST - GUEST COPY

STORE # 3022 OAKD 3205 Ha !ley Avenue North Oakdale, MN 55128

Q

PHONE: (651) 777-0048 FAX: (651) 779-6011

CASHIER - PRESS RECALL TRANS AND SCAN BARCODE ==>

**OAKD 11328** 

CASHIER:

PLEASE STAPLE

RECEIPT HERE.

PAGE 1 OF 1

SOLD BY: ROB A. DATE: 04/17/11

**GUEST NAME - ADDRESS - PHONE** 

Trader, Amanda 1891 Montana Ave E Saint Paul, MN 55119

(651) 735-9297

QUANTI	TY	DESCRIPTION	٧						SKU NUMBER	UNIT PRICE EX	TENDED PRICE
		5/8"4X12		FC	TYPE >	TPRD	EDG-104	LB	131-1303	8.85	106.20

TO AVOID PRODUCT NOT BEING AVAILABLE ON A LATER DATE PLEASE PICK UP ALL MERCHANDISE TODAY. THANK YOU.

This is a quote valid today. Upon payment this quote becomes a yard picking list subject to the terms and conditions below. Quantities listed above may exceed quantities available for immediate pick-up. Product is not held for a specific guest, but instead is available to the buying public on a first come, first serve basis. Please pickup all purchases made on this picking list immediately. Failure to pick up products on this picking list today will result in additional charge to you if, on the day of pick up, the retail price of the products are higher than on the day purchased. Menards liability to you is limited to refunding your original purchase price for any product not picked up.

Guest Instructions:

1. Take this picking list to a cashier to pay for the merchandise.

2. Enter the outside yard to pick up your merchandise. (All vehicles are subject to inspection.)

Load your merchandise. (Menards Team Members will gladly help you load your materials but cannot be held liable for damage to your vehicle.)

When exiting the yard, present this list to the Gate Guard. (The Gate Guard will record the items you are taking with you.)

5. Sign the Gate Guard's signature pad verifying you've received the merchandise.

Our insurance does not allow us to tie down or secure your load, trunk lid, etc. For your convenience, we supply twine, but you will have to decide whether or not your load is secure and if the twine supplied is strong enough. If you do not believe the twine will suffice, stronger material can be purchased inside the store.

READ THE TERMS AND CONDITIONS CAREFULLY. All returns are subject to Menards' posted return policy. In consideration for Menards low prices you agree that if any merchandise purchased by you is defective, Menards will agree to exchange the merchandise or refund the purchase price based on the form of original payment. You agree that there shall be no other remedy available to you. If there is a warranty provided by the manufacturer, that warranty shall govern your rights and Menards shall be selling the product "AS IS." Oral statements do not constitute warranties, and are not a part of this contract. The guest agrees to inspect all merchandise prior to installing or using it. UNDER NO CIRCUMSTANCES SHALL MENARDS BE LIABLE FOR ANY SPECIAL, INCIDENTAL, OR CONSEQUENTIAL DAMAGES.

MENARDS MAKES NO WARRANTIES, EXPRESS OR IMPLIED, AS TO MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE OF THE MERCHANDISE. Any controversy or claim arising out of or relating to this contract, or the breach thereof, shall be settled by arbitration administered by the American Arbitration Association under its applicable Consumer or Commercial Arbitration Rules, and judgments on the award rendered by the arbitrator(s) may be entered in any court having jurisdiction thereof. The guest agrees to these terms and conditions through purchase of merchandise contained on this document.

THIS IS NOT A RECEIPT

GATE GUARD - SCAN HERE ==>



106.20

PRE-TAX TOTAL:

6060 46th Street North Oakdale, Mn 55128 (651) 276-7034

John P. Culliton Fed ID # 84-1695616 **INVOICE** 

	<del>,</del>			
<u>Builder</u>	Sheet Count		<u>Extras</u>	<u>Price</u>
Amamda	Truder			0
•	Montana Ave	lock a	Fine tal	pe Gar
1889			# 050	) 00
			H do	only OFC. "Lobon only
,001	montana	7	2000	whom and
1091	montana Bak due 35000 In cash 350.8	<u>≟</u>	550	Der Giry
$\sim$	350.00	PC	0.00	00
to	in cash	( total	. 600	
			5-6-11	gel Culto
			_	
	P1 4-19-11 PRC			
	M 4-10-1191			
	Ad ,			
	In Las"			

Date: 4-19-11

By: John V-Culto

# Casci Trucking DELIVERY PACKING SLIP

Page 1 of 1





SHIP TO: Trader, Amanda 1891 Montana Ave E Saint Paul, MN 55119 / FW

DELIVERY DATE: 04/18/2011
DELIVERY TIME: 12PM - 6PM
DELIVERY AGREEMENT # 3799097
TRUCK TYPE: Semi-forklift tractor trailer

LOAD BUILT BY: rec

THE MERCHANDISE LISTED BELOW IS INCLUDED ON THIS DELIVERY LOAD

Picking List# 11328

28

**QTY** 12 of 12 DESCRIPTION

5/8"4X12 GYPS FC TYPE X TPRD EDG-104 LB

SKU

1311303

TOTAL AMOUNT: \$106.20

IF YOU HAVE ANY CONCERNS WITH THE QUANTITIES RECEIVED OR THE SERVICE RECEIVED DURING THIS DELIVERY, PLEASE

CONTACT: Carlos Casci AT (651)485-1704

Insurance Co: Insured By: Star Insurance Agancy

Cory Brrgman

Phone:

(651)773-5393

Email:

c-brrgman@starins.com

Submittal Sheet 09250 tm #16,

# Sheetrock<sup>®</sup> Gypsum Panels



## Regular and Firecode Cores

#### Quality interior wall and ceiling panels at low cost

- Fire-resistant dry construction
- Quick installation and decoration
- Score and snap easily
- Resist cracking and warping
- Specialized types for all systems

#### Description

SEETROCK® brand gypsum panels are factory-fabricated, composed of a fire-resistant gypsum core encased in heavy natural-finish face paper and strong liner paper on the back side. The face paper is folded around the long edges to reinforce and protect the core, and the ends are square-cut and finished smooth. Long edges of panels are tapered, allowing joints to be reinforced and concealed with a USG joint treatment system.

SHEETROCK gypsum panels are available with three core types for standard construction uses.

#### Regular core

With a regular core, available in three thicknesses for specific purposes.

1/2" Panels Recommended for single-layer application in residential construction.

3/8" Panels Lightweight, applied principally in the double-wall system over wood framing, and in repair and remodeling.
1/4" Panels Lightweight, low-cost, utility gypsum panels, used as base layer for improving sound control in double-layer steel and wood-stud partitions, and for use over old wall and ceiling surfaces. Also for forming curved surfaces with short radii.

#### FIRECODE® Core

5/8" Type X Gypsum Panels Provide additional fire resistance over regular panels.

#### FIRECODE C Core

1/2" and 5/8" Type C Gypsum Panels Specially formulated mineral core provides fire resistance superior to that offered by FIRECODE Core gypsum panels.

#### Limitations

- 1. Avoid exposure to sustained temperatures exceeding 125 °F (52 °C).
- Avoid exposure to excessive, repetitive or continuous moisture before, during and after installation. Eliminate sources of moisture immediately.
- Non-loadbearing.
- 4. Fire-resistance ratings achieved when assembled in accordance with UL designs.

#### Finishing and Decorating

For high-quality finishing results, USG recommends the following products:

- SEETROCK® ready-mixed joint compounds
- Sheetrock® setting-type joint compounds
- SHEETROCK® joint tape
- Sheetrock® First Coat primer
- Sheetrock™ paper-faced metal bead and trim
- SHEETROCK® TUFF-HIDE™ primer-surfacer

Painting products and systems should be used which comply with recommendations and requirements in Appendixes of ASTM C840. For priming and decorating with paint, texture or wall covering, follow manufacturer's directions for materials used.

All surfaces, including applied joint compound, must be thoroughly dry, dust-free, and not glossy. Prime with SHEETROCK First Coat primer or with an undiluted, interior latex flat paint with high-solids content. Allow to dry before decorating.

To improve fastener concealment, where gypsum panel walls and ceilings will be subjected to severe artificial or natural side lighting and be decorated with a gloss paint (egg shell, semi-gloss or gloss), the gypsum panel



surface should be skim coated with joint compound. This equalizes suction and texture differences between the drywall face paper and the finished joint compound before painting. As an alternative to skim coating, or when a Level 5 finish is required, use SHEETROCK TUFF HIDE\*\* primer-surfacer.

#### **Product Data**

Size: 1/4", 3/8", 1/2" and 5/8" x 48" wide; 8'-14' long. 1/2" and 5/8" also available in 54" wide.

Weight: 1/4" - 1.2 lbs/sf; 3/8" - 1.4 lbs/sf; 1/2" - 1.6 lbs/sf; 5/8" - 2.2 lbs/sf.

Thermal Resistance "R": For 1/2" thickness: 0.45 °F x ft. 2 x h/Btu (0.08 K x m²/W).

Thermal Coefficient of Expansion: Unrestrained: 40-100 °F (4-38 °C):  $9.0 \times 10^{-6}$  in./in./°F ( $16.2 \times 10^{-6}$  mm/mm/°C) ( $16.2 \mu$ m/m/°C).

Hygrometric Coefficient of Expansion: Unrestrained: 5-90% r.h.

7.2 x 10<sup>-6</sup> in./in./% r.h. (7.2 x 10<sup>-6</sup> mm/mm/% r.h.) (7.2 µm/m/% r.h.).

Packaging: 2 panels per bundle.

#### Test Data

Surface Burning Characteristics: Flame spread 15, smoke developed 0.

#### Maximum Frame Spacing Drywail Construction

Direct Application	Panel thickness(1)		Location	Application method <sup>(7)</sup>	Max. frame spacing o.c.		
	in.	mm			in,	j mm	
Single-Layer	3/8	9.5	ceilings	perpendicular <sup>44</sup>	16	406	
				paralle#4	16	406	
	1/2	12.7	celings	perpendicular	240.0	610	
				parallek <sup>q</sup>	16	406	
			sidewalls	parallel or perpendicular	24	610	
				paralle <sup>k4</sup>	16	406	
	5/8	15.9	ceilings**	perpendicular	24	610	
			sidewalls	parallel or perpendicular	24	610	
Double-Layer	3/8	9.5	ceilings <sup>(2)</sup>	perpendicular	16	406	
			sidewalls	perpendicular or parallel	240	610	
	1/2 and 5/8 12.7 and 15.9		ceilings	perpendicular or parallel	240	610	
	1.		sidewalls	perpendicular	2419	610	

(1) 5/8" thickness is recommended for the finest single-tayer construction, providing increased resistance to fire and transmission of sound; 1/2" for single-tayer application in new residential construction and remodeling; and 3/8" for repair and remodeling over existing surfaces. (2) Long edge position relative to framing. (3) Not recommended below unheated spaces. (4) Not recommended if water-based texturing material is to be applied. (5) Max. spacing 16" if water-based texturing material is to be applied. (6) If 1/2" Stettrook® interior ceiling board is used in place of gypsum panels, max. spacing is 249 o.c. for perpendicular application with weight of unsupported insulation not exceeding 1.3 psf., 16" o.c. with weight of unsupported insulation not exceeding 2.2 psf. (7) Adhesive must be used to laminate 3/8" board for double-layer ceilings. (8) Max spacing 16" o.c. if fire rating required.

#### Compliance

Meets ASTM C1396.

#### Submittal Approvals:

Job Name

Contractor

Date

#### **Trademarks**

The following trademarks used herein are owned by United Statos Gypsum Company or a related company: Durabono, EASY SAND, FRECODE, STEETROCK, TUFF HOE.

#### Note

Products described here may not be available in all geographic markets. Consult your U.S. Gyssum Company sales office or representative for information.

#### Notice

We shall not be liable for incidental and consequential damages, directly or indirectly sustained, nor for any loss caused by application of these goods not in accordance with current printed instructions or for other than the intended use.

## Our liability is expressly limited to replacement of defective goods. Any claim shall be Safety First!

deemed waived unless made in writing to us within thirty

(30) days from date it was or

reasonably should have been

discovered.

Follow good safety and industrial hygiene practices during handling and installation of all products and systems. Take necessary precautions and wear the appropriate personal protective equipment as needed. Read material safety data sheets and related literature on products before specification and/or installation.

