CITY OF SAINT PAUL **BUILDING PERMIT** Office of Lineage, inspection & Environmental Protection 8 Pourth Street Suite 200 PERMIT #: 20 05 107558 Seint Paul, MN 68101 Issued Date: May 25, 2005 PHONE: (651) 266-9090 FAX: (651) 268-9124 OWNER: **CONTRACTOR:** JAYANT V SARAPH GLADSTONE WINDOW DOOR STORE **58 ORLIN AVE SE** 1870 ENGLISH ST MAPLEWOOD MN 55109-0000 MINNEAPOLIS MN 55414-3562 PERMIT ADDRESS: 601 CLIFFORD ST ST PAUL MN 55104-4907 SUB TYPE: 2-Family/Duplex WORK TYPE: Express Repair

# of Dwelling Units	. 2	State Valuation	8700
Trim	Yes	Windows (Framed Insert or Poc	k Yes
		FEES	
		Permit Fee	167.25
		Surcharge B	4.35
		TOTAL	171.60

**General Comment: Mise. Exterior Work (Soffit/Fasela, Trim, Gutters, Storm Doors and Windows) NO STRUCTURAL CHANGES. Call the designated Building Inspector between 7:30-9:00am (M-F) when work is complete or if problems/questions arise. **Windows-Add Framed-Insert or "Packet" Windows: For bedroom windows-egress must be maintained such that no additional frame or construction will be allowed that reduces the window operable opening more than 1 (one) inch on each side. Any deviation from this standard requires special, prior approval from this Office. Safety Glass is required within a tub or shower enclusion, within 2 feet of doors and adjacent to stairs and stair landings, when the glass is less than 60 inches above a walking or standing surface. See other specifics in Section R308 of the International Residential Code (1- and 2-family dwellings) or Chapter 24 of the International Building Code (multi-family and commercial). NOTE: Though always highly recommended, smoke detector(s) upgrades are not required for this work (considered exterior work) if it is the only work being performed. Call the Area Building Inspector between 7:30-9:00am (M-F) when work is complete or if any problems/questions arise. NOTE: Per Section 33.04 of the Legislative Code all exterior work must be completed within one year of permit issuance.