



The City Clerk needs the following to process your appeal:

# APPLICATION FOR APPEAL

SEP 0 6 2011 CITY CLERK

## Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

\$25 filing fee payable to the City of Sain (if cash: receipt number)  Copy of the City-issued orders or letter ware being appealed  Attachments you may wish to include This appeal form completed  Walk-In OR Mail-In	YOUR HEARING Date and Time:
Address Being Appealed	1:
Number & Street: 995 Cypres	st. St. City: Paul State: MN Zip: 55/06  / Paul Yang Email Chongh Gang Q yahoo.com
Appellant/Applicant: fortous Yang	/ Paul Yang Email Chongho Gang Q yahoo.com
Phone Numbers: Business 65/ 387/98 Signature: August 1	Residence 979 Cook Art Cell 65(-387-1989)  Date: 8/18/11  Paul Chongtu Yang
Phone Numbers: Business	Residence Cell
What Is Being Appealed and Why? Attachments Are Acceptable	
Vacate Order/Condemnation/ Revocation of Fire C of O	
□ Summary/Vehicle Abatement	
☐ Fire C of O Deficiency List	
Fire C of O: Only Egress Windows	
□ Code Enforcement Correction Notice	
□ Vacant Building Registration	
Other	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

August 12, 2011

PAUL YANG 1016 EUCLID ST ST PAUL MN 55106

#### FIRE INSPECTION CORRECTION NOTICE

RE:

995 CYPRESS ST

Ref. #109836

Residential Class: C

Dear Property Representative:

Your building was inspected on August 11, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

### A re-inspection will be made on September 12, 2011 at 2:30 pm.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

#### **DEFICIENCY LIST**

- 1. EXTERIOR SPLC 34.09 (3), 34.32 (3) Repair and maintain the door in good condition.-Repair rear storm door that does not close properly, and replace missing door closer.
- 2. INTERIOR MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.

- 3. INTERIOR UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work may require a permit(s). Call DSI at (651) 266-8989.-This work requires a permit and a final inspection by a DSI trades inspector.
- 4. INTERIOR NEC 440.13 For cord-connected equipment such as room air conditioners, household refrigerators and freezers, drinking water coolers, and beverage dispensers, a separable connector or an attachment plug and receptable shall be permitted to serve as the disconnecting means. The appliance must plug directly into a permanent outlet.-Freezers in basement must be plugged directly into a permanent outlet.
- 5. INTERIOR MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Upon inspection, double hung windows in all three bedrooms measured 19.5 inches openable height x 36 inches openable width.
- 6. INTERIOR MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.-Provide Carbon Monoxide detectors within 24 hours.
- 7. INTERIOR SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner.-Properly remove mold-like substance from bathroom ceiling.
- 8. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 9. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.

For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: kelly.booker@ci.stpaul.mn.us or call me at 651-266-8985 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely, Kelly Booker Fire Inspector