

CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 
 Telephone:
 651-266-8989

 Facsimile:
 651-266-9124

 Web:
 www.stpaul.gov/dsi

# **Code Compliance Report**

January 07, 2011

THE RELOCATION CENTER 700 TWELVE OAKS CENTER DRIVE STE 235 WAYZATA MN 55391

Re: 627 Ohio St File#: 10 922784 VB2

Dear Property Owner:

The following is the Code Compliance report you requested on December 14, 2010.

Please be advised that this report is accurate and correct as of the date January 07, 2011. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from January 07, 2011. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected:

## BUILDING Inspector: Jim Seeger Phone: 651-266-9046

- Dry out basement and eliminate source of moisture.
- Remove mold, mildew and moldy or water damaged materials.
- Install handrails (34 inches 38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment.
- Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary.
- Provide complete storms and screens, in good repair for all door and window openings.
- Provide functional hardware at all doors and windows
- Exit doors shall be capable of being opened from the inside, easily and without the use of a key. Remove all surface bolts.
- Repair or replace damaged doors and frames as necessary, including storm doors.
- Weather seal exterior doors, threshold and weather-stripping.
- Repair walls, ceiling and floors throughout, as necessary.

BUILDING	Inspector: Jim Seeger	Phone: 651-266-9046

- Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present.
- Install Smoke Detectors/Carbon Monoxide Detectors per MN Co Conservation Code and the MN Dept. of Labor and Industry.
- Provide major clean-up of premises.
- Repair siding, soffit, fascia, trim, etc. as necessary.
- Provide proper drainage around house to direct water away from foundation of house.
- Install downspouts and a complete gutter system.
- Provide durable, dustless parking surface as specified in the zoning code.
- Review all applicable codes & policies when replacing windows including egress windows for sleeping rooms.
- Remove trees which are against foundation of home and garage.
- Openings in stair risers must be less than 4 inches.
- Re-level storage shed.
- Second floor ceiling height does not meet code in 2 bedrooms and second floor north bedroom has 28 x 21 clear opening for window for egress.
- First floor bedroom egress window is under sized also 24 x 21 clear opening.
- Front steps at porch top riser not uniform needs correction.
- Roof appears to be leaking at top of second floor stairs.
- 24 inches of snow on site at time of inspection.
- A building permit is required to correct the above deficiencies.

ELECTRICAL	Inspector: Dan Movnihan	Phone: 651-266-9036
LLLCINCIL	mspector. Dun moymmun	

- Bond around water meter with a copper wire sized for the electrical service per Article 250 of the NEC
- Provide a complete circuit directory at service panel indicating location and use of all circuits
- Verify/install a separate 20 ampere laundry circuit and a separate 20 ampere kitchen appliance circuit
- Verify that fuse/circuit breaker amperage matches wire size (10 AWG on 50 amp breaker)
- Install GFCI receptacle in first floor bathroom adjacent to the sink
- Ground bathroom light in first floor bathroom and disconnect receptacle on fixture
- Repair or Replace all broken, missing or loose light fixtures, switches and outlets, covers and plates
- Check all outlets for proper polarity and verify ground on 3-prong outlets
- Install hard-wired, battery backup smoke detector per bulletin 80-1 and other smoke detectors as required by the IRC. Also, Install carbon monoxide detector(s) within 10 feet of all bedrooms

## ELECTRICAL Inspector: Dan Moynihan Phone: 651-266-9036

- Properly wire exterior lights at front door
- Remove or rewire dryer receptacle to 2008 NEC. Separate neutral and ground in panel.
- All added receptacles must be grounded, tamper-resistant and be on an Arc-Fault Circuit Interrupter-protected circuit.
- Any open walls or walls that are opened as part of this project must be wired to the standards of the 2008 NEC.
- All buildings on the property must meet the St. Paul Property Maintenance Code (Bulletin 80-1).
- All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

## PLUMBING Inspector: Denny Watters Phone: 651-266-9051

- Basement Water Heater No gas shut off or gas piping incorrect (IFGC 402.1)
- Basement Water Heater Vent must be in chimney liner (IFGC 501.12)
- Basement Water Heater Water piping incorrect (MPC 1730 Subp. 1)
- Basement Water Heater gas venting incorrect (IFGC 503)
- Basement Water Heater not fired or in service (MPC 2180)
- Basement Water Meter meter is removed or not in service (MPC 4715.1700)
- Basement Water Meter service valves not functional or correct (MPC 1800 Subp 3,4)
- Basement Water Piping repair or replace all corroded, broken or leaking piping (MPC 4715.1720)
- Basement Water Piping run 1 inch water line from meter to first major take off (SPRWS Water Code)
- Basement Gas Piping dryer gas shutoff; connector or piping incorrect (IFGC 402.1)
- Basement Gas Piping run dryer vent to code (IFGC 613.1 IMC 604.1)
- Basement Soil and Waste Piping improper connections, transitions, fittings or pipe usage (MPC 2420)
- Basement Soil and Waste Piping no front sewer clean out (MPC 1000)
- Basement Laundry tub stand pipe is unvented.
- Basement Laundry Tub provide a vacuum breaker for the spout (MPC 2000 B)
- Basement Laundry Tub unvented (MPC 0200 E)
- Basement Toilet Facilities unvented (MPC 0200. E)
- Basement Tub and Shower provide anti-scald valve (MPC 1380. Subp. 5)
- Basement Tub and Shower unvented (MPC 0200. E)
- First Floor Gas Piping range gas shut off; connector or piping incorrect (IFGC 411 1.3.3)
- First Floor Lavatory incorrectly vented (MPC 2500)
- First Floor Lavatory waste incorrect (MPC 2300)
- First Floor Sink unvented (MPC 0200. E)
- First Floor Sink waste incorrect (MPC 2300)

PLUMBING	<b>Inspector: Denny Watters</b>	Phone: 651-266-9051
	mspector: Denny Watters	

- First Floor Toilet Facilities waste incorrect (MPC 2300)
- First Floor Tub and Shower incorrectly vented (MPC 2500)
- First Floor Tub and Shower provide anti-scald valve (MPC 1380. Subp. 5)
- First Floor Tub and Shower replace waste and overflow (MPC 1240)
- First Floor Tub and Shower waste incorrect (MPC 2300)
- Exterior Lawn Hydrants Requires backflow assembly or device (MPC 2000) could not verify.
- Obtain plumbing permits prior to commencement of work.

#### HEATING Inspect

#### **Inspector:** Gary Stevens

Phone: 651-266-9045

- Install approved lever handle manual gas shutoff valve on all gas appliances and remove unapproved valve.
- Clean and Orsat test furnace burner. Check all controls for proper operation. Check furnace heat exchanger for leaks; provide documentation from a licensed contractor that the heating unit is safe.
- Install approved metal chimney liner.
- Connect furnace and water heater venting into chimney liner.
- Vent clothes dryer to code.
- Provide adequate combustion air and support duct to code.
- Provide support for gas lines to code.
- Plug, cap and/or remove all disconnected gas lines.
- Provide appropriate size operable window in bathrooms or provide bathroom exhaust system vented to outside with approved material according to code. A mechanical ventilation permit is required if an exhaust system is installed.
- All supply and return ducts for warm air heating system must be clean before final approval for occupancy. Provide access for inspection of inside of ducts or provide documentation from a licensed duct-cleaning contractor that the duct system has been cleaned.
- Provide return air from second floor for warm air heating system according to code.
- All supply/return ducts to be supported and repair damaged return air panning in basement according to code.
- Install kitchen exhaust fan duct according to code.
- Repair and/or replace heating registers as necessary.
- Provide heat in every habitable room and bathrooms.
- Mechanical gas and ventilation permits are required for the above work.

## **ZONING**

- 1. This property is in a (n) RT1 zoning district.
- 2. This property was inspected as a Single Family Dwelling.

#### Notes:

- See attachment for permit requirements and appeals procedure.
- Roof, sidewalks, etc. snow covered and could not be inspected. All must meet appropriate codes when completed.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Jim Seeger between 7:30 - 9:00 AM at 651-266-9046 or leave a voice mail message.

Sincerely,

James L. Seeger Code Compliance Officer Department of Safety and Inspections City of Saint Paul 375 Jackson Street, Suite 220 Saint Paul MN 55101 Phone: 651-266-9046 Email: james.seeger@ci.stpaul.mn.us

JLS:ml Attachments