

# **APPLICATION FOR APPEAL**

RECEIVED

SEP 23 7011

CITY CLERK

## Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

The City Clerk needs the following to prod	cess your appeal:
\$25 filing fee payable to the City of Sa (if cash: receipt number) Copy of the City-issued orders or letter are being appealed Attachments you may wish to include This appeal form completed  Walk-In OR  Mail-In	YOUR HEARING Date and Time: Tuesday 10-4-1
Address Being Appeale	d:
Number & Street: 5/1 5/191	WINE City: ST PAGE State: MN Zip:
Appellant/Applicant:	/ /
Phone Numbers: Business	Residence Cell <u>65/-263-317</u> 0
Signature:	Date: 9/83///
Address (if not Appellant's):	
	Residence Cell
What Is Being Appealed	and Why? Attachments Are Acceptable
Vacate Order/Condemnation/ Revocation of Fire C of O  Summary/Vehicle Abatement  Fire C of O Deficiency List  Fire C of O: Only Egress Windows  Code Enforcement Correction Notice	LIST AHACKES
Vacant Building Registration  Other	
· · · · · · · · · · · · · · · · · · ·	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

September 19, 2011

BRUCE FORD 1414 Larkspur Dr Woodbury MN 55129-4810

### FIRE INSPECTION CORRECTION NOTICE

RE:

811 SHERBURNE AVE

Ref. #109531

Residential Class: C

### Dear Property Representative:

Your building was inspected on September 16, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A reinspection will be made on October 18, 2011 at 11:00 am.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

#### DEFICIENCY LIST

- 1. 1st Floor Kitchen Under Sink MSFC 605.1 Remove unapproved exposed wiring and install in accordance with the electrical code. This work may require a permit(s). Call DSI at (651) 266-9090.-Exposed unapproved Romex run under sink.
- 2. 1st Floor Kitchen Under Sink MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.
- 3. 1st Floor Kitchen Under Sink SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 415.0220 Repair or replace and maintain the plumbing fixture to an operational condition.- Multiple flex connectors are chained together on water supply lines to sink.

- 4. 2nd Floor Bathroom SPLC 34.10 (7), 34.33 (6) Repair and maintain the cabinets in an approved manner.-Scrape and paint as necessary.
- 5. 2nd Floor Bathroom SPLC 34.09 (3), 34.32 (3) Repair and maintain the window frame.-Scrape and paint window frame as necessary, repair and seal in an approved manner
- 6. 2nd Floor Bathroom SPLC 34.12 (2), 34.35 (1) Repair and maintain all required and supplied equipment in an operative and safe condition.-Clean accumulation of dust/ lint from vent fan.
- 7. 2nd Floor Hallway MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.-Repair and maintain hard-wired smoke detector with battery backup. Hard-wired detector was present at time of inspection and power light was on but would not test when test button was pressed.
- 8. 2nd Floor Rear Bedroom MSFC 1011.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.-Relocate furniture to provide clear access to at least one bedroom egress window.
- 9. 2nd Floor MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- 10. Basement Dryer UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work may require a permit(s). Call DSI at (651) 266-8989.
- 11. Basement Electrical Panel NEC 408.4 Circuit Directory Every electrical circuit shall be legibly identified as to its clear, evident, and specific purpose or use.
- 12. Basement Incinerator MN Rules 1300.0180 Immediately discontinue use of unapproved appliance. This must be removed in an approved manner by a licensed contractor. This work may require a permit(s). Call DSI at (651) 266-9090.-Remove trash incinerator and cap chimney vent opening and gas line in an approved manner.
- 13. Basement Stairway SPLC 34.10 (3) 34.33(2) Provide an approved guardrail. Intermediate balustrade must not be more than 4 inches apart. Intermediate rails must be provided if the height of the platform is more than 30 inches.
- 14. Basement Stairway SPLC 34.10 (3), 34.33(2) Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.
- 15. Basement Water Meter MSFC 605.1 -Provide a grounding jumper around the water meter.
- 16. Exterior Front SPLC 71.01 The address posted is not visible from street. (HN-1)-Provide reflective numbers or background or illuminate at night.

- 17. Exterior Garage SPLC 34.08 (5), 34.31 (3) Repair, replace and maintain all exterior surfaces on fences, sheds, garages and other accessory structures free from holes and deterioration. Provide and maintain exterior unprotected surfaces painted or protected from the elements.
- 18. Exterior House SPLC 34.09 (1) b,c, 34.32 (1) b,c Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.
- 19. Exterior Rear SPLC 34.08 (7) All parking spaces shall be paved with asphalt, concrete, or durable dustless surfacing. Before any existing spaces may be paved, site plan approval must be obtained as specified in the St. Paul Zoning Code. Contact DSI Zoning at 651-266-9090.
- 20. Exterior Rear SPLC 71.01 Provide address numbers on building per attached HN-1 handout.-Provide access numbers visible from alley, must be reflective or lit at night.
- 21. Exterior Rear MSFC 605.5.3 Immediately, discontinue use of frayed, deteriorated, damaged or spliced electrical cords.-Deterioration noted to cable jacket on overhead wiring running to garage, repair or replace in an approved manner. This work may require a permit(s). Contact DSI at (651) 266-8989.
- 22. Throughout MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-9090.-Repair outlets throughout the building where wired incorrectly. Multiple 3-prong receptacles have open ground connection. Multiple receptacles have reversed polarity.
- 23. Throughout MSFC 605.4 Discontinue use of all multi-plug adapters.
- 24. Throughout MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.
- 25. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 26. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.
- 27. SPLC 40.04 (5) On or after April 30, 2009, The owner of a building used for residential occupancy who is applying for their FIRST Fire Certificate of Occupancy, must complete the Minnesota Crime Free Multi Housing training program or other landlord training program approved by the Fire Marshal.

The training must have occurred within the last two years and the owner must submit a certificate of attendance or provide verification of enrollment in the next scheduled class to the Fire Inspection Division-DSI.

This requirement shall not apply to an owner who has held a Fire Certificate of Occupancy on another residential property in Saint Paul prior to April 30, 2009.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: mitchell.imbertson@ci.stpaul.mn.us or call me at 651-266-8986 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Mitchell Imbertson Fire Inspection

Reference Number 109531

of sid 310

Styps MS gorm