

APPLICATION FOR APPEAL

Saint Paul City Clerk

RECEIVED

DEC 0 8 2011

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

The City Clerk needs the following to process your appeal:	
\$25 filing fee payable to the City of Saint Paul (if cash: receipt number Cost) Copy of the City-issued orders or letter which are being appealed Attachments you may wish to include This appeal form completed Walk-In OR Mail-In	YOUR HEARING Date and Time: Tuesday, Dec 20, 2011 Time 130 p.m. Location of Hearing: Room 330 City Hall/Courthouse
Address Being Appealed: Govern Carty House.	
Number & Street: 1733 York Dee E City: St. Paul State: Mn Zip: 55106	
Appellant/Applicant: Business 763-370 8346 Residence	cell_
Name of Owner (if other than Appellant): Bibly fong lang Address (if not Appellant's): 11044 Yang CF NE Blain, Mn 55449	
Phone Numbers: Business 651. 489-3063 Residence	
What Is Being Appealed and Why? Attachments Are Acceptable	
Vacate Order/Condemnation/ Revocation of Fire C of O □ Summary/Vehicle Abatement □ Fire C of O Deficient Table	
Fire C of O: Only Egress Windows BR Windows	side.
□ Code Enforcement Correction Notice	
□ Vacant Building Registration	
□ Other	

DEPARTMENT OF SAFETY AND INSPECTIONS Fire Inspection Division Ricardo X. Cervantes, Director

CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: Facsimile:

651-266-8989 651-266-8951

Web:

www.stpaul.gov/dsi

November 7, 2011

BILLY FONG VANG ABCS HOME CARE 2353 RICE ST STE 103 ROSEVILLE MN 55113

FIRE INSPECTION CORRECTION NOTICE

RE:

1733 YORK AVE

Ref. #113199

Residential Class: C

Dear Property Representative:

Your building was inspected on November 7, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A reinspection will be made on December 8, 2011 at 12NOON.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. Bedroom N.E.Side - MSFC1026.1 - Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work will require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.-Openable height 23 inches. Openable width 38 inches. Glazed 46inches in height by 35inches in width.
- 2. Kitchen - SPLC 34.10 (7), 34.33 (6) - Repair and maintain the floor in an approved manner.-Repair or replace the torn or missing floor tile.

An Equal Opportunity Employer

- Leading to garage SPLC 34.09 (2), 34.32(2) Repair or replace the damaged handrail in an approved manner. This work may require a permit(s). Call DSI at (651) 266-9090.
- 4. Rear deck SPLC 34.09 (2), 34.32(2) Repair or replace the unsafe stairways, porch, decks or railings in an approved manner. This work may require a permit(s). Call DSI at (651) 266-9090.
- SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a <u>carbon monoxide test</u>. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
 - 6. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.
 - 7. NEC 110-26 Provide and maintain a minimum of 36 inches clearance in front of all electrical panels.
 - 8. SPLC 34.09 (3), 34.32 (3) Provide or repair and maintain the window screens.
 - 9. SPLC 34.10 (4), 34.33 (3) Provide a bathroom floor impervious to water: after securing toilet to floor caulk the base.
 - 10. MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.
 - 11. SPLC 34.10 (7), 34.33 (6) Repair and maintain the floor in an approved manner.-Repair or replace the torn and worn carpeting.
- UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work will require a permit(s). Call DSI at (651) 266-8989.-dryer vent has plastic inserted in the middle of the duct.
 - 13. SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 415.0220 Repair or replace and maintain the plumbing fixture to an operational condition.-Repair or replace and maintain an approved private toilet. Secure toilet to floor

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: james.thomas@ci.stpaul.mn.us or call me at

Appeal Belfroom Window N.E. Side